400 Seventh Street, S.W.
Washington, D.C. 20590

U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***

Get it together!
SAFETY BELTS SAVE LIVES

AUTO SAFETY HOTLINE
(800) 424-9393
Wash. D.C. Area 366-0123

U.S. Department of Transportation
National Highway Traffic Safety Administration

CASE SUMMARY

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU 03 CASE NO. 42A TYPE OF ACCIDENT Angle impact

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

(Provide a summary of the accident sequence as well as any particular event of the accident that is noteworthy. Injury mechanism and vehicle crashworthiness is the focus, not driver culpability. Do not include any personal identifiers.)

National Accident Sampling System
1995 Case Summary Form

PSU03
CASE 042A
TYPE OF ACCIDENT: ANGLE IMPACT

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

VEHICLE #1 HEADING NORTH BOUND WAS STRUCK BY VEHICLE #2 HEADING WEST BOUND. DRIVER #1 WAS KILLED AS A RESULT. VEHICLE #2 OUERTURNED AFTER THIS IMPACT. AFTER THE SECOND AND THIRD HARMFUL EVENT VEHICLE #1 (THE LEFT FRONT WHEEL) HIT THE R/L. VEHICLE #1 CAME TO FINAL REST BY STRIKING THE RP.

B. VEHICLE PROFILE(S)

Vehicle No.	Class of Vehicle	Year/Make/Model	Most Severe Damage Based on Vehicle Inspection		Component Failure
			Damage Plane	Severity Description	
1	Compact	1989 Mitsubishi / Mirage	Right Plane	moderate	none
2	Largest	1986 Chevrolet / caprice	Frontal	major	none

DO NOT SANITIZE THIS FORM

HS Form 434A (1/95)

C. PERSON PROFILE(S)

Vehicle No.	Person Role	Seat Position	Restraint Use	Most Severe Injury (TO BE COMPLETED BY ZONE CENTER)			
				Body Region	Injury Type	AIS	Injury Source

C. PERSON PROFILE(S)

Veh. No	Person Role	Seat Positon	Restraint Use	Body Region	Injury Type	AIS	Injury Source
1	DRIVER	LF	LAP BELT	FATAL	DETAILS UNKNOWN		
2	DRIVER	LF	LAP BELT	HEAD	UNKNOWN	7	
2	PASSENGER	RR	NONE	HEAD	UNKNOWN	7	

Body Region

Abdomen
Ankle—foot
Arm (upper)
Back-thoracolumbar spine
Brain
Chest
Ears
Eye
Elbow
Face
Forearm
Head—skull
Heart
Kidneys
Knee
Leg (lower)
Liver
Lower limbs(s) (whole or unknown part)
Mouth
Neck—cervical spine
Nose
Pelvic—hip
Pulmonary—lungs
Shoulder
Spleen
Thigh
Thyroid, other endocrine gland
Upper limb(s) (whole or unknown part)
Vertebrae
Whole body
Wrist—hand

Injury Type

Abrasion
Amputation
Avulsion
Burn
Concussion
Contusion
Crush
Detachment, separation
Dislocation
Fracture
Fracture and dislocation
Laceration
Other
Perforation, puncture
Rupture
Sprain
Strain
Total severance, transection
Unknown

Abbreviated Injury Scale

(1) Minor injury
(2) Moderate injury
(3) Serious injury
(4) Severe injury
(5) Critical injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

DO NOT SANITIZE THIS FORM

PSU03 1995 Case Summary Form
CASE 042A
TYPE OF ACCIDENT: ANGLE IMPACT

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

VEHICLE #1 HEADING NORTH BOUND WAS STRUCK BY VEHICLE #2 HEADING WEST BOUND. DRIVER #1 WAS KILLED AS A RESULT. VEHICLE #2 OUERTURNED AFTER THIS IMPACT. AFTER THE SECOND AND THIRD HARMFUL EVENT VEHICLE #1 (THE LEFT FRONT WHEEL) HIT THE R/L. VEHICLE #1 CAME TO FINAL REST BY STRIKING THE RP.

01

PSU03 1995 Case Summary Form
CASE 042A
TYPE OF ACCIDENT: ANGLE IMPACT

B. VEHICLE PROFILE(S)

Veh. No	Class of Vehicle	Year/Make/ Model	Damage Plane	Severity Descr.	Component Failure
1	COMPACT	1989 MITSUBISHI/ MIRAGE	RIGHT PLANE	MODERATE	NONE
2	LARGEST	1986 CHEVORLET/ CAPRICE	FRONTAL	MAJOR	NONE

01

PSU03 1995 Case Summary Form
CASE 042A
TYPE OF ACCIDENT: ANGLE IMPACT

C. PERSON PROFILE(S)

Veh. No	Person Role	Seat Positon	Restraint Use	Body Region	Injury Type	AIS	Injury Source
1	DRIVER	LF	LAP BELT	FATAL injured→	DETAILS UNKNOWN		
2	DRIVER	LF	LAP BELT	HEAD	UNKNOWN	7	sunvisor
2	PASSENGER	RR	NONE	HEAD	UNKNOWN	7	roof

O

RL

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION DIAGRAM

NT COLLISION

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 13 Case Number — Stratum 04 2A

Indicate North

tratum ____



HS Form 431B (1/95)

Scale: 1 centimeter = _____ meters

RL

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 03 Case Number 193 Stratum 042A

Indicate North

NT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

tratum

Indicate North



HS Form 4318 (1/95)

Scale: 1 centimeter = _____ meters

Scale: 1 centimeter = _____ meters

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION MEASUREMENT TABLE

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 0 3 | Case Number—Stratum 0 4 2 A

ACCIDENT COLLISION DIAGRAM

Document the physical plant:

* all road/roadway delineation (e.g., curbs/edge lines, lane markings, median markings, pavement markings, parked vehicles, poles, signs, etc.)
* all traffic controls (e.g., speed limit)
* north arrow placed on diagram
* roadway surface type and condition of applicable roadways
* grade measurements for all applicable roadways and at location of rollover initiation
* roadway curvature

Document vehicle dynamics including:

* reference point and reference line relative to physical features present at the scene
* scaled documentation of all accident induced physical evidence
* scaled documentation of all roadside objects contacted
* scaled representations of the vehicle(s) at pre-impact, impact, and final rest based upon either:
  a) physical evidence, or
  b) reconstructed accident dynamics

CRASH DATA

	VEH. #1	VEH. #2	VEH. #3
Heading Angle	359°	290°	
Surface Type	Bituminous		
Surface Condition	DRY	DRY	
Coefficient of Friction	normal		
Grade (v/h) Measurement (between impact and final rest)	0/0 cm	0/0 cm	
Grade (v/h) Measurement (at location of rollover initiation)	N/A	N/A	

Reference Point: Traffic Signal on North West median 0.8 N × 1.0 W

Reference line: Western curb line

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line
Pole base	0°	1.0 W

HS Form 431A (1/95)

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line

U.S. Department of Transportation

National Highway Traffic Safety Administration

BEST AVAILABLE

ACCIDENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 042A

IDENTIFICATION

3. Number of General Vehicle Forms Submitted: 02
4. Date of Accident (Month,Day,Year): [redacted] / 95
5. Time of Accident: 0545

Code reported military time of accident.

NOTE: Midnight = 2400
Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. ___ SS15 Administrative Use: 0
7. ___ SS16 Pedestrian Crash Data Study: 0
   (Data for this special study available in a separate file.)
8. ___ SS17 Impact Fires: 0
9. ___ SS18 Unsafe Driver Actions: 0
10. ___ SS19 _____: 0

NUMBER OF EVENTS

11. Number of Recorded Events in This Accident: 04

Code the number of events which occurred in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columnns.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. 01	13. 01	14. 01	15. R	16. 02	17. 05	18. F
19. 02	20. 02	21. 05	22. LT	23. 31	24. 00	25. N
26. ~~03~~	27. ~~02~~	28. ~~05~~	29. X LF Wheel	30. ~~01~~	31. ~~00~~	32. ~~X~~
33. 03 ~~04~~	34. 01	35. 01	36. 4	37. 63	38. 00	39. 0
40. 04 ~~05~~	41. 01	42. 01	43. L	44. 52	45. 00	46. 0

1st Review: JG
2nd Review:

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

CODES FOR CLASS OF VEHICLE

(00) Not a motor vehicle
(01) Subcompact/mini (wheelbase < 254 cm)
(02) Compact (wheelbase ≥ 254 but < 265 cm)
(03) Intermediate (wheelbase ≥ 265 but < 278 cm)
(04) Full size (wheelbase ≥ 278 but < 291 cm)
(05) Largest (wheelbase ≥ 291 cm)
(09) Unknown passenger car size
(14) Compact utility vehicle
(15) Large utility vehicle (≤ 4,500 kgs GVWR)
(16) Utility station wagon (≤ 4,500 kgs GVWR)
(19) Unknown utility type
(20) Minivan (≤ 4,500 kgs GVWR)
(21) Large van (≤ 4,500 kgs GVWR)
(24) Van Based school bus (≤ 4,500 kgs GVWR)
(28) Other van type (≤ 4,500 kgs GVWR)
(29) Unknown van type (≤ 4,500 kgs GVWR)
(30) Compact pickup truck (≤ 4,500 kgs GVWR)
(31) Large pickup truck (≤ 4,500 kgs GVWR)
(38) Other pickup truck (≤ 4,500 kgs GVWR)
(39) Unknown pickup truck type (≤ 4,500 kgs GVWR
(45) Other light truck (≤ 4,500 kgs GVWR)
(48) Unknown light truck type (≤ 4,500 kgs GVWR)
(49) Unknown light vehicle type
(50) School bus (excludes van based)(> 4,500 kgs GVWR)
(58) Other bus (> 4,500 kgs GVWR)
(59) Unknown bus type
(60) Truck (> 4,500 kgs GVWR)
(67) Tractor without trailer
(68) Tractor-trailer(s)
(78) Unknown medium/heavy truck type
(79) Unknown light/medium/heavy truck type
(80) Motored cycle
(90) Other vehicle
(99) Unknown

CODES FOR GENERAL AREA OF DAMAGE (GAD)

CDS APPLICABLE AND OTHER VEHICLES	(0) Not a motor vehicle	(R) Right side	(T) Top
	(N) Noncollision	(L) Left side	(U) Undercarriage
	(F) Front	(B) Back	(9) Unknown

TDC APPLICABLE VEHICLES	(0) Not a motor vehicle	(L) Left side	(C) Rear of cab
	(N) Noncollision	(B) Back of unit with cargo area (rear of trailer or straight truck)	(V) Front of cargo area
	(F) Front		(T) Top
	(R) Right side	(D) Back (rear of tractor)	(U) Undercarriage
			(9) Unknown

CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
(31) Overturn — rollover (excludes end-over-end)
(32) Rollover — end-over-end
(33) Fire or explosion
(34) Jackknife
(35) Other intraunit damage (specify):
_____
(36) Noncollision injury
(38) Other noncollision (specify):
_____
(39) Noncollision — details unknown

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment
(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____
(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):
_____
(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(72) Pedestrian
(73) Cyclist or cycle
(74) Other nonmotorist or conveyance
_____
(75) Vehicle occupant
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):
_____
(89) Unknown nonfixed object

(98) Other event (specify):
_____
(99) Unknown event or object

psu 03-042A V-01

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction — 2
    (0) Non-interchange area and non-junction
    (1) Interchange area related

    Non-Interchange junctions
    (2) Intersection related
    (3) Driveway, alley access related
    (4) Other junction (specify) _____
    (5) Unknown type of junction

    (9) Unknown

20. Trafficway Flow — 0
    (0) Not physically divided (two way traffic)
    (1) Divided trafficway-median strip without positive barrier
    (2) Divided trafficway-median strip with positive barrier
    (3) One way traffic
    (9) Unknown

21. Number Of Travel Lanes — 1
    (1) One
    (2) Two
    (3) Three
    (4) Four
    (5) Five
    (6) Six
    (7) Seven or more
    (9) Unknown

22. Roadway Alignment — 1
    (1) Straight
    (2) Curve right
    (3) Curve left
    (9) Unknown

23. Roadway Profile — 1
    (1) Level
    (2) Uphill grade (>2%)
    (3) Hill crest
    (4) Downhill grade (>2%)
    (5) Sag
    (9) Unknown

24. Roadway Surface Type — 2
    (1) Concrete
    (2) Bituminous (asphalt)
    (3) Brick or block
    (4) Slag, gravel, or stone
    (5) Dirt
    (8) Other (specify): _____
    (9) Unknown

25. Roadway Surface Condition — 1
    (1) Dry
    (2) Wet
    (3) Snow or slush
    (4) Ice
    (5) Sand, dirt, or oil
    (8) Other (specify): _____
    (9) Unknown

26. Light Conditions — 4
    (1) Daylight
    (2) Dark
    (3) Dark, but lighted
    (4) Dawn
    (5) Dusk
    (9) Unknown

27. Atmospheric Conditions — 0
    (0) No adverse atmospheric-related driving conditions
    (1) Rain
    (2) Sleet/hail
    (3) Snow
    (4) Fog
    (5) Rain and fog
    (6) Sleet and fog
    (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
    (9) Unknown

28. Traffic Control Device — 1
    (0) No traffic control(s)
    (1) Traffic control signal (not RR crossing)

    Regulatory
    (2) Stop sign
    (3) Yield sign
    (4) School zone sign
    (5) Other regulatory sign (specify): _____
    (6) Warning sign (not RR crossing)
    (7) Unknown sign
    (8) Miscellaneous/other controls including RR controls (specify): _____
    (9) Unknown

29. Traffic Control Device Functioning — 2
    (0) No traffic control device
    (1) Traffic control device not functioning (specify): _____
    (2) Traffic control device functioning properly
    (9) Unknown

psu 03-042A V-01

OCCUPANT RELATED

37. Driver Presence in Vehicle: 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle: 01
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted: 01

AIR BAG RELATED

40. Is this an AOPS Vehicle?: 1
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal: 0
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal: 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight: 1,030 0
____ Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
2,271 lbs X .4536 = 1,030 kgs

Source: _____

44. Vehicle Cargo Weight: 0,000 0
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown
___,___ lbs X .4536 = ___,___ kgs

Source: _____

ROLLOVER DATA

45. Rollover: 00
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type: 08
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify):
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation: 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted: 00
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied: 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify):
(6) Non-contact rollover forces (specify):
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll: 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

psu 03-042A V-01

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

_____

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

_____

(89) Unknown nonfixed object

(98) Other event (specify):

_____

(99) Unknown event or object

U.S. Department of Transportation
National Highway Traffic Safety Administration

BEST AVAILABLE

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 042A
3. Vehicle Number: 01

VEHICLE IDENTIFICATION

VIN JA3CU54Z7KU[redacted] Model Year 89

Vehicle Make (specify): mitsubishi Vehicle Model (specify): mirage

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	(R) Front Fender & R Door	(R) Plane	19cm (R) of C5
2	(L) Fender	(L) Fender + door	15cm between C4 and C5

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
1	R Plane	222.0	47	342	23.5	30.0	25.0	0.0	0.5	8.5	
	FS		0.0		10.5	0.0	0.5	0.5	0.5	8.5	
1	adj		47		13.0	30.	24.5	0.0	0.0	0.0	+T36
84	L Plane	158.	16.0	232	0.0	13.0	14.5	2.0	1.0	0.0	
	FS		1.0		0.0	1.0	1.0	1.0	1.0	0.0	
84	adj "C"		15.0		0.0	12.0	3.5	1.0	0.0	0.0	-490

HS Form 435A (Rev. 1/95)

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	96.7	inches	x	2.54	=	245.6 cm
Overall Length	170.1	inches	x	2.54	=	432 cm
Maximum Width	65.7	inches	x	2.54	=	166.8 cm
Curb Weight	2,271	pounds	x	.4536	=	1,030 kg
Average Track 56.3	56.3	inches	x	2.54	=	143 cm
Front Overhang	___.___	inches	x	2.54	=	___ cm
Rear Overhang	___.___	inches	x	2.54	=	___ cm
Undeformed End Width	___.___	inches	x	2.54	=	152 cm
Engine Size: cyl./displ. 5 speed manual transmission	1.6	cc	x	.001	=	1.6 L
	___	CID	x	.0164	=	___.___ L

VEHICLE DAMAGE SKETCH

TIRE–WHEEL DAMAGE

	a. Rotation physically restricted	b. Tire deflated
RF	2	2
LF	1	1
RR	2	2
LR	2	2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☒ Manual ☐ Automatic

END SHIFT ≥ 10 CM
☐ Yes ☐ No

ORIGINAL SPECIFICATIONS

Wheelbase	246	cm
Overall Length	432	cm
Maximum Width	167.	cm
Curb Weight	1030	kg
Average Track	143.	cm
Front Overhang	–	cm
Rear Overhang	–	cm
Undeformed End Width	152.	cm
Engine Size: cyl./displ.	5SP 1.6	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF	±	o
LF	±	o
RR	±	o
LR	±	o

Within ± 5 degrees

DRIVE WHEELS

☒ FWD ☐ RWD ☐ 4WD

Approximate Cargo Weight 000 kg

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

IT is believed the (LF) tire Blow out on impact #1 = IHE
deflated

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object

- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	02	045°	99	R	Y	E	W	03
01 403	63	310°	99	L	F	xlv	N	01
01 504	52	310°	99	L	Y	E	W	02

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 02	6. 02	7. R	8. Y	9. E	10. W	11. 03

MASS CODING CHANGE
1st Review: 1G
2nd Review: _____

Second Highest Delta "V"

12. ~~00~~ 04	13. 52	14. 10	15. L	16. Y	17. E	18. W	19. 02

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
342	013	030	025	000	000	000	⊖138

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
232	000	012	004	001	000	000	⊖049

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 998
____ Code to the nearest centimeter
(250) 250 centimeters or more
(998) No highest severity end plane impact
(999) Unknown

27. Direct Damage Width (For highest severity impact) 222
____ Code to the nearest centimeter
(250) 250 centimeters or more
(999) Unknown

28. Original Wheelbase 246
____ Code to the nearest centimeter
(650) 650 centimeters or more
(999) Unknown
96.7 inches X 2.54 = 245.6 centimeters

29. Original Average Track Width 143
____ Code to the nearest centimter
(185) 185 centimeters or more
(999) Unknown
56.3 inches X 2.54 = 143 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 1
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): _____
_____
_____
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify):
_____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 3

36. Location of Fuel Tank-2 Filler Cap 0
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify):_____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 1

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify):_____
(9) Unknown

41. Damage to Fuel Tank-1 1

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify):_____
(9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 0 1

46. Fuel Type-2 0 0

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 042 A
3. Vehicle Number: 01

INTEGRITY

4. Passenger Compartment Integrity: 98

(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify): 01, 06
(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 3 7. LR 0 8. RR 0 9. TG/H +

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 2
20. BL 2 21. Roof 0 22. Other 0

(0) No glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted (original)
(4) AS-2 — Tempered-with after market tint
(5) AS-3 — Tempered-tinted (with additional after market tint)
(6) AS-14 — Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify):
(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR 2 27. RR 2
28. BL 1 29. Roof 0 30. Other 0

(0) No glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown due to rescue team

Glazing Damage from Impact Forces

31. WS 9 32. LF 9 33. RF 6 34. LR 6 35. RR 6
36. BL 1 37. Roof 0 38. Other 0

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 9 40. LF 9 41. RF 1 42. LR 1 43. RR 1
44. BL 1 45. Roof 0 46. Other 0

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters) COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION
13	Roof Rail	0	–	20	=	20	Lon
3 13	(R) dash	0	–	26	=	26	Lon
2 13	A Pillar	0	–	32	=	32	Lon
4 13	(R) door panel	0	–	21 cm	=	21	La
1 13	B Pillar	0	–	40	=	40cm	La
23	(R) occupant Fwr	0	–	10	=	10	La
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 13	48. 07	49. 4	50. 2
2nd	51. 13	52. 06	53. 4	54. 2
3rd	55. 13	56. 04	57. 3	58. 2
4th	59. 13	60. 11	61. 3	62. 3
5th	63. 13	64. 27	65. 3	66. 3
6th	67. 13	68. 10	69. 2	70. 3
7th	71.	72.	73.	74.
8th	75.	76.	77.	78.
9th	79.	80.	81.	82.
10th	83.	84.	85.	86.

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center ✓
- (04) Instrument panel right ✓
- (05) Toe pan ✓
- (06) A (A1/A2)-pillar ✓
- (07) B-pillar ✓
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side) ✓
- (12) Side panel - rear of the B-pillar ✓
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): Front Roof Rail (R) side

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	–	DAMAGE VALUE	=	DEFORMATION
unk	–	999	=	999
	–		=	
	–		=	
	–		=	

Steering was cut during rescue

STEERING COLUMN

87. Steering Column Type — 1
(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify): _____
(9) Unknown

88. Tilt Steering Column Adjustment — 0
(0) No tilt steering column
(1) Full up
(2) Between full up and center
(3) Center
(4) Between center and full down
(5) Full down
(9) Unknown

89. Telescoping Steering Column Adjustment — 0
(0) No telescoping steering column
(1) Full back
(2) Between full back and midpoint
(3) Midpoint
(4) Between midpoint and full forward
(5) Full forward
(9) Unknown

90. Steering Rim/Spoke Deformation — 99
_____ Code actual measured deformation to the nearest centimeter
(00) No steering rim deformation
(01-14) Actual measured value in centimeters
(15) 15 centimeters or more
(98) Observed deformation cannot be measured
(99) Unknown

91. Location of Steering Rim/Spoke Deformation — 99
(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D



Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke



(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

Steering wheel half was cut for unk reason

INSTRUMENT PANEL

92. Odometer Reading — 055,000
_____ kilometers
Code to the nearest 1,000 kilometers
(000) No odometer
(001) Less than 1,500 kilometers
(500) 499,500 kilometers or more
(999) Unknown
33878 miles X 1.6093 = 54519 kilometers

Source: _____

93. Instrument Panel Damage from Occupant Contact? — 9
(0) No
(1) Yes
(9) Unknown

deformed by impact forces

94. Type of Knee Bolster Covering — 1
(0) No knee bolster
(1) Padded
(2) Rigid plastic
(8) Other (specify): _____
(9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? — 9
(0) No knee bolster
(1) No deformation
(2) Yes - deformation
(9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? — 2
(0) No glove compartment door
(1) No - door did not open
(2) Yes - door opened
(9) Unknown

97. Adaptive (Assistive) Driving Equipment — 0
(0) No adaptive driving equipment
(1) Adaptive driving equipment installed (Check all that apply.)
[ ] Hand controls for braking/acceleration
[ ] Steering control devices (attached to OEM steering wheel
[ ] Steering knob attached to steering wheel
[ ] Low effort power steering (unit or device)
[ ] Replacement steering wheel (i.e., reduced diameter)
[ ] Joy-stick steering controls
[ ] Wheelchair tie-downs
[ ] Modification to seat belts (specify): _____
[ ] Additional or relocated switches (specify): _____
[ ] Raised roof
[ ] Wall-mounted head rest (used behind wheelchair)
[ ] Other adaptive device (specify): _____
(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	01	01	unk	unk if contacted by Driver	
B				The steering wheel was	
C				By rescue team	unk
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column,transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment(e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object, (specify): _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(175) Air bag compartment cover-driver side
(180) Air bag-passenger side
(185) Air bag compartment cover-passenger side
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
(1) Certain
(2) Probable
(3) Possible
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data **for each seat position** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	3	0	3
	Evidence of usage	03	0	03
	Used in this crash?	00	0	00
	Proper Use	9	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment		0	
SECOND	Availability	4	3	4
	Evidence of usage	04	03	04
	Used in this crash?	0	0	0
	Proper Use	0	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment	1	8	1
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability

(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available - type unknown

Integral Belt Partially Destroyed

(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperable (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used - type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat - type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

Proper Use of Manual (Active) Belts

(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly

(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

Shoulder Belt Upper Anchorage Adjustment

(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
FIRST	Availability/Function	0	0	0
	Deployment	7	0	0
	Failure	1	0	0

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

Frontal Air Bag System Deployment (This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Air Bag(s) Deployment, *Other* Than First Seat Frontal (This Occupant Position)
(0) Not equipped with an *"other"* air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	Availability/Function	1	1
	Use	1	1
	Type	2	2
	Proper Use	9	0
	Failure Modes	9	0

Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?		
Flaps open at tear points?		
Flaps damaged?		
Air bag damaged?		
Source of air bag damage		
Air bag tethered?		
Air bag have vent ports?		
Other occupant contact air bag?		
Occupant wearing eyewear?		

Type of Air Bag
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?
(0) Not equipped/not available
(1) No
(2) Yes (specify):

_____

(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

Was There Damage To The Air Bag?
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):

_____

(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

Source of Air Bag Damage
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):

_____

(03) Object carried by occupant, (specify):

_____

(04) Adaptive/assistive controls, (specify):

_____

(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify):

_____

(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

Was The Air Bag Tethered?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps):

_____

(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

Did The Air Bag Have Vent Ports?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports):

_____

(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
(0) Not equipped/not available
(1) No
(2) Yes (specify):

_____

(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

Was This Occupant Wearing Eye-wear?
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



4. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

5. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

6. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)
   a. Flap

   width (W) _____

   height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

   a. Upper Flap

   width (W_U) _____

   height (H_U) _____

   b. Lower Flap

   width (W_L) _____

   height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3	0	3
	Seat Type	02	00	02
	Seat Performance	1	0	0
	Seat Orientation	1	0	0
	Seat Track Position	5	0	0
	Seat Back Incline Pre/Post Impact	23	0	0
SECOND	Head Restraint Type/Damage	0	0	0
	Seat Type	09	09	09
	Seat Performance	0	0	0
	Seat Orientation	0	0	0
	Seat Track Position	0	0	0
	Seat Back Incline Pre/Post Impact	0	0	0
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

Deform due to impact

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other Specify):_____
(9) Unknown

Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Other seat type (specify): 04,05
(10) Box mounted seat (i.e., van type)
(99) Unknown

Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify):
(7) Combination of above (specify):
(8) Other (specify):
(9) Unknown

Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
(9) Unknown

Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown



Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

   (0) No child safety seat
   (1) Infant seat
   (2) Toddler seat
   (3) Convertible seat
   (4) Booster seat
   (7) Other type child safety seat (specify):

   _____

   (8) Unknown child safety seat type
   (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

   (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   (01) Rear facing
   (02) Forward facing
   (08) Other orientation (specify):

   _____

   (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   (11) Rear facing
   (12) Forward facing
   (18) Other orientation (specify):

   _____

   (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   (21) Rear facing
   (22) Forward facing
   (28) Other orientation (specify):

   _____

   (29) Unknown orientation

   (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.

   (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   (01) After market harness/shield/tether added, not used
   (02) After market harness/shield/tether used
   (03) Child safety seat used, but no after market harness/shield/tether added
   (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   (11) Harness/shield/tether not used
   (12) Harness/shield/tether used
   (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   (21) Harness/shield/tether not used
   (22) Harness/shield/tether used
   (29) Unknown if harness/shield/tether used

   (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [X] Yes [ ]
Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [X] Yes [ ]
Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 042A
3. Vehicle Number: 01
4. Occupant Number: 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 24
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 183
Code actual height to the nearest centimeter.
(999) Unknown
72 inches X 2.54 = 182.8 centimeters

8. Occupant's Weight: 077
Code actual weight to the nearest kilogram.
(999)Unknown
170 pounds X .4536 = 077.1 kilograms

9. Occupant's Role: 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 2
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection [0]
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area [0]
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.)
    (specify):_____
    (9) Unknown

14. Ejection Medium [0]
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) [0]
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment [0]
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility [0]
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 3
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 99
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify):
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 9
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 0
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 1
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 2
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 9
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 9
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 3
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
[X] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present: _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 000
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 00
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 0 0
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):
(03) Object carried by occupant, (specify):
(04) Adaptive/assistive controls, (specify):
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify):
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps):
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports):
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 3
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify):
(9) Unknown

50. Seat Type (this Occupant Position) 0 2
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 5
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 23

(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown







54. Seat Performance (this Occupant Position) 1

(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):_____
(4) Seat track/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion, (specify):_____
_____
(7) Combination of above (specify):
_____
(8) Other (specify): _____
(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 4

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 1

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 0

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 0 0

(00) Not Hospitalized
_____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 6 2

_____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 01
Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 99

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
(97) Other result (includes fatal ruled disease) (specify):
(99) Unknown

70. Number of Recorded Injuries for This Occupant 97
Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 97
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units):
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 97
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):
(9) Unknown if belt used

U.S. Department of Transportation

National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	03	3. Vehicle Number	01
2. Case Number - Stratum	042A	4. Occupant Number	01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.
2nd	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.
3rd	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.
4th	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.
5th	49.	50.	51.	52.	53.	54.	55.	56.	57.	58.	59.
6th	60.	61.	62.	63.	64.	65.	66.	67.	68.	69.	70.
7th	71.	72.	73.	74.	75.	76.	77.	78.	79.	80.	81.
8th	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.
9th	93.	94.	95.	96.	97.	98.	99.	100.	101.	102.	103.
10th	104.	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th	—	—	—	— —	— —	—	—	— — —	—	—	— —
12th	—	—	—	— —	— —	—	—	— — —	—	—	— —
13th	—	—	—	— —	— —	—	—	— — —	—	—	— —
14th	—	—	—	— —	— —	—	—	— — —	—	—	— —
15th	—	—	—	— —	— —	—	—	— — —	—	—	— —
16th	—	—	—	— —	— —	—	—	— — —	—	—	— —
17th	—	—	—	— —	— —	—	—	— — —	—	—	— —
18th	—	—	—	— —	— —	—	—	— — —	—	—	— —
19th	—	—	—	— —	— —	—	—	— — —	—	—	— —
20th	—	—	—	— —	— —	—	—	— — —	—	—	— —
21st	—	—	—	— —	— —	—	—	— — —	—	—	— —
22nd	—	—	—	— —	— —	—	—	— — —	—	—	— —
23rd	—	—	—	— —	— —	—	—	— — —	—	—	— —
24th	—	—	—	— —	— —	—	—	— — —	—	—	— —
25th	—	—	—	— —	— —	—	—	— — —	—	—	— —

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs. Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify):

(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify) _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify): _____
(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify): _____
(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify): _____
(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify): _____
(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify): _____
(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Blood Alcohol Level (mg/dl)

BAL = ____

Glasgow Coma Scale Score

GCSS = ____

Units of Blood Given

Units = ____

Arterial Blood Gases

pH = _.__

PO_2 = ____

PCO_2 ____

HCO_3 ____

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction — 2
    (0) Non-interchange area and non-junction
    (1) Interchange area related

    Non-Interchange junctions
    (2) Intersection related
    (3) Driveway, alley access related
    (4) Other junction (specify) _____
    (5) Unknown type of junction

    (9) Unknown

20. Trafficway Flow — 0
    (0) Not physically divided (two way traffic)
    (1) Divided trafficway-median strip without positive barrier
    (2) Divided trafficway-median strip with positive barrier
    (3) One way traffic
    (9) Unknown

21. Number Of Travel Lanes — 2
    (1) One
    (2) Two
    (3) Three
    (4) Four
    (5) Five
    (6) Six
    (7) Seven or more
    (9) Unknown

22. Roadway Alignment — 1
    (1) Straight
    (2) Curve right
    (3) Curve left
    (9) Unknown

23. Roadway Profile — 1
    (1) Level
    (2) Uphill grade (>2%)
    (3) Hill crest
    (4) Downhill grade (>2%)
    (5) Sag
    (9) Unknown

24. Roadway Surface Type — 2
    (1) Concrete
    (2) Bituminous (asphalt)
    (3) Brick or block
    (4) Slag, gravel, or stone
    (5) Dirt
    (8) Other (specify): _____
    (9) Unknown

25. Roadway Surface Condition — 1
    (1) Dry
    (2) Wet
    (3) Snow or slush
    (4) Ice
    (5) Sand, dirt, or oil
    (8) Other (specify): _____
    (9) Unknown

26. Light Conditions — 4
    (1) Daylight
    (2) Dark
    (3) Dark, but lighted
    (4) Dawn
    (5) Dusk
    (9) Unknown

27. Atmospheric Conditions — 0
    (0) No adverse atmospheric-related driving conditions
    (1) Rain
    (2) Sleet/hail
    (3) Snow
    (4) Fog
    (5) Rain and fog
    (6) Sleet and fog
    (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
    (9) Unknown

28. Traffic Control Device — 1
    (0) No traffic control(s)
    (1) Traffic control signal (not RR crossing)

    Regulatory
    (2) Stop sign
    (3) Yield sign
    (4) School zone sign
    (5) Other regulatory sign (specify): _____
    (6) Warning sign (not RR crossing)
    (7) Unknown sign
    (8) Miscellaneous/other controls including RR controls (specify): _____
    (9) Unknown

29. Traffic Control Device Functioning — 2
    (0) No traffic control device
    (1) Traffic control device not functioning (specify): _____
    (2) Traffic control device functioning properly
    (9) Unknown

PSU 03-042A V-02

OCCUPANT RELATED

37. Driver Presence in Vehicle — 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle — 02
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted — 02

AIR BAG RELATED

40. Is this an AOPS Vehicle? — 0
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal — 0
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal — 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight — 1,630
____ Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
3,586 lbs X .4536 = 1,627 kgs

Source: _____

44. Vehicle Cargo Weight — 0,000
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown
____,____ lbs X .4536 = ____,____ kgs

Source: _____

ROLLOVER DATA

45. Rollover (L) (T) — 04 ~~02~~
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns
(specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type — 07
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify):
_____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation — 1
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted — 02
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied — 3
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane → Front Bumper
(4) Undercarriage
(5) Other location on vehicle (specify):
_____
(6) Non-contact rollover forces (specify):
_____
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll — 1 ~~2~~
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

PSU 03-042A V-02

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

(89) Unknown nonfixed object

(98) Other event (specify):

(99) Unknown event or object

U.S. Department of Transportation

National Highway Traffic Safety Administration

BEST AVAILABLE

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 042A
3. Vehicle Number: 02

VEHICLE IDENTIFICATION

VIN 1G1BL6965GX[redacted] Model Year 86

Vehicle Make (specify): chevrolet Vehicle Model (specify): caprice

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	110 Rt the left 3/4 of Bumper	174 End To End	at C6

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage		Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
		Width (CDC)	Max Crush								
1	Front Bumper	110	88.	174.	88.	71.	59.	44.	30	30X	
	F|S		21.		21	6.0	00	00	6.0	21.	
1	adj "C"		67.		67.	65.	59.0	44.	24.	9.	-33.
2	L Plane										
	Rollover										
3	T Roof										

HS Form 435A (Rev. 1/95)

BEST AVAILABLE

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	116.0	inches	x 2.54	=	294.6 cm
Overall Length	212.2	inches	x 2.54	=	538.9 cm
Maximum Width	75.4	inches	x 2.54	=	191.5 cm
Curb Weight	3586	pounds	x .4536	=	1626.6 kg
Average Track	61.2	inches	x 2.54	=	155 cm
Front Overhang	___.__	inches	x 2.54	=	103 cm
Rear Overhang	___.__	inches	x 2.54	=	141 cm
Undeformed End Width	___.__	inches	x 2.54	=	176 cm
Engine Size: cyl./displ.	V8 5.7	cc	x .001	=	5.7 L
	___	CID	x .0164	=	__.__ L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

	a. Rotation physically restricted	b. Tire deflated
RF	2	2
LF	2	2
RR	2	2
LR	2	2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☒ Automatic

END SHIFT ≥ 10 CM

☐ Yes ☒ No

ORIGINAL SPECIFICATIONS

Wheelbase	295.	cm
Overall Length	539.	cm
Maximum Width	192.	cm
Curb Weight	1627	kg
Average Track	155	cm
Front Overhang	103	cm
Rear Overhang	141	cm
Undeformed End Width	176	cm
Engine Size: cyl./displ.	V8 5.7	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± ____ ____ o
LF ± ____ ____ o
RR ± ____ ____ o
LR ± ____ ____ o

Within ± 5 degrees

DRIVE WHEELS

☐ FWD ☒ RWD ☐ 4WD

Approximate Cargo Weight 000 kg

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	01	335°	99	F	Y	E	W	03
02	31	999	99	±T	D	A O	0	01
03	61	999	99	T	D	G	0	01

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 01	6. 11	7. F	8. Y	9. E	10. W	11. 03

Second Highest Delta "V"

12. 02	13. 31	14. 00	15. ~~L~~ T	16. D	17. ~~A~~ D	18. 0	19. 01

MASS CODING CHANGE
1st Review: IG
2nd Review:

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
176	067	065	059	044	024	009	±033

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
							+ −

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 176
____ Code to the nearest centimeter
(250) 250 centimeters or more
(998) No highest severity end plane impact
(999) Unknown

27. Direct Damage Width (For highest severity impact) 174
____ Code to the nearest centimeter
(250) 250 centimeters or more
(999) Unknown

28. Original Wheelbase 295
____ Code to the nearest centimeter
(650) 650 centimeters or more
(999) Unknown
____.__ inches X 2.54 = 294.6 centimeters

29. Original Average Track Width 155
____ Code to the nearest centimter
(185) 185 centimeters or more
(999) Unknown
61.2 inches X 2.54 = 155 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 1
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): _____
_____
_____
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify):
_____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 1

36. Location of Fuel Tank-2 Filler Cap 0
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify):_____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 1

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify):_____
(9) Unknown

41. Damage to Fuel Tank-1 1

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify):_____
(9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 03
2. Case Number - Stratum 042A
3. Vehicle Number 02

INTEGRITY

4. Passenger Compartment Integrity 98
(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify): 01, 06
(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 3 7. LR 3 8. RR 3 9. TG/H 0

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code 0

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 4 17. RF 4 18. LR 4 19. RR 4
20. BL 4 21. Roof 0 22. Other 4

(0) No glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted (original)
(4) AS-2 — Tempered-with after market tint
(5) AS-3 — Tempered-tinted (with additional after market tint)
(6) AS-14 — Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify):
(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 3 25. RF 3 26. LR 3 27. RR 3
28. BL 1 29. Roof 0 30. Other 1

(0) No glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown

Glazing Damage from Impact Forces

31. WS 3 32. LF 6 33. RF 1 34. LR 1 35. RR 6
36. BL 1 37. Roof 0 38. Other 6

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 9 40. LF 1 41. RF 1 42. LR 1 43. RR 1
44. BL 1 45. Roof 0 46. Other 1

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas





LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters) COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION
11	13	0.0	–	18.	=	18 cm	
12	13	0.0	–	18.	=	18 cm	
13	13	0.0	–	21.	=	21 cm	
13	14	0.0	–	21.	=	21 cm	
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 1 1	48. 1 3	49. 3	50. 1
2nd	51. 1 2	52. 1 3	53. 3	54. 1
3rd	55. 1 3	56. 1 3	57. 3	58. 1
4th	59. 1 3	60. 1 4	61. 3	62. 1
5th	63.	64.	65.	66.
6th	67.	68.	69.	70.
7th	71.	72.	73.	74.
8th	75.	76.	77.	78.
9th	79.	80.	81.	82.
10th	83.	84.	85.	86.

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail (R)
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	–	DAMAGE VALUE	=	DEFORMATION
0,0	–	2, cm	=	2, Cm
	–		=	
	–		=	
	–		=	

STEERING COLUMN

87. Steering Column Type — 1
(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify): _____
(9) Unknown

88. Tilt Steering Column Adjustment — 0
(0) No tilt steering column
(1) Full up
(2) Between full up and center
(3) Center
(4) Between center and full down
(5) Full down
(9) Unknown

89. Telescoping Steering Column Adjustment — 0
(0) No telescoping steering column
(1) Full back
(2) Between full back and midpoint
(3) Midpoint
(4) Between midpoint and full forward
(5) Full forward
(9) Unknown

90. Steering Rim/Spoke Deformation — 0 2
2 cm Code actual measured deformation to the nearest centimeter
(00) No steering rim deformation
(01-14) Actual measured value in centimeters
(15) 15 centimeters or more
(98) Observed deformation cannot be measured
(99) Unknown

91. Location of Steering Rim/Spoke Deformation — 6 5
(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D



Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke



(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

INSTRUMENT PANEL

92. Odometer Reading — 259,000
____ kilometers
Code to the nearest 1,000 kilometers
(000) No odometer
(001) Less than 1,500 kilometers
(500) 499,500 kilometers or more
(999) Unknown
160952 miles X 1.6093 = 259,020 kilometers

Source: _____

93. Instrument Panel Damage from Occupant Contact? — 1
(0) No
(1) Yes
(9) Unknown

94. Type of Knee Bolster Covering — 2
(0) No knee bolster
(1) Padded
(2) Rigid plastic
(8) Other (specify): _____
(9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? — 1
(0) No knee bolster
(1) No deformation
(2) Yes - deformation
(9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? — 2
(0) No glove compartment door
(1) No - door did not open
(2) Yes - door opened
(9) Unknown

97. Adaptive (Assistive) Driving Equipment — 0
(0) No adaptive driving equipment
(1) Adaptive driving equipment installed
(Check all that apply.)
[ ] Hand controls for braking/acceleration
[ ] Steering control devices (attached to OEM steering wheel
[ ] Steering knob attached to steering wheel
[ ] Low effort power steering (unit or device)
[ ] Replacement steering wheel (i.e., reduced diameter)
[ ] Joy-stick steering controls
[ ] Wheelchair tie-downs
[ ] Modification to seat belts (specify): _____
[ ] Additional or relocated switches (specify): _____
[ ] Raised roof
[ ] Wall-mounted head rest (used behind wheelchair)
[ ] Other adaptive device (specify): _____
(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	003	01	Head	impression	1
B	010	01	(L) Knee	F.X. Cracked	1
C	006	01	Chest	deformed	1
D	019	02	unk	deformed.	1
E	205	02	unk	impression	1
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column,transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment(e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object, (specify): _____
- (019) Other front object (specify): protection Barrier

LEFT SIDE
- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): _____
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): _____

RIGHT SIDE
- (101) Right side interior surface, excluding hardware or armrests
- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): _____
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): _____

INTERIOR
- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): _____
- (155) Head restraint system
- (160) Other occupants (specify): _____
- (161) Interior loose objects
- (162) Child safety seat (specify): _____
- (163) Other interior object (specify): _____

AIR BAG
- (170) Air bag-driver side
- (175) Air bag compartment cover-driver side
- (180) Air bag-passenger side
- (185) Air bag compartment cover-passenger side
- (190) Other air bag (specify) _____
- (195) Other air bag compartment cover (specify) _____

ROOF
- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

FLOOR
- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

REAR
- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): _____
- (409) Additional or relocated switches, (specify): _____
- (410) Raised roof
- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data **for each seat position** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	0	4
	Evidence of usage	04	00	04
	Used in this crash?	00	00	00
	Proper Use	0	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment	1	0	1
SECOND	Availability	3	3	3
	Evidence of usage	03	03	03
	Used in this crash?	0	0	0
	Proper Use	0	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment	0	0	0
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability

(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available - type unknown

Integral Belt Partially Destroyed

(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperable (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used - type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat - type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

Proper Use of Manual (Active) Belts

(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly

(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

Shoulder Belt Upper Anchorage Adjustment

(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
FIRST	Availability/Function			
	Deployment			
	Failure			

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify):
_____
(3) Air bag not reinstalled
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify):
_____
(9) Unknown

Frontal Air Bag System Deployment (This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Air Bag(s) Deployment, *Other* Than First Seat Frontal (This Occupant Position)
(0) Not equipped with an *"other"* air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	Availability/Function		
	Use		
	Type		
	Proper Use		
	Failure Modes		

Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):
_____
(8) Other improper use of automatic belt system (specify):_____
(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):
_____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):
_____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?		
Flaps open at tear points?		
Flaps damaged?		
Air bag damaged?		
Source of air bag damage		
Air bag tethered?		
Air bag have vent ports?		
Other occupant contact air bag?		
Occupant wearing eyewear?		

Type of Air Bag
- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was There Damage To The Air Bag?
- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage
- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify): _____
- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Source of Air Bag Damage
- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify): _____
- (03) Object carried by occupant, (specify): _____
- (04) Adaptive/assistive controls, (specify): _____
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify): _____
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Was The Air Bag Tethered?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps): _____
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Did The Air Bag Have Vent Ports?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports): _____
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was This Occupant Wearing Eye-wear?
- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



4. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

5. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

6. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)
   a. Flap

   width (W) _____

   height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

   a. Upper Flap

   width (W_U) _____

   height (H_U) _____

   b. Lower Flap

   width (W_L) _____

   height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG



4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3	0	3
	Seat Type	06	06	06
	Seat Performance	1	0	0
	Seat Orientation	1	1	1
	Seat Track Position	9	0	5
	Seat Back Incline Pre/Post Impact	23	00	15
SECOND	Head Restraint Type/Damage		0	0
	Seat Type	03	03	03
	Seat Performance	0	0	1
	Seat Orientation	0	0	1
	Seat Track Position	0	0	1
	Seat Back Incline Pre/Post Impact	00	01	01
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other Specify):_____
(9) Unknown

Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Other seat type (specify):
_____
(10) Box mounted seat (i.e., van type)
(99) Unknown

Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
_____
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify):_____
(7) Combination of above (specify):
_____
(8) Other (specify):
_____
(9) Unknown

Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown



Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

   (0) No child safety seat
   (1) Infant seat
   (2) Toddler seat
   (3) Convertible seat
   (4) Booster seat
   (7) Other type child safety seat (specify):

   _____

   (8) Unknown child safety seat type
   (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

   (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   (01) Rear facing
   (02) Forward facing
   (08) Other orientation (specify):

   _____

   (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   (11) Rear facing
   (12) Forward facing
   (18) Other orientation (specify):

   _____

   (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   (21) Rear facing
   (22) Forward facing
   (28) Other orientation (specify):

   _____

   (29) Unknown orientation

   (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.

   (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   (01) After market harness/shield/tether added, not used
   (02) After market harness/shield/tether used
   (03) Child safety seat used, but no after market harness/shield/tether added
   (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   (11) Harness/shield/tether not used
   (12) Harness/shield/tether used
   (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   (21) Harness/shield/tether not used
   (22) Harness/shield/tether used
   (29) Unknown if harness/shield/tether used

   (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [X] Yes [ ]
Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [X] Yes [ ]
Describe entrapment mechanism: all doors jammed shut

Component(s): _____

(Note in vehicle interior diagram)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 0 4 2 A
3. Vehicle Number: 02
4. Occupant Number: 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 36
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 999
Code actual height to the nearest centimeter.
(999) Unknown

___ ___ inches X 2.54 = ___ ___ ___ centimeters

8. Occupant's Weight: 999
Code actual weight to the nearest kilogram.
(999)Unknown

___ ___ ___ pounds X .4536 = ___ ___ ___ kilograms

9. Occupant's Role: 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 11

Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.)
    (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility 9
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 99
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify):
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 9
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 1
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 0
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 0
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 0
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 3
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
[X] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present:

    _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 2
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + / − 000
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 00
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 00
    (00) Not equipped/not available
    (01) Not damaged
    (02) Object worn by occupant, (specify):
    (03) Object carried by occupant, (specify):
    (04) Adaptive/assistive controls, (specify):
    (05) Fire in vehicle
    (06) Thermal burns
    (07) Rescue or emergency efforts
    (88) Other damage source (specify):
    (95) Damaged, unknown source
    (96) Deployed, unknown if damaged
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

45. Was The Air Bag Tethered? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of tether straps):
    (3) Deployed, unknown if tethered
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

46. Did The Air Bag Have Vent Ports? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of vent ports):
    (3) Deployed, unknown if vent ports present
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 6
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify):
    (3) Deployed, unknown if other occupant contact to air bag
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
    (0) Not equipped/not available
    (1) No
    (2) Eyeglasses/sunglasses
    (3) Contact lenses
    (4) Deployed, unknown if eyewear worn
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 3
    (0) No head restraints
    (1) Integral—no damage
    (2) Integral—damaged during accident
    (3) Adjustable—no damage
    (4) Adjustable—damaged during accident
    (5) Add-on—no damage
    (6) Add-on—damaged during accident
    (8) Other (specify):
    (9) Unknown

50. Seat Type (this Occupant Position) 06
    (00) Occupant not seated or no seat
    (01) Bucket
    (02) Bucket with folding back
    (03) Bench
    (04) Bench with separate back cushions
    (05) Bench with folding back(s)
    (06) Split bench with separate back cushions
    (07) Split bench with folding back(s)
    (08) Pedestal (i.e., column supported)
    (09) Box mounted seat (i.e., van type)
    (10) Other seat type (specify):
    (99) Unknown

51. Seat Orientation (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) Forward facing seat
    (2) Rear facing seat
    (3) Side facing seat (inward)
    (4) Side facing seat (outward)
    (8) Other (specify):
    (9) Unknown

52. Seat Track Adjusted Position Prior To Impact 9
    (0) Occupant not seated or no seat
    (1) Non-adjustable seat track

    Adjustable Seat Track
    (2) Seat at forward most track position
    (3) Seat between forward most and middle track positions
    (4) Seat at middle track position
    (5) Seat between middle and rear most track positions
    (6) Seat at rear most track position
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 23

(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown







54. Seat Performance (this Occupant Position) 1

(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):_____
(4) Seat track/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion, (specify):_____
(7) Combination of above (specify):_____
(8) Other (specify): _____
(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 000
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):

_____

(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):

_____

(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 00
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):

_____

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):

_____

(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):

_____

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 00

59. Child Safety Seat Shield Usage 00

60. Child Safety Seat Tether Usage 00

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 3

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 8

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 9 9

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 9 9

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 00
_____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 00

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
_____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 01
_____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 02
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO_3 01
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

U.S. Department of Transportation

National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	03	3. Vehicle Number	02
2. Case Number - Stratum	042A	4. Occupant Number	01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. 9	6. 1	7. 1	8. 50	9. 99	10. 7	11. 0	12. 003	13. 2	14. 1	15. 00
2nd	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.
3rd	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.
4th	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.
5th	49.	50.	51.	52.	53.	54.	55.	56.	57.	58.	59.
6th	60.	61.	62.	63.	64.	65.	66.	67.	68.	69.	70.
7th	71.	72.	73.	74.	75.	76.	77.	78.	79.	80.	81.
8th	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.
9th	93.	94.	95.	96.	97.	98.	99.	100.	101.	102.	103.
10th	104.	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th	—	—	—	— —	— —	—	—	— — —	—	—	— —
12th	—	—	—	— —	— —	—	—	— — —	—	—	— —
13th	—	—	—	— —	— —	—	—	— — —	—	—	— —
14th	—	—	—	— —	— —	—	—	— — —	—	—	— —
15th	—	—	—	— —	— —	—	—	— — —	—	—	— —
16th	—	—	—	— —	— —	—	—	— — —	—	—	— —
17th	—	—	—	— —	— —	—	—	— — —	—	—	— —
18th	—	—	—	— —	— —	—	—	— — —	—	—	— —
19th	—	—	—	— —	— —	—	—	— — —	—	—	— —
20th	—	—	—	— —	— —	—	—	— — —	—	—	— —
21st	—	—	—	— —	— —	—	—	— — —	—	—	— —
22nd	—	—	—	— —	— —	—	—	— — —	—	—	— —
23rd	—	—	—	— —	— —	—	—	— — —	—	—	— —
24th	—	—	—	— —	— —	—	—	— — —	—	—	— —
25th	—	—	—	— —	— —	—	—	— — —	—	—	— —

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs. Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify)

(019) Other front object (specify):

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify):

(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify):

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify):

(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify):

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify):

(155) Head restraint system
(160) Other occupants (specify):

(161) Interior loose objects
(162) Child safety seat (specify):

(163) Other interior object (specify):

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify)

(195) Other air bag compartment cover (specify)

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify):

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify):
(409) Additional or relocated switches, (specify):

(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify):

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify):

(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify):

(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify):

(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify):

(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify):

(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify):
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Blood Alcohol Level (mg/dl)

BAL = ____

Glasgow Coma Scale Score

GCSS = ____

Units of Blood Given

Units = ____

Arterial Blood Gases

pH = __.__

PO_2 = ____

PCO_2 ____

HCO_3 ____

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





U.S. Department of Transportation
National Highway Traffic Safety Administration

UPDATE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number — Stratum: 042A
3. Vehicle Number: 02
4. Occupant Number: 01

RECEIVED [redacted] 1995

Driver or Occupant Name: _____

Address: _____

_____

Other Information: _____

_____

(Sanitize this section prior to Update submission.)

STATUS OF OCCUPANT INFORMATION

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL08.	Date Official Medical Data Requested	[redacted]	95
OAL09.	Date Official Medical Data Obtained	[redacted]	95
OAL16.	Injury Treatment Status	09	
OAL17.	Injury Information		
	Official		
a.	Autopsy (invasive examination)	B	
b.	Post-ER medical record which includes information about death based on non-invasive examination	B	
c.	Admission record/summary or admission/discharge face sheet	B	
d.	Discharge summary	B	
e.	Operative report	B	
f.	Radiographic record(s) (X-ray, CT scan)	B	
g.	History and physical examination and/or consultation records	B	
h.	Emergency room records (includes nurses' notes)	B 08	01
j.	Private physician	B	
	Unofficial		
k.	Lay coroner	B	
l.	EMS record	B	
m.	Interviewee	B	
n.	Other source (specify): _____	B	B
o.	Police report	B 1	B

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL18.	Medical Facility Code	03	
GV14.	Alcohol Test Results For Driver	96	
GV16.	Other Drug Specimen Test Type For Driver	0	
OA05.	Occupant's Age	36	
OA06.	Occupant's Sex	1	
OA07.	Occupant's Height	999	
OA08.	Occupant's Weight	999	
OA61.	Treatment-Mortality	9	
OA62.	Type of Medical Facility (for Initial Treatment)	9	
OA63.	Hospital Stay	99	

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number - Stratum: 0428A
3. Vehicle Number: 02
4. Occupant Number: 02

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age: 25
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex: 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height: 999
Code actual height to the nearest centimeter.
(999) Unknown

___ ___ inches X 2.54 = ___ ___ ___ centimeters

8. Occupant's Weight: 999
Code actual weight to the nearest kilogram.
(999)Unknown

___ ___ ___ pounds X .4536 = ___ ___ ___ kilograms

9. Occupant's Role: 2
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position: 23
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture: 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.)
    (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify):
    _____
    (5) Integral structure
    (8) Other medium (specify):
    _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc.
    (specify):_____
    _____
    (9) Unknown

17. Occupant Mobility 9
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or disoriented
    (2) Removed from vehicle due to injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 3
(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available—type unknown

Integral Belt Partially Destroyed
(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 0 0
(00) None used, not available, or belt removed/destroyed
(01) Inoperative (specify):

(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used—type unknown
(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat—type unknown
(18) Other belt used with child safety seat (specify):
(99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 0
(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly
(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 6
(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 0
(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage
(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/ Function 0
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

24. Automatic (Passive) Belt System Use 0
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
(3) Automatic belt use unknown
(9) Unknown

25. Automatic (Passive) Belt System Type 0
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):
(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 0
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify):

    _____

    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[ ] Not equipped/not available/destroyed or rendered inoperative
[X] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify):

_____

[ ] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify):

    _____

    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify):

    _____

    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present:

    _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify):

    _____

    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 000 / − ____
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 00
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 0 0
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify):
(03) Object carried by occupant, (specify):
(04) Adaptive/assistive controls, (specify):
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify):
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps):
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports):
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 0
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify):
(9) Unknown

50. Seat Type (this Occupant Position) 0 3
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 1
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 01

(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position



Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position



Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 1

(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):_____
(4) Seat track/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion, (specify):_____
(7) Combination of above (specify):_____
(8) Other (specify): _____
(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model ___
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat ___
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation ___
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage ___

59. Child Safety Seat Shield Usage ___

60. Child Safety Seat Tether Usage ___

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 3

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 8

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 99

(00) Not Hospitalized
_____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 99

_____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 00
_____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 00

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
_____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 01
_____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 02
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 01
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	03	3. Vehicle Number	02
2. Case Number - Stratum	042A	4. Occupant Number	02

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. 2	6. 1	7. 1	8. 50	9. 29	10. 7	11. 0	12. 605	13. 3	14. 1	15. 00
2nd	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.
3rd	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.
4th	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.
5th	49.	50.	51.	52.	53.	54.	55.	56.	57.	58.	59.
6th	60.	61.	62.	63.	64.	65.	66.	67.	68.	69.	70.
7th	71.	72.	73.	74.	75.	76.	77.	78.	79.	80.	81.
8th	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.
9th	93.	94.	95.	96.	97.	98.	99.	100.	101.	102.	103.
10th	104.	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th											
12th											
13th											
14th											
15th											
16th											
17th											
18th											
19th											
20th											
21st											
22nd											
23rd											
24th											
25th											

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify)

(019) Other front object (specify):

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify):

(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify):

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify):

(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify):

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify):

(155) Head restraint system
(160) Other occupants (specify):

(161) Interior loose objects
(162) Child safety seat (specify):

(163) Other interior object (specify):

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify)

(195) Other air bag compartment cover (specify)

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify):

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify):
(409) Additional or relocated switches, (specify):

(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify):

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify):

(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify):

(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify):

(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify):

(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify):

(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify):
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Blood Alcohol Level (mg/dl)

BAL = ____

Glasgow Coma Scale Score

GCSS = ____

Units of Blood Given

Units = ____

Arterial Blood Gases

pH = __.__

PO_2 = ____

PCO_2 ____

HCO_3 ____

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

UPDATE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 03
2. Case Number — Stratum: 042A
3. Vehicle Number: 02
4. Occupant Number: 02

[redacted]1995

Driver or Occupant Name: _____

Address: _____

_____

Other Information: _____

_____

(Sanitize this section prior to Update submission.)

STATUS OF OCCUPANT INFORMATION

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL08.	Date Official Medical Data Requested	[redacted]/95	
OAL09.	Date Official Medical Data Obtained	[redacted]/96	
OAL16.	Injury Treatment Status	09	09
OAL17.	Injury Information		
	Official		
a.	Autopsy (invasive examination)	B	
b.	Post-ER medical record which includes information about death based on non-invasive examination	B	
c.	Admission record/summary or admission/discharge face sheet	B	
d.	Discharge summary	B	
e.	Operative report	B	
f.	Radiographic record(s) (X-ray, CT scan)	B	
g.	History and physical examination and/or consultation records	B	
h.	Emergency room records (includes nurses' notes)	B 08	01
j.	Private physician	B	
	Unofficial		
k.	Lay coroner	B	
l.	EMS record	B	
m.	Interviewee	B 11	
n.	Other source (specify): _____	B	B
o.	Police report	B 11	B

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL18.	Medical Facility Code	03	03
GV14.	Alcohol Test Results For Driver	96	96
GV16.	Other Drug Specimen Test Type For Driver	0	0
OA05.	Occupant's Age	25	25
OA06.	Occupant's Sex	1	1
OA07.	Occupant's Height	999	999
OA08.	Occupant's Weight	999	999
OA61.	Treatment-Mortality	9	9
OA62.	Type of Medical Facility (for Initial Treatment)	9	9
OA63.	Hospital Stay	99	99

Imp 1

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title				
03	042A	01	[redacted]	95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.		Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1989	52	035	1
Vehicle 2	1986	20	002	2

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	1	5
Weight	1030 (Curb) + 77 (Occupant(s)) + 00 (Cargo) = 1107 kg	1627 (Curb) + 158 (Occupant(s)) + 000 (Cargo) = 1785 kg
CDC	02RYEW3	11FYEW3
PDOF (-180 to +180)	±045°	±25°
Stiffness	1	5

SCENE INFORMATION

Rest and Impact Positions [X] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	___°	___°
Impact Position	X	____.____ m	____.____ m
	Y	____.____ m	____.____ m
	PSI	___°	___°
Slip Angle(-180 to +180)		___°	___°

VEHICLE MOTION

Sustained Contact [X] No [ ] Yes

	VEHICLE 1	VEHICLE 2
Vehicle Rotation	[X] No [ ] Yes	[X] No [ ] Yes
Rotation Stop Before Rest	[X] No [ ] Yes	[X] No [ ] Yes
End of Rotation Position X	____.____ m	____.____ m
End of Rotation Position Y	____.____ m	____.____ m
End of Rotation Position PSI	___°	___°
Curved Path	[X] No [ ] Yes	[X] No [ ] Yes
Point on Path X	____.____ m	____.____ m
Point on Path Y	____.____ m	____.____ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [X] **No** [ ] **Yes**

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [X] **No** [ ] **Yes**

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	342 cm	L	176 cm
Crush Depths	C_1	13 cm	C_1	67 cm
	C_2	30 cm	C_2	65 cm
	C_3	25 cm	C_3	59 cm
	C_4	00 cm	C_4	44 cm
	C_5	00 cm	C_5	24 cm
	C_6	00 cm	C_6	9 cm
Damage Offset	D	(+) 138 cm	Damage Offset	D (±) 33 cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT*, FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT

SUMMARY OF CRASHPC RESULTS USING DAMAGE

042A

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	46 KPH (29 MPH)
LONGITUDINAL	-33 KPH (-20 MPH)
LATITUDINAL	-33 KPH (-20 MPH)
PDOF ANGLE	45 DEGREES
ENERGY DISSIPATED =	38994 JOULES (28757 FT-LB)
VEHICLE #2	
TOTAL	29 KPH (18 MPH)
LONGITUDINAL	-26 KPH (-16 MPH)
LATITUDINAL	12 KPH (8 MPH)
PDOF ANGLE	-25 DEGREES
ENERGY DISSIPATED =	137306 JOULES (101258 FT-LB)

PRESS ANY KEY TO CONTINUE

INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT

DAMAGE DATA

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	1	5
STIFFNESS CATEGORY	1	5
VEHICLE WEIGHT	1107 KGS (2440 LBS)	1785 KGS (3935 LBS)
CDC	02RYEW3	11FYEW3
PDOF ANGLE	45 DEGREES	-25 DEGREES
CRUSH LENGTH	342 CM. (135 IN.)	176 CM. (69 IN.)
C1	13 CM. (5 IN.)	67 CM. (26 IN.)
C2	30 CM. (12 IN.)	65 CM. (26 IN.)
C3	25 CM. (10 IN.)	59 CM. (23 IN.)
C4	0 CM. (0 IN.)	44 CM. (17 IN.)
C5	0 CM. (0 IN.)	24 CM. (9 IN.)
C6	0 CM. (0 IN.)	9 CM. (4 IN.)
D	138 CM. (54 IN.)	33 CM. (13 IN.)
D'	58 CM. (23 IN.)	13 CM. (5 IN.)

(* INDICATES DEFAULT VALUE)
PRESS ANY KEY TO CONTINUE

INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	115 CM. (45 IN.)	142 CM. (56 IN.)
CG TO REAR AXLE	122 CM. (48 IN.)	160 CM. (63 IN.)
TRACK	130 CM. (51 IN.)	162 CM. (64 IN.)
CG TO FRONT OF VEH	193 CM. (76 IN.)	259 CM. (102 IN.)
CG TO REAR OF VEH	-213 CM. (-84 IN.)	-310 CM. (-122 IN.)
CG TO SIDE OF VEH	77 CM. (30 IN.)	101 CM. (40 IN.)
MOMENT OF INERTIA	5774 KGS (12729 LBS)	18750 KGS (41337 LBS)
VEHICLE MASS	3 KGS (6 LBS)	5 KGS (10 LBS)

PRESS ANY KEY TO CONTINUE

Printing Picture: 042A



DAMAGE DESCRIPTION

35MPH V1

U.S. Department of Transportation

National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

03	0420	04	[redacted] 95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1989	MITSUBISHI	MIRAGE	01
Vehicle 2				11

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	1	11
Weight	1030 (Curb) + 77 (Occupant(s)) + — (Cargo) = 1107 kg	____ (Curb) + ____ (Occupant(s)) + ____ (Cargo) = ____ kg
CDC	1OLYEW2	
PDOF (-180 to +180)	±050 °	± ____ °
Stiffness	1	

SCENE INFORMATION

Rest and Impact Positions [ ] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____ . ____ m	____ . ____ m
	Y	____ . ____ m	____ . ____ m
	PSI	____ °	____ °
Impact Position	X	____ . ____ m	____ . ____ m
	Y	____ . ____ m	____ . ____ m
	PSI	____ °	____ °
Slip Angle(-180 to +180)		____ °	____ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

	VEHICLE 1	VEHICLE 2
Vehicle Rotation	[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest	[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position X	____ . ____ m	____ . ____ m
Y	____ . ____ m	____ . ____ m
PSI	____ °	____ °
Curved Path	[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path X	____ . ____ m	____ . ____ m
Y	____ . ____ m	____ . ____ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] No [ ] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] No [ ] Yes

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	232 cm	L	___ ___ ___ cm
Crush Depths	C_1	006 cm	C_1	___ ___ ___ cm
	C_2	012 cm	C_2	___ ___ ___ cm
	C_3	004 cm	C_3	___ ___ ___ cm
	C_4	001 cm	C_4	___ ___ ___ cm
	C_5	000 cm	C_5	___ ___ ___ cm
	C_6	000 cm	C_6	___ ___ ___ cm
Damage Offset	D	±049 cm	D	± ___ ___ ___ cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :
HMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMM<

SUMMARY OF CRASHPC RESULTS USING DAMAGE

03 042B Z.C. RUN IMP.#4 V1

	SPEED CHANGE (DAMAGE)
VEHICLE #1	
TOTAL	7 KPH (4 MPH)
LONGITUDINAL	-4 KPH (-3 MPH)
LATITUDINAL	5 KPH (3 MPH)
PDOF ANGLE	-50 DEGREES
ENERGY DISSIPATED =	4494 JOULES (3314 FT-LB)
VEHICLE #2	
TOTAL	0 KPH (0 MPH)
LONGITUDINAL	0 KPH (0 MPH)
LATITUDINAL	0 KPH (0 MPH)
PDOF ANGLE	0 DEGREES
ENERGY DISSIPATED =	0 JOULES (0 FT-LB)

PRESS ANY KEY TO CONTINUE

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :
HMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMM<

DAMAGE DATA

	VEHICLE #1	VEHICLE #2
SIZE CATEGORY	1	11
STIFFNESS CATEGORY	1	0
VEHICLE WEIGHT	1107 KGS (2440 LBS)	****** KGS (2204586 LBS) *
CDC	10LYEW2	BARRIER
PDOF ANGLE	-50 DEGREES	0 DEGREES *
CRUSH LENGTH	232 CM. (91 IN.)	0 CM. (0 IN.) *
C1	0 CM. (0 IN.)	0 CM. (0 IN.) *
C2	12 CM. (5 IN.)	0 CM. (0 IN.) *
C3	4 CM. (2 IN.)	0 CM. (0 IN.) *
C4	1 CM. (0 IN.)	0 CM. (0 IN.) *
C5	0 CM. (0 IN.)	0 CM. (0 IN.) *
C6	0 CM. (0 IN.)	0 CM. (0 IN.) *
D	-49 CM. (-19 IN.)	0 CM. (0 IN.) *
D'	-102 CM. (-40 IN.)	0 CM. (0 IN.) *

(* INDICATES DEFAULT VALUE)
PRESS ANY KEY TO CONTINUE

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :
HMMM

Printing Picture:



U.S. Department of Transportation

National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

C 3	C 4 2 A	C 1	[redacted]	9 5
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.		Date (Month, day, year) of Run

CRASHPC Vehicle Identification

	Year	Make	Model	NASS Veh. No.
Vehicle 1	1989	MITSUBISHI	MIRAGE	1
Vehicle 2				11

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	1	11
Weight	1030 (Curb) + 77 (Occupant(s)) + - (Cargo) = 1107 kg	___ (Curb) + ___ (Occupant(s)) + ___ (Cargo) = ___ kg
CDC	01 FREW 3	___
PDOF (-180 to +180)	046 °	± ___ °
Stiffness	1	___

SCENE INFORMATION

Rest and Impact Positions [X] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	___ . ___ m	___ . ___ m
	Y	___ . ___ m	___ . ___ m
	PSI	___ °	___ °
Impact Position	X	___ . ___ m	___ . ___ m
	Y	___ . ___ m	___ . ___ m
	PSI	___ °	___ °
Slip Angle(-180 to +180)		___ °	___ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

	VEHICLE 1	VEHICLE 2
Vehicle Rotation	[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest	[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position X	___ . ___ m	___ . ___ m
End of Rotation Position Y	___ . ___ m	___ . ___ m
End of Rotation Position PSI	___ °	___ °
Curved Path	[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path X	___ . ___ m	___ . ___ m
Point on Path Y	___ . ___ m	___ . ___ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] No [ ] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] No [ ] Yes

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	342 cm	L	___ ___ ___ cm
Crush Depths	C_1	013 cm	C_1	___ ___ ___ cm
	C_2	030 cm	C_2	___ ___ ___ cm
	C_3	025 cm	C_3	___ ___ ___ cm
	C_4	000 cm	C_4	___ ___ ___ cm
	C_5	000 cm	C_5	___ ___ ___ cm
	C_6	000 cm	C_6	___ ___ ___ cm
Damage Offset	D	± 138 cm	D	± ___ ___ ___ cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :
HMMM

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	115 CM. (45 IN.)	127 CM. (50 IN.)
CG TO REAR AXLE	122 CM. (48 IN.)	127 CM. (50 IN.)
TRACK	130 CM. (51 IN.)	127 CM. (50 IN.)
CG TO FRONT OF VEH	193 CM. (76 IN.)	127 CM. (50 IN.)
CG TO REAR OF VEH	-213 CM. (-84 IN.)	-127 CM. (-50 IN.)
CG TO SIDE OF VEH	77 CM. (30 IN.)	127 CM. (50 IN.)
MOMENT OF INERTIA	5774 KGS (12729 LBS)	****** KGS (******* LBS)
VEHICLE MASS	3 KGS (6 LBS)	2600 KGS (5732 LBS)

PRESS ANY KEY TO CONTINUE

Printing Picture: CRASH



DAMAGE DESCRIPTION

BES V2

U.S. Department of Transportation
National Highway Traffic Safety Administration

CRASHPC PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

63	042A	01	[redacted] 95
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

Vehicle 1				11
Vehicle 2	1986	CHEVROLET	CAPRICE	2
	Year	Make	Model	NASS Veh. No.

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
Size	11	5
Weight		
	___ (Curb) + ___ (Occupant(s)) + ___ (Cargo) = ____ kg	1627 (Curb) + 158 (Occupant(s)) + — (Cargo) = 1785 kg
CDC	____	11FYEW3
PDOF (-180 to +180)	± ___ °	±025 °
Stiffness	___	5

SCENE INFORMATION

Rest and Impact Positions [X] No, *Go To Damage Information* [ ] Yes

		VEHICLE 1	VEHICLE 2
Rest Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___ °	___ °
Impact Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___ °	___ °
Slip Angle(-180 to +180)		___ °	___ °

VEHICLE MOTION

Sustained Contact [ ] No [ ] Yes

		VEHICLE 1	VEHICLE 2
Vehicle Rotation		[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest		[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
	PSI	___ °	___ °
Curved Path		[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X	____.___ m	____.___ m
	Y	____.___ m	____.___ m
Rotation Direction		[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°		[ ] No [ ] Yes	[ ] No [ ] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . ___ ___ ___

Rolling Resistance Option ___

Vehicle 1 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

Vehicle 2 Rolling Resistance

LF ___ . ___ ___ RF ___ . ___ ___

LR ___ . ___ ___ RR ___ . ___ ___

TRAJECTORY INFORMATION

Trajectory Data [ ] No [ ] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Vehicle 2 Steer Angles

LF ___ ___ ___ ° RF ___ ___ ___ °

LR ___ ___ ___ ° RR ___ ___ ___ °

Terrain Boundary [ ] No [ ] Yes

First Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Second Point

X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m

Secondary Coefficient of Friction . ___ ___ ___

DAMAGE INFORMATION

	VEHICLE 1		VEHICLE 2	
Damage Length	L	___ ___ ___ cm	L	176 cm
Crush Depths	C_1	___ ___ ___ cm	C_1	067 cm
	C_2	___ ___ ___ cm	C_2	065 cm
	C_3	___ ___ ___ cm	C_3	059 cm
	C_4	___ ___ ___ cm	C_4	044 cm
	C_5	___ ___ ___ cm	C_5	024 cm
	C_6	___ ___ ___ cm	C_6	009 cm
Damage Offset	D $\pm$	___ ___ ___ cm	D	⊖033 cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :
HMMM

: INPUT CALCULATE TRAJECTORY OUTPUT GRAPHICS EXIT :

DIMENSIONS AND INERTIAL PROPERTIES

	VEHICLE #1	VEHICLE #2
CG TO FRONT AXLE	127 CM. (50 IN.)	142 CM. (56 IN.)
CG TO REAR AXLE	127 CM. (50 IN.)	160 CM. (63 IN.)
TRACK	127 CM. (50 IN.)	162 CM. (64 IN.)
CG TO FRONT OF VEH	127 CM. (50 IN.)	259 CM. (102 IN.)
CG TO REAR OF VEH	-127 CM. (-50 IN.)	-310 CM. (-122 IN.)
CG TO SIDE OF VEH	127 CM. (50 IN.)	101 CM. (40 IN.)
MOMENT OF INERTIA	****** KGS (******* LBS)	18750 KGS (41337 LBS)
VEHICLE MASS	2600 KGS (5732 LBS)	5 KGS (10 LBS)

PRESS ANY KEY TO CONTINUE

Printing Picture:



```
03042A00000011[redacted]958.020000000000020545000000[redacted]95[redacted]95[redacted]95[redacted]95002546000
00398000001013305  0703
03042A00010012[redacted]958.021000000000101R0205F
03042A00020012[redacted]958.021000000000205T3100N
03042A00030012[redacted]958.021000000000101U63000
03042A00040012[redacted]958.021000000000101L52000
03042A01000021       8.02 000000000895203503JA3CU54Z7KU[redacted]019990560960007303120
07112140129901669999987
03042A01000022       8.02 000000000101011001030000000000000003592900000104 6-033-03
303039099810300 3
03042A01000031       8.02 000000000010202RYEW03045210LYEW023420130300250000000000+
13823200001200400100000 0-049998222246143110003010101010010 00
03042A01000041       8.02 000000000983300100000122222001222210099666100991111 00
03042A01000042       8.02 000000000130742130642130432131133132733131023
                100999905591990
03042A01010051       8.02 000000000241183077111000000039999011299310000000000 00
000000000003021523100000000000041000620199000097979971
03042A02000021       8.02 000000000862000204 1G1BL6965GX[redacted]1199904809600112309 2
021121401299011799998 6
03042A02000022       8.02 000000000102020001630000407102310029035900001029-026+01
21373998104303
03042A02000031       8.02 000000000010111FYEW03023100TDD0011760670650590440240 09-
033                        1761742951551100010101010101001000
03042A02000041       8.02 000000000983333000000144444041333210136116101911111101
03042A02000042       8.02 000000000111331121331131331131431
                100020525912120
03042A02010051       8.02 000000000361999999111900000949999100000310000000000 00
000000000003061923100000000000038199990000000001029011
03042A02010161       8.02 000000000911509970003 2100
03042A02020051       8.02 000000000251999999223900000930000000000010000000000 00
000000000000031101100000000000038199990000000001029011
03042A02020161       8.02 000000000911509970205 3100
03042A00000066       8.02 000000000ANGLE IMPACT
```

03042A00000171 8.02 000000000 VEHICLE #1 HEADING NORTH BOUND WA
S STRUCK BY VEHICLE #2
03042A00000271 8.02 000000000 HEADING WEST BOUND. DRIVER #1 WAS KILLED AS
A RESULT. VEHICLE #2
03042A00000371 8.02 000000000 OUERTURNED AFTER THIS IMPACT. AFTER THE SECO
ND AND THIRD HARMFUL
03042A00000471 8.02 000000000 EVENT VEHICLE #1 (THE LEFT FRONT WHEEL) HIT
THE R/L. VEHICLE #1
03042A00000571 8.02 000000000 CAME TO FINAL REST BY STRIKING THE RP.

03042A00000181 8.02 0000000001 COMPACT 1989 MITSUBISHI/ RIGHT P
LANE MODERATE NONE
03042A00000281 8.02 000000000 MIRAGE

03042A00000381 8.02 0000000002 LARGEST 1986 CHEVORLET/ FRONTAL
MAJOR NONE
03042A00000481 8.02 000000000 CAPRICE

03042A00000581 8.02 000000000

03042A00000681 8.02 000000000

03042A00000781 8.02 000000000

03042A00000191 8.02 0000000001 DRIVER LF LAP BELT FATAL D
ETAILS UNKNOWN
03042A00000291 8.02 0000000002 DRIVER LF LAP BELT HEAD U
NKNOWN 7
03042A00000391 8.02 0000000002 PASSENGER RR NONE HEAD U
NKNOWN 7
03042A99999999000000000000000000000000000000000200000000000000000010000000000000
0000000000002

BEST AVAILABLE

GENERAL VEHICLE Vehicle: 1

INTRA ERRORS

GG0961 2 If AOPS VEHICLE GV40 equals 1-4, then MODEL YEAR GV04 should
GG0962 equal 90-98.

GENERAL VEHICLE Vehicle: 2

INTRA ERRORS

GG0421 2 If ROLLOVER GV45 equals 01-17 or 98, then BASIS FOR DELTA V GV58
GG0422 should equal 04-10.

INTERIOR VEHICLE Vehicle: 2

INTRA ERRORS

CC0541 2 ********* THIS CASE SHOWS A POSSIBLE HOLED WINDSHIELD. ********
CC0542 ****** CHECK YOUR DATA AND IF CORRECT, NOTIFY YOUR ZONE ******
CC0543 GLAZING WINDSHIELD IV31 equals 3 or 5 or CONTACT WINDSHIELD IV39
CC0544 equals 4 or 6.

BEST AVAILABLE

INTER ERRORS

AG0021 2 If CASE AC02(4) equals A, C, E, G or J, then at least one MODEL
AG0022 YEAR GV04 should equal 91-96.

EH0011 2 If TREATMENT 0A62 equals 1, then 1st DEFORMATION EXTENT EV11
EH0012 should be greater than 03. GV=01 0A=01

PSU03 ERROR SUMMARY SCREEN [redacted]/95
CASE 042A
CURRENT VERSION: 8.02

FORM NAME	NUMBER OF DOLLAR SIGNS	NUMBER OF LEVEL 1 ERRORS	NUMBER OF LEVEL 2 ERRORS	VERSION NUMBER CONSISTENT
Accident	0	0	0	Y
General Vehicle	0	0	2	Y
Vehicle Exterior	0	0	0	Y
Vehicle Interior	0	0	1	Y
Occupant Assessment	0	0	0	Y
Occupant Injury	0	0	0	Y
Total Inter Errors		0	2	
Total Case Errors	0	0	5	

U.S. Department of Transportation
National Highway Traffic Safety Administration

SLIDE INDEX

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 03 Case Number—Stratum 042P

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
1-3	V1	NO	approach to IHE V1
4	V1+V2	SWO	angle view
5-13	V1	NWO	approach to 3 HE V1
14-17	V1	SO	angle view of Pole base.
18-19	V1	SO	Look back
20-22	V2	WO	approach to IHE
23	V2+V1	NWO	angle view
24-25	V2	SO	Look back
26	V2	SEO	Look back of Rollover
27	V1		Vehicle #1
28-33	V1		3HE to (L) Plane done by traffic Pole base.
34-35	V1		(L) & Rear Plane
36-44	V1		IHE, impact to (R) Plane
45-51	V1		V1 interior Front seat area
52-58	V1		V1 interior Rear seat area note intrusion to interior slides # 48, 49, 51, 53
59-71	V2		Vehicle #2 Front damage.
72-79	V2		note rollover damage on Top and Left Plane (#17) deformed (L) side view mirror
80-84	V2		V2 (R) plane, note roof deformation
85-89	V2		due to rollover
90-100	V2		interior front seat area note possible occupant contact.
11			

HS Form 434B (1/95)

BEST AVAILABLE

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
101-107	V2		interior rear seat area note occupant contact roof and protection barrier.

PSU 03-042A (1995) #1

PSU 03-042A (1995) #2



PSU 03-042A (1995) #3

PSU 03-042A (1995) #4

PSU 03-042A (1995) #5

PSU 03-042A (1995) #6

PSU 03-042A (1995) #7

PSU 03-042A (1995) #8

PSU 03-042A (1995) #9

PSU 03-042A (1995) #10

PSU 03-042A (1995) #11

PSU 03-042A (1995) #12

PSU 03-042A (1995) #13

PSU 03-042A (1995) #14

PSU 03-042A (1995) #15

PSU 03-042A (1995) #16

PSU 03-042A (1995) #17

PSU 03-042A (1995) #18

PSU 03-042A (1995) #19

PSU 03-042A (1995) #20

PSU 03-042A (1995) #21

PSU 03-042A (1995) #22

PSU 03-042A (1995) #23

PSU 03-042A (1995) #24

PSU 03-042A (1995) #25

PSU 03-042A (1995) #26

PSU 03-042A (1995) #27
Best Available

PSU 03-042A (1995) #28
Best Available

PSU 03-042A (1995) #29
Best Available

PSU 03-042A (1995) #30
Best Available



PSU 03-042A (1995) #31

PSU 03-042A (1995) #32

PSU 03-042A (1995) #33

PSU 03-042A (1995) #34

PSU 03-042A (1995) #35
Best Available

PSU 03-042A (1995) #36
Best Available

PSU 03-042A (1995) #37



PSU 03-042A (1995) #38

PSU 03-042A (1995) #39
Best Available

PSU 03-042A (1995) #40
Best Available

PSU 03-042A (1995) #41
Best Available

PSU 03-042A (1995) #42
Best Available

PSU 03-042A (1995) #43
Best Available

PSU 03-042A (1995) #44
Best Available

PSU 03-042A (1995) #45

PSU 03-042A (1995) #46

PSU 03-042A (1995) #47

PSU 03-042A (1995) #48

PSU 03-042A (1995) #49

PSU 03-042A (1995) #50

PSU 03-042A (1995) #51

PSU 03-042A (1995) #52

PSU 03-042A (1995) #53

PSU 03-042A (1995) #54

PSU 03-042A (1995) #55

PSU 03-042A (1995) #56

PSU 03-042A (1995) #57

PSU 03-042A (1995) #58

PSU 03-042A (1995) #59
Best Available

PSU 03-042A (1995) #60
Best Available

PSU 03-042A (1995) #61
Best Available

PSU 03-042A (1995) #62

PSU 03-042A (1995) #63
Best Available

PSU 03-042A (1995) #64
Best Available

PSU 03-042A (1995) #65
Best Available

PSU 03-042A (1995) #66
Best Available

PSU 03-042A (1995) #67
Best Available

PSU 03-042A (1995) #68

PSU 03-042A (1995) #69

PSU 03-042A (1995) #70

PSU 03-042A (1995) #71

PSU 03-042A (1995) #72

PSU 03-042A (1995) #73

PSU 03-042A (1995) #74

PSU 03-042A (1995) #75

PSU 03-042A (1995) #76

PSU 03-042A (1995) #77

PSU 03-042A (1995) #78

PSU 03-042A (1995) #79

PSU 03-042A (1995) #80

PSU 03-042A (1995) #81

PSU 03-042A (1995) #82
Best Available

PSU 03-042A (1995) #83

PSU 03-042A (1995) #84

PSU 03-042A (1995) #85

PSU 03-042A (1995) #86

PSU 03-042A (1995) #87

PSU 03-042A (1995) #88

PSU 03-042A (1995) #89
Best Available

PSU 03-042A (1995) #90
Best Available

PSU 03-042A (1995) #91
Best Available

PSU 03-042A (1995) #92
Best Available

PSU 03-042A (1995) #93
Best Available

PSU 03-042A (1995) #94

PSU 03-042A (1995) #95
Best Available

PSU 03-042A (1995) #96

PSU 03-042A (1995) #97

PSU 03-042A (1995) #98

PSU 03-042A (1995) #99

PSU 03-042A (1995) #100

PSU 03-042A (1995) #101

PSU 03-042A (1995) #102

PSU 03-042A (1995) #103

PSU 03-042A (1995) #104
Best Available

PSU 03-042A (1995) #105

PSU 03-042A (1995) #106
Best Available

PSU 03-042A (1995) #107
Best Available