U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***

Get it together!
SAFETY BELTS SAVE LIVES

AUTO SAFETY HOTLINE
(800) 424-9393
Wash. D.C. Area 366-0123

U.S. Department of Transportation
National Highway Traffic Safety Administration

CASE SUMMARY

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU 05 CASE NO. 011A TYPE OF ACCIDENT CAR-Compact Pickup / Obtuse Angle

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

(Provide a summary of the accident sequence as well as any particular event of the accident that is noteworthy. Injury mechanism and vehicle crashworthiness is the focus, not driver culpability. Do not include any personal identifiers.)

B. VEHICLE PROFILE(S)

Vehicle No.	Class of Vehicle	Year/Make/Model	Most Severe Damage Based on Vehicle Inspection		Component Failure
			Damage Plane	Severity Description	

DO NOT SANITIZE THIS FORM

HS Form 434A (1/96)

C. PERSON PROFILE(S)

Vehicle No.	Person Role	Seat Position	Restraint Use	Most Severe Injury (TO BE COMPLETED BY ZONE CENTER)			
				Body Region	Injury Type	AIS	Injury Source

Body Region

Abdomen
Ankle—foot
Arm (upper)
Back-thoracolumbar spine
Brain
Chest
Ears
Eye
Elbow
Face
Forearm
Head—skull
Heart
Kidneys
Knee
Leg (lower)
Liver
Lower limbs(s) (whole or unknown part)
Mouth
Neck—cervical spine
Nose
Pelvic—hip
Pulmonary—lungs
Shoulder
Spleen
Thigh
Thyroid, other endocrine gland
Upper limb(s) (whole or unknown part)
Vertebrae
Whole body
Wrist—hand

Injury Type

Abrasion
Amputation
Avulsion
Burn
Concussion
Contusion
Crush
Detachment, separation
Dislocation
Fracture
Fracture and dislocation
Laceration
Other
Perforation, puncture
Rupture
Sprain
Strain
Total severance, transection
Unknown

Abbreviated Injury Scale

(1) Minor injury
(2) Moderate injury
(3) Serious injury
(4) Severe injury
(5) Critical injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

DO NOT SANITIZE THIS FORM

PSU05
CASE 011A
TYPE OF ACCIDENT: CAR-COMPACT PICKUP/OBTUSEANGLE

1996 Case Summary Form

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

V1 WAS TRAVELING NORTHBOUND AND V2 WAS TRAVELING EASTBOUND. AS V1 TRAVELED INTO THE INTERSECTION IT WAS IMPACTED ON THE LEFT SIDE BY THE FRONT OF V2. AFTER IMPACT, V2 ROLLED OVER ONTO ITS RIGHT SIDE WHERE IT CAME TO FINAL REST. V1 ROTATED COUNTER CLOCKWISE AND TRAVELED OFF THE ROAD WHERE IT IMPACTED A SIGN POST AND CAME TO FINAL REST AFTER IT IMPACTED ITS RIGHT SIDE WHEELS WITH A CULVERT. THE DRIVER AND THE DRIVERS SIDE REAR PASSENGER OF V1 WERE FATALLY INJURIED. THE PASSENGER SIDE REAR PASSENGER WAS TRANSPORTED TO A LOCAL HOSPITAL AND RELEASED. THE DRIVER OF V2 WAS ALSO TRANSPORTED AND RELEASED.

PSU05
CASE 011A
TYPE OF ACCIDENT: CAR-COMPACT PICKUP/OBTUSEANGLE

1996 Case Summary Form

B. VEHICLE PROFILE(S)

Veh. No	Class of Vehicle	Year/Make/Model	Most Severe Damage Based on Vehicle Inspection: Damage Plane	Severity Descr.	Component Failure
01	FULL SIZE	1993/PONTIAC/BONNEVILLE	LEFT	SEVERE	NONE
02	COMPACT PICKUP	1988/FORD/RANGER 4X4	FRONT	MODERATE	NONE

PSU05.
CASE 011A
TYPE OF ACCIDENT: CAR-COMPACT PICKUP/OBTUSEANGLE

1996 Case Summary Form

C. PERSON PROFILE(S)

Veh. No	Person Role	Seat Positon	Restraint Use	Most Severe Injury (TO BE COMPLETED BY ZONE CENTER) Body Region	Injury Type	AIS	Injury Source
01	DRIVER	FRONT LEFT	MAN-LAP/SHLDR AIR BAG	brain	hemorrhage	5	hood of other veh.
01	PASSENGER	2ND LEFT	MAN-LAP/SHLDR	BRAIN	HEMORRHAGE	5	(L) SIDE
01	PASSENGER	2ND RIGHT	MAN-LAP/SHLDR	BRAIN	CONCUSSIVE	2	SEATBACK
02	DRIVER	FRONT LEFT	MAN-LAP/SHLDR	NOSE	CONTUSION	1	STEERING

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 05 Case Number—Stratum 011A

Indicate North



HS Form 431B (1/96)

Scale: 1 centimeter = 2.5 meters

U.S. Department of Transportation
National Highway Traffic Safety Administration

BEST AVAILABLE

ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

PSU No. 05 Case Number—Stratum 011A

Indicate North



HS Form 431B (1/96)

Scale: 1 centimeter = 2.5 meters

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT COLLISION MEASUREMENT TABLE

BEST AVAILABLE

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 05

Case Number—Stratum 0 1 1 A

ACCIDENT COLLISION DIAGRAM

Document the physical plant:

- all road/roadway delineation (e.g., curbs/edge lines, lane markings, median markings, pavement markings, parked vehicles, poles, signs, etc.)
- all traffic controls (e.g., signs/signals, etc.)
- north arrow placed on diagram
- roadway surface type and condition of applicable roadways
- grade measurements for all applicable roadways and at location of rollover initiation
- roadway curvature (include measurement of precrash superelevation for each vehicle if applicable)

Document vehicle dynamics including:

- reference point and reference line relative to physical features present at the scene
- scaled documentation of all accident induced physical evidence
- scaled documentation of all roadside objects contacted
- scaled representations of the vehicle(s) at pre-impact, impact, and final rest based upon either:
  - a) physical evidence, or
  - b) reconstructed accident dynamics

CRASH DATA

	VEH. #1	VEH. #2	VEH. #3
Heading Angle	340	80	
Surface Type	BIT	BIT	
Surface Condition	BIT	BIT	
Coefficient of Friction	.75	.75	
Grade (v/h) Measurement (between impact and final rest)	-2/61	-3/61	
Grade (v/h) Measurement (at location of rollover initiation)	—	-5/61	
Grade (v/h) Measurement (at pre-crash location)	-4/61	-5/61	

Reference Point: Utility Pole

Reference line: Westbound Roadside

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line
RP	0/0	15/ N ✓
Sign Impacted	17/ E	19 N ✓
Face Impacted By Sign	33/ E	—
Apex #1	21/ E	—
Apex #2	18/ W	—
Possible [illegible]	75/ 8/ E	37/ S ✓
STOP	123/ W	10 N ✓
STOP	78/ E	16/ S ✓
[illegible] Curve	7/ W	—
[illegible]	70/ E	3/ N ✓
Gouge #2	21/ W	19/ S ✓

HS Form 431A (1/96)

Item	Distance and Direction from Reference Point	Distance and Direction from Reference Line
45		
24 30		
16		
15		
Beg of		
Curve		

U.S. Department of Transportation
National Highway Traffic Safety Administration

ACCIDENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 01 A

IDENTIFICATION

3. Number of General Vehicle Forms Submitted 02
4. Date of Accident (Month,Day,Year) [redacted] 9 6
5. Time of Accident 0730

Code reported military time of accident.

NOTE: Midnight = 2400
Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. ___ SS15 Administrative Use 0
7. ___ SS16 Pedestrian Crash Data Study 0
(Data for this special study available in a separate file.)
8. ___ SS17 Impact Fires 0
9. ___ SS18 Unsafe Driver Actions 0
10. ___ SS19 Run Off Road 0

NUMBER OF EVENTS

11. Number of Recorded Events in This Accident ~~05~~ 06

Code the number of events which occurred in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columnns.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. 01	13. 01	14. 04	15. L	16. 02	17. 30	18. F
	01	04	R	50	00	0
19. 02	20. 02	21. 30	22. R	23. 31	24. 00	25. N
	01	04	R	60	00	0
26. 03	27. 01	28. 04	29. R	30. 50	31. 00	32. 0
	01	04	R	60	00	0
33. 04	34. 01	35. 04	36. R	37. 60	38. 00	39. 0
	01	04	R	57	00	0
40. 05	41. 01	42. 04	43. R	44. 60	45. 00	46. 0
	02	30	R	31	00	N

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

HS Form 434 (Rev. 1/96)

CODES FOR CLASS OF VEHICLE

(00) Not a motor vehicle
(01) Subcompact/mini (wheelbase < 254 cm)
(02) Compact (wheelbase ≥ 254 but < 265 cm)
(03) Intermediate (wheelbase ≥ 265 but < 278 cm)
(04) Full size (wheelbase ≥ 278 but < 291 cm)
(05) Largest (wheelbase ≥ 291 cm)
(09) Unknown passenger car size
(14) Compact utility vehicle
(15) Large utility vehicle (≤ 4,536 kgs GVWR)
(16) Utility station wagon (≤ 4,536 kgs GVWR)
(19) Unknown utility type
(20) Minivan (≤ 4,536 kgs GVWR)
(21) Large van (≤ 4,536 kgs GVWR)
(24) Van Based school bus (≤ 4,536 kgs GVWR)
(28) Other van type (≤ 4,536 kgs GVWR)
(29) Unknown van type (≤ 4,536 kgs GVWR)
(30) Compact pickup truck (≤ 4,536 kgs GVWR)
(31) Large pickup truck (≤ 4,536 kgs GVWR)
(38) Other pickup truck (≤ 4,536 kgs GVWR)
(39) Unknown pickup truck type (≤ 4,536 kgs GVWR
(45) Other light truck (≤ 4,536 kgs GVWR)
(48) Unknown light truck type (≤ 4,536 kgs GVWR)
(49) Unknown light vehicle type
(50) School bus (excludes van based)(>4,536 kgs GVWR)
(58) Other bus (> 4,536 kgs GVWR)
(59) Unknown bus type
(60) Truck (> 4,536 kgs GVWR)
(67) Tractor without trailer
(68) Tractor-trailer(s)
(78) Unknown medium/heavy truck type
(79) Unknown light/medium/heavy truck type
(80) Motored cycle
(90) Other vehicle
(99) Unknown

CODES FOR GENERAL AREA OF DAMAGE (GAD)

CDS APPLICABLE AND OTHER VEHICLES	(0) Not a motor vehicle (N) Noncollision (F) Front	(R) Right side (L) Left side (B) Back	(T) Top (U) Undercarriage (9) Unknown
TDC APPLICABLE VEHICLES	(0) Not a motor vehicle (N) Noncollision (F) Front (R) Right side	(L) Left side (B) Back of unit with cargo area (rear of trailer or straight truck) (D) Back (rear of tractor)	(C) Rear of cab (V) Front of cargo area (T) Top (U) Undercarriage (9) Unknown

CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
(31) Overturn — rollover (excludes end-over-end)
(32) Rollover — end-over-end
(33) Fire or explosion
(34) Jackknife
(35) Other intraunit damage (specify): _____
(36) Noncollision injury
(38) Other noncollision (specify): _____
(39) Noncollision — details unknown

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment
(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify): _____
(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify): _____
(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(72) Pedestrian
(73) Cyclist or cycle
(74) Other nonmotorist or conveyance _____
(75) Vehicle occupant
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify): _____
(89) Unknown nonfixed object

(98) Other event (specify): _____
(99) Unknown event or object

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction 2
(0) Non-interchange area and non-junction
(1) Interchange area related

Non-Interchange junctions
(2) Intersection related
(3) Driveway, alley access related
(4) Other junction (specify)
_____
(5) Unknown type of junction

(9) Unknown

20. Trafficway Flow 0
(0) Not physically divided (two way traffic)
(1) Divided trafficway-median strip without positive barrier
(2) Divided trafficway-median strip with positive barrier
(3) One way traffic
(9) Unknown

21. Number Of Travel Lanes 2
(1) One
(2) Two
(3) Three
(4) Four
(5) Five
(6) Six
(7) Seven or more
(9) Unknown

22. Roadway Alignment 1
(1) Straight
(2) Curve right
(3) Curve left
(9) Unknown

23. Roadway Profile 4 -2/61 = 3%
(1) Level
(2) Uphill grade (>2%)
(3) Hill crest
(4) Downhill grade (>2%)
(5) Sag
(9) Unknown

24. Roadway Surface Type 2
(1) Concrete
(2) Bituminous (asphalt)
(3) Brick or block
(4) Slag, gravel, or stone
(5) Dirt
(8) Other (specify): _____
(9) Unknown

25. Roadway Surface Condition 2
(1) Dry
(2) Wet
(3) Snow or slush
(4) Ice
(5) Sand, dirt, or oil
(8) Other (specify): _____
(9) Unknown

26. Light Conditions 1
(1) Daylight
(2) Dark
(3) Dark, but lighted
(4) Dawn
(5) Dusk
(9) Unknown

27. Atmospheric Conditions 0
(0) No adverse atmospheric-related driving conditions
(1) Rain
(2) Sleet/hail
(3) Snow
(4) Fog
(5) Rain and fog
(6) Sleet and fog
(7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify):
_____
(9) Unknown

28. Traffic Control Device 2
(0) No traffic control(s)
(1) Traffic control signal (not RR crossing)

Regulatory
(2) Stop sign
(3) Yield sign
(4) School zone sign
(5) Other regulatory sign (specify):
_____
(6) Warning sign (not RR crossing)
(7) Unknown sign
(8) Miscellaneous/other controls including RR controls (specify):
_____
(9) Unknown

29. Traffic Control Device Functioning 2
(0) No traffic control device
(1) Traffic control device not functioning (specify):
_____
(2) Traffic control device functioning properly
(9) Unknown

PSU 05-011A(1996)

OCCUPANT RELATED

37. Driver Presence in Vehicle 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle 03
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted 03

AIR BAG RELATED

40. Is this an AOPS Vehicle? 1
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal 2
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight 1,530
1525 Code weight to nearest 10 kilograms.
(045) Less than 454 kilograms
(612) 6,124 kilograms or more
(999) Unknown
3,362 lbs X .4536 = 1,525.0 kgs
Source: [redacted]

44. Vehicle Cargo Weight 0000
____ Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(454) 4,536 kilograms or more
(999) Unknown
__,___ lbs X .4536 = __,___ kgs
Source: Inspection

ROLLOVER DATA

45. Rollover 00
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type 00
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify): _____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted 00
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____
(6) Non-contact rollover forces (specify): _____
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

PSU 05-011A (1996)
V 01

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

(89) Unknown nonfixed object

(98) Other event (specify):

(99) Unknown event or object

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number: 05
2. Case Number - Stratum: 011A
3. Vehicle Number: 01

VEHICLE IDENTIFICATION

VIN 1G2HX53L1P1[redacted] Model Year 93

Vehicle Make (specify): Pontiac Vehicle Model (specify): Bonneville SE

LOCATOR

Locate the end of the damage with respect to the vehicle's damaged center point or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	Begins 48" Forward of (L) Rear Axle	SAME	C4
~~1~~ 2	Begins 125 Forward of (R) Rear Axle	SAME	C2

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush. 394

Taken to Fender not main body (Deflection)

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
1	(L) Mid side	226	84	197	0	56	72	84	26	0	+12
	FREESPACE										
X	RESULTANT	226	84	197	0	56	72	84	26	0	+12
~~1~~ 2	(R) Lower	20	12	54	6	12	10	9	10	9	-5
	Freespace		-4		-4	-4	-4	-4	-4	-4	
~~1~~ 2	* RESULTANT	20	8	54	2	8	6	5	6	5	-5

HS Form 435A (Rev. 1/96)

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Overall Length	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Maximum Width	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Curb Weight	___ ___,___ ___ ___	pounds	x	.4536	=	___,___ ___ ___ kg
Average Track	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Front Overhang	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Rear Overhang	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Undeformed End Width	___ ___ ___.___	inches	x	2.54	=	___ ___ ___cm
Engine Size: cyl./displ.	___ ___ ___ ___	cc	x	.001	=	___.___ L
	___ ___ ___	CID	x	.0164	=	___.___ L

BEST AVAILABLE

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

a. Rotation physically restricted		b. Tire deflated	
RF	2	RF	2
LF	2	LF	2
RR	1	RR	1
LR	9	LR	1

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION
☐ Manual ☒ Automatic

END SHIFT ≥ 10 CM
☐ Yes ☒ No

ORIGINAL SPECIFICATIONS

Wheelbase 110.8	281	cm
Overall Length 199.5	507	cm
Maximum Width 73.6	187 (93)	cm
Curb Weight 336.2	1525	kg
Average Track 60.35	153	cm
Front Overhang	—	cm
Rear Overhang	—	cm
Undeformed End Width	—	cm
Engine Size: cyl./displ.	3.8	L

WHEEL STEER ANGLES
(For locked front wheels or displaced rear axles only)

RF	± NA	°
LF	±	°
RR	±	°
LR	± 0 05	°

Within ± 5 degrees

DRIVE WHEELS
☒ FWD ☐ RWD ☐ 4WD

Approximate Cargo Weight 00 kg

* ABS 4 wheel

MEASUREMENTS IN CENTIMETERS



Windshield hold NOT by EMS since contact on A pillar

NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

located within same corresponding area.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	02	-70	--	L	Y	A	W	05
02	50	+90		R	P	E	N	01
03	60	+90	--	R	F	W	N	01
04	60	+90		R	B	W	N	01
05	57	090		R	B	E	E	?

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 02	6. 10	7. L	8. Y	9. A	10. W	11. 05

Second Highest Delta "V"

12. 03	13. ~~50~~ 60	14. 03	15. R	16. P	17. E	18. N	19. 01

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
197	000	056	072	084	026	000	+012

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
054	002	008	006	005	006	005	+005

26. Undeformed End Width (Coded when highest severity impact is an end plane impact.) 998
____ Code to the nearest centimeter
(250) 250 centimeters or more
(998) No highest severity end plane impact
(999) Unknown

27. Direct Damage Width (For highest severity impact) 226
____ Code to the nearest centimeter
(250) 250 centimeters or more
(999) Unknown

28. Original Wheelbase 281
____ Code to the nearest centimeter
(650) 650 centimeters or more
(999) Unknown
110.8 inches X 2.54 = 281.4 centimeters

29. Original Average Track Width 153
____ Code to the nearest centimeter
(185) 185 centimeters or more
(999) Unknown
60.35 inches X 2.54 = 153.25 centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 1
(0) No
(1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
(0) No post manufacturer modifications
(1) Yes - post manufacturer modifications (specify): _____
(Include photograph of CERTIFICATION PLACARD in case report)
(9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
(0) No fire

Yes, fire occurred
(1) Minor
(2) Major
(9) Unknown

34. Origin of Fire 0
(0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify): _____
(9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 2

36. Location of Fuel Tank-2 Filler Cap 0
(0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on left side plane
(3) Aft of center of the rear wheels (rear axle) on right side plane
(4) Forward of center of the rear wheels (rear axle) on left side plane
(5) Forward of center of the rear wheels (rear axle) on right side plane
(6) Over the center of the rear wheels (rear axle) on left side plane
(7) Over the center of the rear wheels (rear axle) on right side plane
(8) Other (specify): _____
(9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
(0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1 4

40. Location of Fuel Tank-2 0
(0) No fuel tank
(1) Aft of center of the rear wheels (rear axle) centered
(2) Aft of center of the rear wheels (rear axle) left side
(3) Aft of center of the rear wheels (rear axle) right side
(4) Forward of center of the rear wheels (rear axle) centered
(5) Forward of center of the rear wheels (rear axle) left side
(6) Forward of center of the rear wheels (rear axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

41. Damage to Fuel Tank-1 2

42. Damage to Fuel Tank-2 0
(0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): _____
(9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

_____
_____
_____
_____
_____
_____
_____
_____
_____
_____
_____

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 0111 A
3. Vehicle Number 01

INTEGRITY

4. Passenger Compartment Integrity 11
(00) No integrity loss

98

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify): 01, +11
(99) Unknown

NASS CODING CHANGE
1st Review: LF
2nd Review:

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 1 7. LR 3 8. RR 1 9. TG/H 0

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 2
20. BL 2 21. Roof 0 22. Other 2

(0) No glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted (original)
(4) AS-2 — Tempered-with after market tint
(5) AS-3 — Tempered-tinted (with additional after market tint)
(6) AS-14 — Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify):
(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR 2 27. RR 2
28. BL 1 29. Roof 0 30. Other 1

(0) No glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown

Glazing Damage from Impact Forces

31. WS 23 32. LF 6 33. RF 1 34. LR 6 35. RR 1
36. BL 6 37. Roof 0 38. Other 6

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 9 40. LF 1 41. RF 1 42. LR 1 43. RR 1
44. BL 1 45. Roof 0 46. Other 1

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

NOTE: SKETCH INTRUDED AREAS

Row Width (cm)

160





LOCATION OF INTRUSION	INTRUDED COMPONENT	COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION
		(All Measurements Are In Centimeters)					
11	Door Panel	76	–	11	=	~~53~~ ~~65~~ ✓	LAT
11	A Pillar	65	–	46	=	19 ✓	
11	B Pillar	71	–	21	=	50 ✓	
11	SideRail	65	–	24	=	41 ✓	
11	Sill Lower	70	–	47	=	23 ✓	
11	Forward of A Pillar	65	–	61	=	4 ✓	
21	Door Panel	76	–	15	=	53 ~~61~~ ✓	
21	SideRail	65	–	34	=	31 ✓	
21	Sill	70	–	~~52~~	=	18 ✓	
21	C Pillar	67	–	61	=	2	LAT
~~0~~-12	Seat	71	–	51 to B-Pillar	=	20. ✓	LAT
2-2	Door panel		–		=	8	Lat
1-2	Door panel		–		=	65-53=12	Lat
			–		=		
			–		=		

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 11	48. 11	49. 6	50. 3
2nd	51. 21	52. 11	53. 6	54. 3
3rd	55. 11	56. 07	57. 5	58. 3
4th	59. 11	60. 14	61. 4	62. 3
5th	63. 21	64. 14	65. 4	66. 3
6th	67. 11	68. 18	69. 3	70. 3
7th	71. 12	72. 25	73. 3	74. 3
8th	75. 11	76. 06	77. 3	78. 3
9th	79. 21	80. 18	81. 3	82. 3
10th	83. ~~11~~ 1-2	84. ~~10~~ 11	85. ~~1~~ 2	86. ~~3~~ 3

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

Note: Appears drivers head came out window during impact striking V2

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION
- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION
- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

BEST AVAILABLE

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	—	DAMAGE VALUE	=	DEFORMATION
	—		=	7
	—		=	
	—		=	
	—		=	

STEERING COLUMN

87. Steering Column Type 2
(1) Fixed column
(2) Tilt column
(3) Telescoping column
(4) Tilt and telescoping column
(8) Other column type (specify): _____
(9) Unknown

88. Tilt Steering Column Adjustment 2
(0) No tilt steering column
(1) Full up
(2) Between full up and center
(3) Center
(4) Between center and full down
(5) Full down
(9) Unknown

89. Telescoping Steering Column Adjustment 0
(0) No telescoping steering column
(1) Full back
(2) Between full back and midpoint
(3) Midpoint
(4) Between midpoint and full forward
(5) Full forward
(9) Unknown

90. Steering Rim/Spoke Deformation 07
____Code actual measured deformation to the nearest centimeter
(00) No steering rim deformation
(01-14) Actual measured value in centimeters
(15) 15 centimeters or more
(98) Observed deformation cannot be measured
(99) Unknown

91. Location of Steering Rim/Spoke Deformation 08
(00) No steering rim deformation

Quarter Sections
(01) Section A
(02) Section B
(03) Section C
(04) Section D



Half Sections
(05) Upper half of rim/spoke
(06) Lower half of rim/spoke
(07) Left half of rim/spoke
(08) Right half of rim/spoke



(09) Complete steering wheel collapse
(10) Undetermined location
(99) Unknown

INSTRUMENT PANEL

92. Odometer Reading 064,000
64050 kilometers
Code to the nearest 1,000 kilometers
(000) No odometer
(001) Less than 1,500 kilometers
(500) 499,500 kilometers or more
(999) Unknown
39,800 miles X 1.6093 = 64,050.1 kilometers
Source: Inspection

93. Instrument Panel Damage from Occupant Contact? 1
(0) No
(1) Yes
(9) Unknown

94. Type of Knee Bolster Covering 1
(0) No knee bolster
(1) Padded
(2) Rigid plastic
(8) Other (specify): _____
(9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 9
There was a lot of Intrusion
(0) No knee bolster
(1) No deformation
(2) Yes - deformation
(9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 1
(0) No glove compartment door
(1) No - door did not open
(2) Yes - door opened
(9) Unknown

97. Adaptive (Assistive) Driving Equipment 0
(0) No adaptive driving equipment
(1) Adaptive driving equipment installed (Check all that apply.)
[ ] Hand controls for braking/acceleration
[ ] Steering control devices (attached to OEM steering wheel
[ ] Steering knob attached to steering wheel
[ ] Low effort power steering (unit or device)
[ ] Replacement steering wheel (i.e., reduced diameter)
[ ] Joy-stick steering controls
[ ] Wheelchair tie-downs
[ ] Modification to seat belts (specify): _____
[ ] Additional or relocated switches (specify): _____
[ ] Raised roof
[ ] Wall-mounted head rest (used behind wheelchair)
[ ] Other adaptive device (specify): _____
(9) Unknown

BEST AVAILABLE

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	007	1	Knee/Thigh	Column Bent up	2
B	051	1	(L) Torso	Intrusion / Damaged Door Panel	2
C	054	1	(L) Shoulder	Broken Interior	3
D	252	1	(R) Knee	Broken Console	2
E	004	1	(L) Abd.	Bent Rim	2
F	052	2	(L) Torso/Hip	Intrusion / Indentation	2
G	051	2	(L) Torso	Intrusion / Indentation	2
H	151	2	Back	Indented	2
I	Unknown	2	(L) Side/upper	Possible Other vehicle	3
J	151	2	(R) Knee/leg	Indentation / Blood	2
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column,transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment(e.g., tapedeck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object, (specify): _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(175) Air bag compartment cover-driver side
(180) Air bag-passenger side
(185) Air bag compartment cover-passenger side
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
(1) Certain
(2) Probable
(3) Possible
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data **for each seat position** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a child safety seat is present, encode the data on the back of this page 11.

If the vehicle has automatic restraints available, encode the appropriate data on page 6.

		Left	Center	Right
FIRST	A-Availability	4		4
	B-Evidence of usage	04		04
	C-Used in this crash?	04		04
	D-Proper Use	1		1
	E-Failure Modes	1		1
	F-Anchorage Adjustment	9		4
SECOND	A-Availability	4	3	4
	B-Evidence of usage	04	03	04
	C-Used in this crash?	04	00	00
	D-Proper Use	1	0	0
	E-Failure Modes	1	0	0
	F-Anchorage Adjustment	1	0	1
OTHER	A-Availability			
	B-Evidence of usage			
	C-Used in this crash?			
	D-Proper Use			
	E-Failure Modes			
	F-Anchorage Adjustment			

A-Manual (Active) Belt System Availability

(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available - type unknown

Integral Belt Partially Destroyed

(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

B/C-Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperable (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used - type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat - type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

D-Proper Use of Manual (Active) Belts

(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly

(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

E-Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

F-Shoulder Belt Upper Anchorage Adjustment

(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Frontal Air Bags--**Left Front**	Frontal Air Bags-**Right Front**	OtherAir Bag
FIRST	Availability/Function			
	Deployment			
	Failure			

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Air Bag System Deployment
(This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	A-Availability/Function		
	B-Use		
	C-Type		
	D-Proper Use		
	E-Failure Modes		

A-Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

B-Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

C-Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

D-Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

E-Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
A-Type of air bag?	1	
B-Flaps open at tear points?	2	
C-Flaps damaged?	0	
D-Air bag damaged?	01	
E-Source of air bag damage	01	
F-Air bag tethered?	1	
G-Air bag have vent ports?	2	
H-Other occupant contact air bag?	1	
I-Occupant wearing eyewear?	9	

A-Type of Air Bag
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

B-Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

C-Were Air Bag Module Cover Flap(s) Damaged?
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

D-Was There Damage To The Air Bag?
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

E-Source of Air Bag Damage
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify): _____
(03) Object carried by occupant, (specify): _____
(04) Adaptive/assistive controls, (specify): _____
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify): _____
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

F-Was The Air Bag Tethered?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps): _____
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

G-Did The Air Bag Have Vent Ports?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): _____
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

H-Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

I-Was This Occupant Wearing Eye-wear?
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)

AIR BAG WAS Deflected TO The Drivers - (R) Due To Intrusion By Door



50 cm.

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W_U) _____ width (W_L) _____

height (H) _____



4. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap b. Lower Flap

width (W_U) _____ width (W_L) _____

height (H_U) _____ height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W) _____

height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	A-Head Restraint Type/Damage	4		3
	B-Seat Type	01		01
	C-Seat Orientation	1		1
	D-Seat Track Position	4		4
	E-Seat Back Incline Pre/Post Impact	23		23
	F-Seat Performance	6		6
SECOND	A-Head Restraint Type/Damage	1	0	1
	B-Seat Type	03	03	03
	C-Seat Orientation	1	1	1
	D-Seat Track Position	1	1	1
	E-Seat Back Incline Pre/Post Impact	01	01	01
	F-Seat Performance	6/5	6	1
THIRD	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			
OTHER	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

BEST AVAILABLE

HEAD RESTRAINTS/SEAT EVALUATION

A-Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other Specify):_____
(9) Unknown

B-Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
_____
(99) Unknown

C-Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

D-Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

E-Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown

F-Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
_____
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify): B Pillar / Door Panel
(7) Combination of above (specify):
_____
(8) Other (specify):
_____
(9) Unknown







Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

Deformed By Driver Seat

BACK SEAT – Deformed By Door Panel

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat
   - (0) No child safety seat
   - (1) Infant seat
   - (2) Toddler seat
   - (3) Convertible seat
   - (4) Booster seat
   - (7) Other type child safety seat (specify): _____
   - (8) Unknown child safety seat type
   - (9) Unknown if child safety seat used

2. Child Safety Seat Orientation
   - (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   - (01) Rear facing
   - (02) Forward facing
   - (08) Other orientation (specify): _____
   - (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   - (11) Rear facing
   - (12) Forward facing
   - (18) Other orientation (specify): _____
   - (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   - (21) Rear facing
   - (22) Forward facing
   - (28) Other orientation (specify): _____
   - (29) Unknown orientation

   - (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.
   - (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   - (01) After market harness/shield/tether added, not used
   - (02) After market harness/shield/tether used
   - (03) Child safety seat used, but no after market harness/shield/tether added
   - (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   - (11) Harness/shield/tether not used
   - (12) Harness/shield/tether used
   - (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   - (21) Harness/shield/tether not used
   - (22) Harness/shield/tether used
   - (29) Unknown if harness/shield/tether used

   - (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [ ] Yes [X]

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number	1					
Ejection	2					
(Note on Vehicle Interior Sketch) Ejection Area	2					
Ejection Medium	4					
Medium Status	2					

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): LF WINDOW
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [ ] Yes [X]

Describe entrapment mechanism: (L) Door Driver & Passenger

Component(s): _____

(Note on vehicle interior sketch)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 011A
3. Vehicle Number 01
4. Occupant Number 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 37
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 2
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height 168
Code actual height to the nearest centimeter.
(999) Unknown

66 inches X 2.54 = 167.6 centimeters

8. Occupant's Weight 064
Code actual weight to the nearest kilogram.
(999) Unknown

140 pounds X .4536 = 63.5 kilograms

9. Occupant's Role 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

BEST AVAILABLE

EJECTION/ENTRAPMENT

12. Ejection 2 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 2 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.) (specify):_____
    (9) Unknown

NASS CODING CHANGE
1st Review: 1F
2nd Review: _____

14. Ejection Medium 4 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify): LF win
    (5) Integral structure
    (8) Other medium (specify): _____
    (9) Unknown

NASS CODING CHANGE
1st Review: 1G
2nd Review: _____

15. Medium Status (Immediately Prior To Impact) 2 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 1
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc. (specify):_____
    (9) Unknown

17. Occupant Mobility 0
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or not oriented to time or place
    (2) Removed from vehicle due to perceived serious injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (8) Removed from vehicle for other reasons (specify): _____
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
    (0) None available
    (1) Belt removed/destroyed
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt available—type unknown

    Integral Belt Partially Destroyed
    (6) Shoulder belt (lap belt destroyed/removed)
    (7) Lap belt (shoulder belt destroyed/removed)
    (8) Other belt (specify): _____
    (9) Unknown

19. Manual (Active) Belt System Use 04
    (00) None used, not available, or belt removed/destroyed
    (01) Inoperative (specify): _____
    (02) Shoulder belt
    (03) Lap belt
    (04) Lap and shoulder belt
    (05) Belt used—type unknown
    (08) Other belt used (specify): _____
    (12) Shoulder belt used with child safety seat
    (13) Lap belt used with child safety seat
    (14) Lap and shoulder belt used with child safety seat
    (15) Belt used with child safety seat—type unknown
    (18) Other belt used with child safety seat (specify): _____
    (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
    (0) None used or not available
    (1) Belt used properly
    (2) Belt used properly with child safety seat

    Belt Used Improperly
    (3) Shoulder belt worn under arm
    (4) Shoulder belt worn behind back or seat
    (5) Belt worn around more than one person
    (6) Lap belt worn on abdomen
    (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of manual belt system (specify): _____
    (9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
    (0) No manual belt used or not available
    (1) No manual belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify): _____
    (8) Other manual belt failure (specify): _____
    (9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 5
    (0) No manual shoulder belt
    (1) No upper anchorage adjustment for manual shoulder belt

    Adjustable shoulder Belt Upper Anchorage
    (2) In full up position
    (3) In mid position
    (4) In full down position
    (5) Position unknown
    (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0
    (0) Not equipped/not available
    (1) 2 point automatic belts
    (2) 3 point automatic belts
    (3) Automatic belts - type unknown

    Non-functional
    (4) Automatic belts destroyed or rendered inoperative
    (9) Unknown

24. Automatic (Passive) Belt System Use 0
    (0) Not equipped/not available/destroyed or rendered inoperative
    (1) Automatic belt in use
    (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
    (3) Automatic belt use unknown
    (9) Unknown

25. Automatic (Passive) Belt System Type 0
    (0) Not equipped/not available
    (1) Non-motorized system
    (2) Motorized system
    (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
    (0) Not equipped/not available/not used
    (1) Automatic belt used properly
    (2) Automatic belt used properly with child safety seat

    Automatic Belt Used Improperly
    (3) Automatic shoulder belt worn under arm
    (4) Automatic shoulder belt worn behind back
    (5) Automatic belt worn around more than one person
    (6) Lap portion of automatic belt worn on abdomen
    (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of automatic belt system (specify): _____
    (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
    (0) Not equipped/not available/not in use
    (1) No automatic belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify):
    (8) Other automatic belt failure (specify): _____
    (9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 2
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[✓] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

_____
_____
_____
_____

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 1
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present:
    _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 1
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 9
    (0) Not equipped/not available
    (1) No previous accidents

    Yes
    (2) Previous accident(s) without deployment(s)
    (3) One previous accident with deployment
    (4) More than one previous accident with at least one deployment
    (8) Previous accidents, unknown deployment status
    (9) Unknown

36. Type of Air Bag 9
    (0) Not equipped/not available
    (1) Original manufacturer installed system
    (2) Retrofitted air bag
    (3) Replacement air bag
    (8) Unknown type of air bag
    (9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 9
    (0) Not equipped/not available
    (1) No prior maintenance
    (2) Yes, prior maintenance (specify): _____
    (9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01
    (00) Not equipped/not available
    _____ Code the accident event sequence number that initiated the air bag deployment
    (96) Deployed, unknown event
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

39. CDC For Air Bag Deployment Impact 1
    (0) Not equipped/not available
    (1) Highest delta V
    (2) Second highest delta V
    (3) Other non-coded delta V (specify): _____
    (6) Deployed, unknown event
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact ± 013
    (_000) Not equipped/not available
    Code the value of the delta V for the impact that initiated the air bag deployment
    (_996) Deployment, unknown longitudinal Delta V
    (_997) Not deployed
    (_998) Unknown if deployed
    (_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2
    (0) Not equipped/not available
    (1) No
    (2) Yes
    (3) Deployed, unknown if flap(s) opened at designated tear points
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 1
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (3) Deployed, unknown if air bag module cover flap(s) damaged
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

43. Was There Damage To The Air Bag? 01
    (00) Not equipped/not available
    (01) Not damaged

    Yes - Air Bag Damage
    (02) Ruptured
    (03) Cut
    (04) Torn
    (05) Holed
    (06) Burned
    (07) Abraded
    (88) Other damage (specify): _____
    (95) Damaged, details unknown
    (96) Deployed, unknown if damaged
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 01
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify): _____
(03) Object carried by occupant, (specify): _____
(04) Adaptive/assistive controls, (specify): _____
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify): _____
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps): _____
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 2
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): 2
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 4
(0) Not air bag equipped/air bag not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 4
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify): _____
(9) Unknown

50. Seat Type (this Occupant Position) 01
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify): _____
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify): _____
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 4
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 22
    (00) Occupant not seated or no seat
    (01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position



Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position



Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 6
    (0) Occupant not seated or no seat
    (1) No seat performance failure(s)
    (2) Seat adjusters failed
    (3) Seat back folding locks or "seat back" failed (specify): _____
    (4) Seat track/anchors failed
    (5) Deformed by impact of occupant
    (6) Deformed by passenger compartment intrusion, (specify): B Pillar / Door Panel
    (7) Combination of above (specify): _____
    (8) Other (specify): _____
    (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify): _____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify): _____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify): _____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify): _____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify): _____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 4

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 1

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 0

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 00

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 62

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 0 1
_____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 0 1

68. 2nd Medically Reported Cause of Death 0 2

69. 3rd Medically Reported Cause of Death 0 8
_____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____
(97) Other result (includes fatal ruled disease) (specify): _____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 3 2
_____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 0 1
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given (specify units): _____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 0 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	05	3. Vehicle Number	01
2. Case Number - Stratum	011A	4. Occupant Number	01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
brainstem hem											
1st	5. 1	6. 1	7. 4	8. 02	9. 10	10. 5	11. 8	12. 502	13. 2	14. 1	15. 00
subdural hem											
2nd	16. 1	17. 1	18. 4	19. 06	20. 50	21. 4	22. 9	23. 502	24. 2	25. 1	26. 00
(R) subarachnoid hem											
3rd	27. 1	28. 1	29. 4	30. 06	31. 84	32. 3	33. 1	34. 502	35. 2	36. 1	37. 00
(L) subarachnoid hem											
4th	38. 1	39. 1	40. 4	41. 06	42. 84	43. 3	44. 2	45. 502	46. 2	47. 1	48. 00
intraventricular hem											
5th	49. 1	50. 1	51. 4	52. 06	53. 78	54. 4	55. 9	56. 502	57. 2	58. 1	59. 00
(B) intracerebral hem											
6th	60. 1	61. 1	62. 4	63. 06	64. 46	65. 5	66. 3	67. 502	68. 2	69. 1	70. 00
(B) High cort.											
7th	71. 1	72. 8	73. 9	74. 04	75. 02	76. 1	77. 2	78. 004	79. 1	80. 1	81. 00
basilar skull fx											
8th	82. 1	83. 1	84. 5	85. 02	86. 06	87. 4	88. 8	89. 502	90. 2	91. 1	92. 00
loose teeth											
9th	93. 1	94. 2	95. 5	96. 14	97. 02	98. 1	99. 8	100. 502	101. 2	102. 1	103. 02
fx tooth											
10th	104. 1	105. 2	106. 5	107. 14	108. 04	109. 1	110. 8	111. 502	112. 2	113. 1	114. 00

HS Form 433B (1/96)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

BEST AVAILABLE

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th	rib fx 1	4	5	02	42	5	3	051	1	1	01
(B) 12th	lung cont 1	4	4	14	10	4	3	051	1	1	01
13th	bladder loc 1	5	4	06	24	4	8	051	1	1	01
14th	mesentery loc 1	5	4	20	20	2	8	051	1	1	01
15th	spleen loc 1	5	4	42	26	4	2	051	1	1	01
(L) 16th	Kidney loc 1	5	4	16	26	4	2	051	1	1	01
17th	renal artery loc 1	5	2	14	04	3	2	051	1	1	01
18th	pelvis fx 1	8	5	26	04	3	5	051	1	1	01
(L) 19th	head loc 1	1	9	06	02	1	2	054	2	1	03
(L) 20th	head abr 1	1	9	02	02	1	2	054	2	1	03
(L) 21st	head cont 1	1	9	04	02	1	2	054	2	1	03
(L) 22nd	face loc 1	2	9	06	02	1	2	054	2	1	03
(L) 23rd	face abr 1	2	9	02	02	1	2	054	2	1	03
(L) 24th	face cont 1	2	9	04	02	1	2	054	2	1	03
(L) 25th	neck loc 1	3	9	06	02	1	2	602	2	3	00

BEST AVAILABLE

National Accident Sampling System-Crashworthiness Data System: Occupant Injury Form

OCCUPANT INJURY DATA SUPPLEMENT

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
(L) neck other 26	1	3	9	02	02	1	2	602	1	3	00
(L) neck cont 27	1	3	9	04	02	1	2	051	2	1	01
(L) arm cont 28	1	7	9	04	02	1	2	051	1	1	01
(R) wrist radius/ulna 29	1	7	9	06	02	1	3	602	2	3	00
(L) hip + thigh cont 30	1	8	9	04	02	1	2	051	1	1	01
(L) hip + thigh, abrs 31	1	8	9	02	02	1	2	051	1	1	01
(L) thigh other 32	1	8	9	02	02	1	2	004	1	1	00
33											
34											
35											
36											
37											

HS Form 433F (1/96)

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify) _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify): _____
(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify): _____
(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify): _____
(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify): _____
(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify): _____
(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Restrained?

__ No
__ Yes NR

Blood Alcohol Level (mg/dl)

BAL = 0

Glasgow Coma Scale Score

GCSS = DOA

Units of Blood Given

Units = 0

Arterial Blood Gases

pH = __.__
PO_2 = ___
PCO_2 = ___
HCO_3 = ___

DOA

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

ALL INJURIES FROM AUTOPSY



OFFICIAL INJURY DATA — SKELETAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

ALL INJURIES FROM AUTOPSY

TEETH-
LOOSENING OF UPPER + LOWER TEETH WITH 1 FX

MULTIPLE BILATERAL RIB FXS INCLUDING RIBS 1+2 IN POSTERIOR AXILLARY LINE, 4 IN MID-AXILLARY LINE, 5,6,+7 MID-CLAVICULAR LINE

PELVIS
BILATERAL FXS OF SUPERIOR + INFERIOR PUBIC RAMI WITH A WEDGE OF THE SYMPHSIS DISPLACED

FX RIBS 1, 2, 3, 4 + 5 AND 5 + 10 + 12 (L) SIDE POSTERIORLY

MASSIVE BASILAR SKULL FX CREATING A HINGE FX





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

ALL INJURIES FROM AUTOPSY



952 cc = 30%

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 011A
3. Vehicle Number 01
4. Occupant Number 02

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 12
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 2
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height 147 ~~999~~
Code actual height to the nearest centimeter.
(999) Unknown
58 inches X 2.54 = 147.3 centimeters

8. Occupant's Weight 041 ~~999~~
Code actual weight to the nearest kilogram.
(999) Unknown
090 pounds X .4536 = 40.8 kilograms

9. Occupant's Role 2
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 21
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.) (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify): _____
    (5) Integral structure
    (8) Other medium (specify): _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

NASS CODING CHANGE
1st Review: IF
2nd Review: _____

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc. (specify):_____
    (9) Unknown

17. Occupant Mobility 0
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or not oriented to time or place
    (2) Removed from vehicle due to perceived serious injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (8) Removed from vehicle for other reasons (specify): _____
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
    (0) None available
    (1) Belt removed/destroyed
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt available—type unknown

    Integral Belt Partially Destroyed
    (6) Shoulder belt (lap belt destroyed/removed)
    (7) Lap belt (shoulder belt destroyed/removed)
    (8) Other belt (specify): _____
    (9) Unknown

19. Manual (Active) Belt System Use 04
    (00) None used, not available, or belt removed/destroyed
    (01) Inoperative (specify): _____
    (02) Shoulder belt
    (03) Lap belt
    (04) Lap and shoulder belt
    (05) Belt used—type unknown
    (08) Other belt used (specify): _____
    (12) Shoulder belt used with child safety seat
    (13) Lap belt used with child safety seat
    (14) Lap and shoulder belt used with child safety seat
    (15) Belt used with child safety seat—type unknown
    (18) Other belt used with child safety seat (specify): _____
    (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
    (0) None used or not available
    (1) Belt used properly
    (2) Belt used properly with child safety seat

    Belt Used Improperly
    (3) Shoulder belt worn under arm
    (4) Shoulder belt worn behind back or seat
    (5) Belt worn around more than one person
    (6) Lap belt worn on abdomen
    (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of manual belt system (specify): _____
    (9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
    (0) No manual belt used or not available
    (1) No manual belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify): _____
    (8) Other manual belt failure (specify): _____
    (9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 1
    (0) No manual shoulder belt
    (1) No upper anchorage adjustment for manual shoulder belt

    Adjustable shoulder Belt Upper Anchorage
    (2) In full up position
    (3) In mid position
    (4) In full down position
    (5) Position unknown
    (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0
    (0) Not equipped/not available
    (1) 2 point automatic belts
    (2) 3 point automatic belts
    (3) Automatic belts - type unknown

    Non-functional
    (4) Automatic belts destroyed or rendered inoperative
    (9) Unknown

24. Automatic (Passive) Belt System Use 0
    (0) Not equipped/not available/destroyed or rendered inoperative
    (1) Automatic belt in use
    (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
    (3) Automatic belt use unknown
    (9) Unknown

25. Automatic (Passive) Belt System Type 0
    (0) Not equipped/not available
    (1) Non-motorized system
    (2) Motorized system
    (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
    (0) Not equipped/not available/not used
    (1) Automatic belt used properly
    (2) Automatic belt used properly with child safety seat

    Automatic Belt Used Improperly
    (3) Automatic shoulder belt worn under arm
    (4) Automatic shoulder belt worn behind back
    (5) Automatic belt worn around more than one person
    (6) Lap portion of automatic belt worn on abdomen
    (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of automatic belt system (specify): _____
    (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
    (0) Not equipped/not available/not in use
    (1) No automatic belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify):
    (8) Other automatic belt failure (specify): _____
    (9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 0
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[✓] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

_____
_____
_____
_____

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present:
    _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + - 000
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 00
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 00
    (00) Not equipped/not available
    (01) Not damaged
    (02) Object worn by occupant, (specify): _____
    (03) Object carried by occupant, (specify): _____
    (04) Adaptive/assistive controls, (specify): _____
    (05) Fire in vehicle
    (06) Thermal burns
    (07) Rescue or emergency efforts
    (88) Other damage source (specify): _____
    (95) Damaged, unknown source
    (96) Deployed, unknown if damaged
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

45. Was The Air Bag Tethered? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of tether straps): _____
    (3) Deployed, unknown if tethered
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

46. Did The Air Bag Have Vent Ports? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of vent ports): _____
    (3) Deployed, unknown if vent ports present
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (3) Deployed, unknown if other occupant contact to air bag
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
    (0) Not air bag equipped/air bag not available
    (1) No
    (2) Eyeglasses/sunglasses
    (3) Contact lenses
    (4) Deployed, unknown if eyewear worn
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
    (0) No head restraints
    (1) Integral—no damage
    (2) Integral—damaged during accident
    (3) Adjustable—no damage
    (4) Adjustable—damaged during accident
    (5) Add-on—no damage
    (6) Add-on—damaged during accident
    (8) Other (specify): _____
    (9) Unknown

50. Seat Type (this Occupant Position) 03
    (00) Occupant not seated or no seat
    (01) Bucket
    (02) Bucket with folding back
    (03) Bench
    (04) Bench with separate back cushions
    (05) Bench with folding back(s)
    (06) Split bench with separate back cushions
    (07) Split bench with folding back(s)
    (08) Pedestal (i.e., column supported)
    (09) Box mounted seat (i.e., van type)
    (10) Other seat type (specify): _____
    (99) Unknown

51. Seat Orientation (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) Forward facing seat
    (2) Rear facing seat
    (3) Side facing seat (inward)
    (4) Side facing seat (outward)
    (8) Other (specify): _____
    (9) Unknown

52. Seat Track Adjusted Position Prior To Impact 1
    (0) Occupant not seated or no seat
    (1) Non-adjustable seat track

    Adjustable Seat Track
    (2) Seat at forward most track position
    (3) Seat between forward most and middle track positions
    (4) Seat at middle track position
    (5) Seat between middle and rear most track positions
    (6) Seat at rear most track position
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 0 1
    (00) Occupant not seated or no seat
    (01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position



Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position



Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 6
    (0) Occupant not seated or no seat
    (1) No seat performance failure(s)
    (2) Seat adjusters failed
    (3) Seat back folding locks or "seat back" failed (specify): _____
    (4) Seat track/anchors failed
    (5) Deformed by impact of occupant
    (6) Deformed by passenger compartment intrusion, (specify): Door Panel
    (7) Combination of above (specify): _____
    (8) Other (specify): _____
    (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 0 0 0
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify): _____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify): _____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 0 0
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify): _____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify): _____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify): _____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 0 0

59. Child Safety Seat Shield Usage 0 0

60. Child Safety Seat Tether Usage 0 0

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 4

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 1

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 0

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 00

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 62

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 0 1
____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 0 1

68. 2nd Medically Reported Cause of Death 0 2

69. 3rd Medically Reported Cause of Death 0 3
____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):
_____
(97) Other result (includes fatal ruled disease) (specify):
_____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 1 9
____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 0 1
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given (specify units):_____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 0 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):_____
(9) Unknown if belt used

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	05	3. Vehicle Number	01
2. Case Number - Stratum	01 1A	4. Occupant Number	02

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
(B) subdural hem											
1st	5. 1	6. 1	7. 4	8. 06	9. 54	10. 5	11. 3	12. 051	13. 2	14. 1	15. 02
intraventricular hem											
2nd	16. 1	17. 1	18. 4	19. 06	20. 78	21. 4	22. 9	23. 051	24. 2	25. 1	26. 02
epidural hem											
3rd	27. 1	28. 1	29. 4	30. 06	31. 30	32. 4	33. 9	34. 051	35. 2	36. 1	37. 02
(B) cerebral cont											
4th	38. 1	39. 1	40. 4	41. 06	42. 24	43. 4	44. 3	45. 051	46. 2	47. 1	48. 02
cerebellar cont											
5th	49. 1	50. 1	51. 4	52. 04	53. 02	54. 3	55. 6	56. 051	57. 2	58. 1	59. 02
(R) subarachnoid hem											
6th	60. 1	61. 1	62. 4	63. 06	64. 84	65. 3	66. 1	67. 051	68. 2	69. 1	70. 02
(L) subarachnoid hem											
7th	71. 1	72. 1	73. 4	74. 06	75. 84	76. 3	77. 2	78. 051	79. 2	80. 1	81. 02
skull base fx											
8th	82. 1	83. 1	84. 5	85. 02	86. 00	87. 3	88. 8	89. 051	90. 2	91. 1	92. 02
atlanto-occipital dislocation											
9th	93. 1	94. 6	95. 5	96. 02	97. 08	98. 2	99. 6	100. 051	101. 2	102. 2	103. 02
nose fx											
10th	104. 1	105. 2	106. 5	107. 10	108. 04	109. 2	110. 4	111. 051	112. 2	113. 1	114. 02

HS Form 433B (1/96)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

BEST AVAILABLE

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
(L) 11th	jaw fx	1	2	5	06	00	1	2	051	2	1	02
12th	alveolar ridge fx	1	2	5	02	10	2	8	051	2	1	02
13th	whole face abr	1	2	9	02	02	1	0	051	2	1	02
14th	whole face lac	1	2	9	06	02	1	0	051	2	1	02
15th	whole face cont	1	2	9	04	02	1	0	051	2	1	02
(R) 16th	chest cont	1	4	9	04	02	1	1	051	1	1	02
(L) 17th	elbow cont	1	7	9	04	02	1	2	051	1	1	02
18th	abdomen cont	1	5	9	04	02	1	2	051	1	1	02
(B) 19th	thigh cont	1	8	9	04	02	1	3	051	1	1	02
20th												
21st												
22nd												
23rd												
24th												
25th												

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____

(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify) _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify): _____
(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify): _____
(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify): _____
(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify): _____
(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify): _____
(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Restrained?

___ No

✓ Yes

Blood Alcohol Level (mg/dl)

BAL = NR

Glasgow Coma Scale Score

GCSS = DOA

Units of Blood Given

Units = DOA

Arterial Blood Gases

pH = ___

PO_2 = ___

PCO_2 = ___

HCO_3 = ___

DOA

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.) ALL INJURIES FROM AUTOPSY



OFFICIAL INJURY DATA — SKELETAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

AUTOPSY

MINIMAL BILATERAL SUBDURAL HEMORRHAGES

DIFFUSE, MILD SUBARACHNOID HEMORRHAGE IN FRONTAL + PARIETAL AREAS

AUTOPSY

FAIRLY EXTENSIVE COUP CONTUSIONS ON THE ORBITAL SURFACE OF BOTH FRONTAL LOBES AND CONTRECOUP CONTUSIONS ON THE INFERIOR SURFACE OF THE TEMPORAL LOBES.

INTRAVENTRICULAR HEMORRHAGE



AUTOPSY

CONTRECOUP CONTUSIONS ON THE INFERIOR SURFACE OF (L) CEREBELLAR HEMISPHERE

EPIDURAL HEMORRHAGE SURROUNDING FORAMEN MAGNUM



Rec'd [redacted]

U.S. Department of Transportation
National Highway Traffic Safety Administration

UPDATE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number — Stratum 011A
3. Vehicle Number 01
4. Occupant Number 02

RECEIVED [redacted]1996

Driver or Occupant Name: [redacted]

Address: _____

Other Information: _____

(Sanitize this section prior to Update submission.)

STATUS OF OCCUPANT INFORMATION

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL08.	Date Official Medical Data Requested	[redacted]	96
OAL09.	Date Official Medical Data Obtained	[redacted]	96
OAL16.	Injury Treatment Status	2	
OAL17.	Injury Information		
	Official		
a.	Autopsy (invasive examination)	B 08	011
b.	Post-ER medical record which includes information about death based on non-invasive examination	B 11	
c.	Admission record/summary or admission/discharge face sheet	B	
d.	Discharge summary	B	
e.	Operative report	B	
f.	Radiographic record(s) (X-ray, CT scan)	B	
g.	History and physical examination and/or consultation records	B	
h.	Emergency room records (includes nurses' notes)	B	
j.	Private physician	B	
	Unofficial		
k.	Lay coroner	B	
l.	EMS record	B	
m.	Interviewee	B	
n.	Other source (specify): _____	B	B
o.	Police report	B	B

		INITIAL SUBMISSION	UPDATED INFORMATION
OAL18.	Medical Facility Code	12	
GV14.	Alcohol Test Results For Driver	96	
GV16.	Other Drug Specimen Test Type For Driver	0	
OA05.	Occupant's Age	12	
OA06.	Occupant's Sex	2	
OA07.	Occupant's Height	999	147
OA08.	Occupant's Weight	999	040
OA61.	Treatment-Mortality	2	
OA62.	Type of Medical Facility (for Initial Treatment)	1	
OA63.	Hospital Stay	00	

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 011A
3. Vehicle Number 01
4. Occupant Number 03

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 11
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height 999
Code actual height to the nearest centimeter.
(999) Unknown

___ ___ inches X 2.54 = ___ ___ ___ centimeters 032

8. Occupant's Weight ~~999~~
Code actual weight to the nearest kilogram.
(999) Unknown

070 pounds X .4536 = 31.75 kilograms

9. Occupant's Role 2
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 23
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 9
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.) (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify): _____
    (5) Integral structure
    (8) Other medium (specify): _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc. (specify):_____
    (9) Unknown

17. Occupant Mobility 4
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or not oriented to time or place
    (2) Removed from vehicle due to perceived serious injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (8) Removed from vehicle for other reasons (specify): _____
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
    (0) None available
    (1) Belt removed/destroyed
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt available—type unknown

    Integral Belt Partially Destroyed
    (6) Shoulder belt (lap belt destroyed/removed)
    (7) Lap belt (shoulder belt destroyed/removed)
    (8) Other belt (specify): _____
    (9) Unknown

19. Manual (Active) Belt System Use 04
    (00) None used, not available, or belt removed/destroyed
    (01) Inoperative (specify): _____
    (02) Shoulder belt
    (03) Lap belt
    (04) Lap and shoulder belt
    (05) Belt used—type unknown
    (08) Other belt used (specify): _____
    (12) Shoulder belt used with child safety seat
    (13) Lap belt used with child safety seat
    (14) Lap and shoulder belt used with child safety seat
    (15) Belt used with child safety seat—type unknown
    (18) Other belt used with child safety seat (specify): _____
    (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 1
    (0) None used or not available
    (1) Belt used properly
    (2) Belt used properly with child safety seat

    Belt Used Improperly
    (3) Shoulder belt worn under arm
    (4) Shoulder belt worn behind back or seat
    (5) Belt worn around more than one person
    (6) Lap belt worn on abdomen
    (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of manual belt system (specify): _____
    (9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 1
    (0) No manual belt used or not available
    (1) No manual belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify): _____
    (8) Other manual belt failure (specify): _____
    (9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 1
    (0) No manual shoulder belt
    (1) No upper anchorage adjustment for manual shoulder belt

    Adjustable shoulder Belt Upper Anchorage
    (2) In full up position
    (3) In mid position
    (4) In full down position
    (5) Position unknown
    (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0
    (0) Not equipped/not available
    (1) 2 point automatic belts
    (2) 3 point automatic belts
    (3) Automatic belts - type unknown

    Non-functional
    (4) Automatic belts destroyed or rendered inoperative
    (9) Unknown

24. Automatic (Passive) Belt System Use 0
    (0) Not equipped/not available/destroyed or rendered inoperative
    (1) Automatic belt in use
    (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
    (3) Automatic belt use unknown
    (9) Unknown

25. Automatic (Passive) Belt System Type 0
    (0) Not equipped/not available
    (1) Non-motorized system
    (2) Motorized system
    (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
    (0) Not equipped/not available/not used
    (1) Automatic belt used properly
    (2) Automatic belt used properly with child safety seat

    Automatic Belt Used Improperly
    (3) Automatic shoulder belt worn under arm
    (4) Automatic shoulder belt worn behind back
    (5) Automatic belt worn around more than one person
    (6) Lap portion of automatic belt worn on abdomen
    (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of automatic belt system (specify): _____
    (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
    (0) Not equipped/not available/not in use
    (1) No automatic belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify):
    (8) Other automatic belt failure (specify): _____
    (9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 0
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[X] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

_____
_____
_____
_____

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag

    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

    Specify type of "other" air bag present:
    _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
(0) Not equipped/not available
(1) No previous accidents

Yes
(2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 0
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
(0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 0 0
(00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 0
(0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 0 0 0
(_000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(_996) Deployment, unknown longitudinal Delta V
(_997) Not deployed
(_998) Unknown if deployed
(_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 0 0
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 00
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify): _____
(03) Object carried by occupant, (specify): _____
(04) Adaptive/assistive controls, (specify): _____
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify): _____
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

45. Was The Air Bag Tethered? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps): _____
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

46. Did The Air Bag Have Vent Ports? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): _____
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
(0) Not air bag equipped/air bag not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
(0) No head restraints
(1) Integral—no damage
(2) Integral—damaged during accident
(3) Adjustable—no damage
(4) Adjustable—damaged during accident
(5) Add-on—no damage
(6) Add-on—damaged during accident
(8) Other (specify): _____
(9) Unknown

50. Seat Type (this Occupant Position) 03
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify): _____
(99) Unknown

51. Seat Orientation (this Occupant Position) 1
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify): _____
(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 1
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 01
    (00) Occupant not seated or no seat
    (01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position



Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact position
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position



Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) No seat performance failure(s)
    (2) Seat adjusters failed
    (3) Seat back folding locks or "seat back" failed (specify):_____
    (4) Seat track/anchors failed
    (5) Deformed by impact of occupant
    (6) Deformed by passenger compartment intrusion, (specify):_____
    (7) Combination of above (specify):_____
    (8) Other (specify): _____
    (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 000
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 00
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 00

59. Child Safety Seat Shield Usage 00

60. Child Safety Seat Tether Usage 00

Note: Options below applicable to Variables 0A58-0A60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 2

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 3

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 01

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 97

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 0 0
____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 +n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 0 0

68. 2nd Medically Reported Cause of Death 0 0

69. 3rd Medically Reported Cause of Death 0 0
____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____
(97) Other result (includes fatal ruled disease) (specify): _____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 0 7
____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 15
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given (specify units): _____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 24
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

BEST AVAILABLE

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	05	3. Vehicle Number	01
2. Case Number - Stratum	011A	4. Occupant Number	03

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
Concussion											
1st	5. 2	6. 1	7. 6	8. 04	9. 10	10. 2	11. 0	12. 151	13. 2	14. 1	15. 00
face lac											
2nd	16. 2	17. 2	18. 9	19. 06	20. 00	21. 1	22. 7	23. 602	24. 2	25. 3	26. 00
face abr											
3rd	27. 2	28. 2	29. 7	30. 02	31. 02	32. 1	33. 7	34. 602	35. 2	36. 3	37. 00
(L) lar rupture											
4th	38. 3	39. 2	40. 4	41. 02	42. 16	43. 1	44. 2	45. 151	46. 3	47. 1	48. 00
(L) lgt cont											
5th	49. 3	50. 2	51. 9	52. 74	53. 02	54. 1	55. 2	56. 151	57. 2	58. 1	59. 00
(R) leg cont											
6th	60. 2	61. 8	62. 9	63. 04	64. 02	65. 1	66. 1	67. 151	68. 1	69. 1	70. 00
(R) leg abr											
7th	71. 3	72. 8	73. 9	74. 02	75. 02	76. 1	77. 1	78. 151	79. 1	80. 1	81. 00
8th	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.
9th	93.	94.	95.	96.	97.	98.	99.	100.	101.	102.	103.
10th	104.	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.

HS Form 433B (1/96)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
12th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
13th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
14th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
15th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
16th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
17th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
18th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
19th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
20th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
21st	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
22nd	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
23rd	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
24th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __
25th	__	__	__	__ __	__ __	__	__	__ __ __	__	__	__ __

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify) _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify): _____
(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify): _____
(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify): _____
(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify): _____
(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify): _____
(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Restrained?

___ No

✓ Yes

Blood Alcohol Level (mg/dl)

BAL = NR

Glasgow Coma Scale Score

GCSS = 15

Units of Blood Given

Units = 0

Arterial Blood Gases

pH = ___

PO_2 = ___

PCO_2 ___

HCO_3 24

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

DS, ER; CONCUSSION; (+) LOC; AMNESTIC TO EVENTS OF ACCIDENT



OFFICIAL INJURY DATA — SKELETAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction 2
    (0) Non-interchange area and non-junction
    (1) Interchange area related

    Non-Interchange junctions
    (2) Intersection related
    (3) Driveway, alley access related
    (4) Other junction (specify) _____
    (5) Unknown type of junction
    (9) Unknown

20. Trafficway Flow 0
    (0) Not physically divided (two way traffic)
    (1) Divided trafficway-median strip without positive barrier
    (2) Divided trafficway-median strip with positive barrier
    (3) One way traffic
    (9) Unknown

21. Number Of Travel Lanes 2
    (1) One
    (2) Two
    (3) Three
    (4) Four
    (5) Five
    (6) Six
    (7) Seven or more
    (9) Unknown

22. Roadway Alignment 1
    (1) Straight
    (2) Curve right
    (3) Curve left
    (9) Unknown

23. Roadway Profile -3/61 -4.9% 4
    (1) Level
    (2) Uphill grade (>2%)
    (3) Hill crest
    (4) Downhill grade (>2%)
    (5) Sag
    (9) Unknown

24. Roadway Surface Type 2
    (1) Concrete
    (2) Bituminous (asphalt)
    (3) Brick or block
    (4) Slag, gravel, or stone
    (5) Dirt
    (8) Other (specify): _____
    (9) Unknown

25. Roadway Surface Condition 2
    (1) Dry
    (2) Wet
    (3) Snow or slush
    (4) Ice
    (5) Sand, dirt, or oil
    (8) Other (specify): _____
    (9) Unknown

26. Light Conditions 1
    (1) Daylight
    (2) Dark
    (3) Dark, but lighted
    (4) Dawn
    (5) Dusk
    (9) Unknown

27. Atmospheric Conditions 0
    (0) No adverse atmospheric-related driving conditions
    (1) Rain
    (2) Sleet/hail
    (3) Snow
    (4) Fog
    (5) Rain and fog
    (6) Sleet and fog
    (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
    (9) Unknown

28. Traffic Control Device 0
    (0) No traffic control(s)
    (1) Traffic control signal (not RR crossing)

    Regulatory
    (2) Stop sign
    (3) Yield sign
    (4) School zone sign
    (5) Other regulatory sign (specify): _____
    (6) Warning sign (not RR crossing)
    (7) Unknown sign
    (8) Miscellaneous/other controls including RR controls (specify): _____
    (9) Unknown

29. Traffic Control Device Functioning 0
    (0) No traffic control device
    (1) Traffic control device not functioning (specify): _____
    (2) Traffic control device functioning properly
    (9) Unknown

PSU 05-011A(1996)

OCCUPANT RELATED

37. Driver Presence in Vehicle 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle 01
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted 01

AIR BAG RELATED

40. Is this an AOPS Vehicle? 0
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal 0
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle
(2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle
(4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight ~~1,52~~ 147 0
Code weight to nearest 10 kilograms.
(045) Less than 454 kilograms
(612) 6,124 kilograms or more
(999) Unknown
3,240 lbs X .4536 = 1,469.6 kgs
Source: MVMA Bus Truck

44. Vehicle Cargo Weight ~~0,14~~ 006 0
136 Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(454) 4,536 kilograms or more
(999) Unknown
136 lbs X .4536 = 61.6 kgs
Source: Est Body shop

NASS CODING CHANGE
1st Review: 1F
2nd Review:

ROLLOVER DATA

45. Rollover 01
(00) No rollover (no overturning)

Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify): _____
(98) Rollover--end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type ~~01~~ 03
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify): _____
(98) Rollover--end-over-end
(99) Unknown rollover initiation type

NASS CODING CHANGE
1st Review: 1F
2nd Review:

47. Location of Rollover Initiation 1
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover--end-over-end
(9) Unknown

31

48. Rollover Initiation Object Contacted ~~01~~
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 6~~7~~
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____
(6) Non-contact rollover forces (specify): turn over
(8) Rollover--end-over-end
(9) Unknown

50. Direction of Initial Roll 1
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover--end-over-end
(9) Unknown roll direction

NASS CODING CHANGE
1st Review: 1F
2nd Review:

PSU05-011A(1996)
V 02

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

(00) No rollover
(01-30) — Vehicle Number

Noncollision
(31) Turn-over — fall-over
(32) No rollover impact initiation (end-over-end)
(34) Jackknife

Collision With Fixed Object
(41) Tree (≤ 10 cm in diameter)
(42) Tree (> 10 cm in diameter)
(43) Shrubbery or bush
(44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
(50) Pole or post (≤ 10 cm in diameter)
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
(52) Pole or post (> 30 cm in diameter)
(53) Pole or post (diameter unknown)

(54) Concrete traffic barrier
(55) Impact attenuator
(56) Other traffic barrier (includes guardrail) (specify):_____

(57) Fence
(58) Wall
(59) Building
(60) Ditch or culvert
(61) Ground
(62) Fire hydrant
(63) Curb
(64) Bridge
(68) Other fixed object (specify):

(69) Unknown fixed object

Collision with Nonfixed Object
(70) Passenger car, light truck, van, or other vehicle not in-transport
(71) Medium/heavy truck or bus not in-transport
(76) Animal
(77) Train
(78) Trailer, disconnected in transport
(79) Object fell from vehicle in-transport
(88) Other nonfixed object (specify):

(89) Unknown nonfixed object

(98) Other event (specify):

(99) Unknown event or object

U.S. Department of Transportation
National Highway Traffic Safety Administration

EXTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 01 1A
3. Vehicle Number 02

VEHICLE IDENTIFICATION

VIN 1FTCR15T9JP [redacted]

Model Year 88

Vehicle Make (specify): FORD

Vehicle Model (specify): RANGER XLT

LOCATOR

Locate the end of the damage with respect to the vehicle's damaged center point or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage Entire Pre	Location of Field L	Location of Max Crush
1	Begins (1) Front Bumper Corner	Entire Front	C1
2	Entire (R) side	Entire (R) side	

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

22

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage Width (CDC)	Direct Damage Max Crush	Field L	C_1	C_2	C_3	C_4	C_5	C_6	±D
1	Front Bumper	120	74	111	74	32	25	17	8	4	00
	Freespace		-5		-5	-1	0	0	-1	-5	
	STAND Adjustment		-11		11	11	11	11	11	11	
1	X Resultant	120	58	111	58	20	14	6	0	0	00
1	(R) side	480	7cm	480							

HS Form 435A (Rev. 1/96)

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	125.0	inches	x	2.54	=	___ cm
Overall Length	192.7	inches	x	2.54	=	___ cm
Maximum Width	___.___	inches	x	2.54	=	___ cm
Curb Weight 3240(2.9V6)	___,___	pounds	x	.4536	=	___,___ kg
Average Track	___.___	inches	x	2.54	=	___ cm
Front Overhang	28.3	inches	x	2.54	=	71.8 cm
Rear Overhang	___.___	inches	x	2.54	=	___ cm
Undeformed End Width	___.___	inches	x	2.54	=	___ cm
Engine Size: cyl./displ.	___	cc	x	.001	=	2.9 L
	___	CID	x	.0164	=	___.___ L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

a. Rotation physically restricted

RF 9
LF 1
RR 9
LR 2

b. Tire deflated

RF 9
LF 1
RR 9
LR 2

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☐ Automatic

END SHIFT ≥ 10 CM

☐ Yes ☐ No

ORIGINAL SPECIFICATIONS

Wheelbase	125" 317.5 318	cm
Overall Length	189.5 189	cm
Maximum Width	170	cm
Curb Weight	1469.6 ~~1515~~ 1470	kg
Average Track	140	cm
Front Overhang	72	cm
Rear Overhang	~~99~~ 100.2	cm
Undeformed End Width	148	cm
Engine Size: cyl./displ.	2.9 V6	L

WHEEL STEER ANGLES
(For locked front wheels or displaced rear axles only)

RF ± NA °
LF ± 20 °
RR ± NA °
LR ± NA °

Within ± 5 degrees

DRIVE WHEELS

☐ FWD ☐ RWD ☒ 4WD

Approximate Cargo Weight CAP 136 kg

* STANDS SET AT 500 From BACK of vehicle *

MEASUREMENTS IN CENTIMETERS



Original Bumper height



Bumper wide 15 11 cm

CAP top Dented



Bumper corner 39 289 99 Bumper corner

Stringline — — Stringline





CAP SLID BACK During Accident

Bumper corner 101 323 69 Bumper corner

Stringline — — Stringline

NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CDC WORKSHEET

CODES FOR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision
- (31) Overturn — rollover (excludes end-over-end)
- (32) Rollover—end-over-end
- (33) Fire or explosion
- (34) Jackknife
- (35) Other intraunit damage (specify): _____
- (36) Noncollision injury
- (38) Other noncollision (specify): _____
- (39) Noncollision — details unknown

Collision With Fixed Object
- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post
- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail) (specify): _____
- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____
- (69) Unknown fixed object

Collision with Nonfixed Object
- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (72) Pedestrian
- (73) Cyclist or cycle
- (74) Other nonmotorist or conveyance _____
- (75) Vehicle occupant
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____
- (89) Unknown nonfixed object
- (98) Other event (specify): _____
- (99) Unknown event or object

DEFORMATION CLASSIFICATION BY EVENT NUMBER

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force (degrees)	Incremental Value of Shift	(3) Deformation Location	(4) Specific Longitudinal or Lateral Location	(5) Specific Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
01	01	140	--	P	D	E	W	03
02	31	000	--	R	D	A	O	02

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. 01	5. 01	6. 01	7. F	8. D	9. E	10. W	11. 03

Second Highest Delta "V"

12. 02	13. 31	14. 00	15. R	16. D	17. A	18. 0	19. 02

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. L	21. C_1	C_2	C_3	C_4	C_5	C_6	22. ±D
148	058	020	014	006	000	000	+ 000

Second Highest Delta "V"

23. L	24. C_1	C_2	C_3	C_4	C_5	C_6	25. ±D
							+

26. Undeformed End Width 148
(Coded when highest severity impact is an end plane impact.)
____ Code to the nearest centimeter
(250) 250 centimeters or more
(998) No highest severity end plane impact
(999) Unknown

27. Direct Damage Width 120
(For highest severity impact)
____ Code to the nearest centimeter
(250) 250 centimeters or more
(999) Unknown

28. Original Wheelbase 318
____ Code to the nearest centimeter
(650) 650 centimeters or more
(999) Unknown
125.__ inches X 2.54 = 317.5 centimeters

29. Original Average Track Width 140
____ Code to the nearest centimeter
(185) 185 centimeters or more
(999) Unknown
___.__ inches X 2.54 = ___ centimeters

30. Are CDCs Documented but Not Coded on The Automated File? 0
    (0) No
    (1) Yes

31. Researcher's Assessment of Vehicle Disposition 1
    (0) Not towed due to vehicle damage
    (1) Towed due to vehicle damage
    (9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0
    (0) No post manufacturer modifications
    (1) Yes - post manufacturer modifications (specify): _____
    _____
    _____
    (Include photograph of CERTIFICATION PLACARD in case report)
    (9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence 0
    (0) No fire

    Yes, fire occurred
    (1) Minor
    (2) Major
    (9) Unknown

34. Origin of Fire 0
    (0) No fire
    (1) Vehicle exterior (front, side, back, top)
    (2) Exhaust system
    (3) Fuel tank (and other fuel retention system parts)
    (4) Engine compartment
    (5) Cargo/trunk compartment
    (6) Instrument panel
    (7) Passenger compartment area
    (8) Other location (specify):
    _____
    (9) Unknown

FUEL SYSTEM

35. Location of Fuel Tank-1 Filler Cap 4

36. Location of Fuel Tank-2 Filler Cap 0
    (0) No fuel tank
    (1) On back plane
    (2) Aft of center of the rear wheels (rear axle) on left side plane
    (3) Aft of center of the rear wheels (rear axle) on right side plane
    (4) Forward of center of the rear wheels (rear axle) on left side plane
    (5) Forward of center of the rear wheels (rear axle) on right side plane
    (6) Over the center of the rear wheels (rear axle) on left side plane
    (7) Over the center of the rear wheels (rear axle) on right side plane
    (8) Other (specify): _____
    (9) Unknown

37. Type of Fuel Tank-1 1

38. Type of Fuel Tank-2 0
    (0) No fuel tank (electrical vehicle)
    (1) Metallic
    (2) Non-metallic
    (9) Unknown

39. Location of Fuel Tank-1 5

40. Location of Fuel Tank-2 0
    (0) No fuel tank
    (1) Aft of center of the rear wheels (rear axle) centered
    (2) Aft of center of the rear wheels (rear axle) left side
    (3) Aft of center of the rear wheels (rear axle) right side
    (4) Forward of center of the rear wheels (rear axle) centered
    (5) Forward of center of the rear wheels (rear axle) left side
    (6) Forward of center of the rear wheels (rear axle) right side
    (7) Over center of the rear wheels (rear axle)
    (8) Other (specify): _____
    (9) Unknown

41. Damage to Fuel Tank-1 1

42. Damage to Fuel Tank-2 0
    (0) No fuel tank
    (1) No damage to fuel tank
    (2) Deformed, no seam failure
    (3) Deformed, with a seam failure
    (4) Punctured
    (5) Lacerated (ripped)
    (6) Abraded (scraped)
    (7) Filler neck separation from the fuel tank
    (8) Other damage (specify): _____
    (9) Unknown

43. Leakage Location of Fuel System-1 1

44. Leakage Location of Fuel System-2 0
(0) No fuel tank
(1) No fuel leakage

Primary Area Of Leakage
(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify):_____
(9) Unknown

45. Fuel Type-1 01

46. Fuel Type-2 00

Single Fuel Type
(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):
_____

Electric Powered or Electric/Solar Powered Vehicles
(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify):_____

(98) Other Hybrid (specify):
_____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks? 0
(0) No (one or two tanks only)

Yes - More Than Two Tanks
(1) Yes -- no damage to any tank or filler cap and no fuel system leakage
(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location):
_____
(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):
Type of tank _____
Tank location _____
Filler cap location _____
Tank damage _____
Location of leakage _____
Type of fuel _____
(9) Unknown if more than two tanks

COMMENTS

_____
_____
_____
_____
_____
_____
_____
_____
_____
_____
_____

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.

U.S. Department of Transportation
National Highway Traffic Safety Administration

INTERIOR VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 0 1 1 A
3. Vehicle Number 02

INTEGRITY

4. Passenger Compartment Integrity 06
(00) No integrity loss

Yes, Integrity Was Lost Through
(01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight) , RF, RR
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify):
(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 1 6. RF 1 7. LR 0 8. RR 0 9. TG/H 0

(0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):
(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision
(1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):
(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 2
20. BL 2 21. Roof 0 22. Other 0

(0) No glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted (original)
(4) AS-2 — Tempered-with after market tint
(5) AS-3 — Tempered-tinted (with additional after market tint)
(6) AS-14 — Glass/Plastic
(7) Glazing removed prior to accident
(8) Other (specify):
(9) Unknown

Window Precrash Glazing Status (down at time of inspection)

23. WS 1 24. LF 2 25. RF 2 26. LR 2 27. RR 2
28. BL 2 29. Roof 0 30. Other 0

(0) No glazing (slider)
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(7) Glazing removed prior to accident
(9) Unknown

Glazing Damage from Impact Forces

31. WS 2 32. LF 1 33. RF 6 34. LR 1 35. RR 6
36. BL 1 37. Roof 0 38. Other 0

(0) No glazing
(1) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 1 40. LF 1 41. RF 1 42. LR 1 43. RR 1
44. BL 1 45. Roof 0 46. Other 0

(0) No glazing
(1) No occupant contact to glazing
(2) Glazing contacted by occupant but no glazing damage
(3) Glazing in place and cracked by occupant contact
(4) Glazing in place and holed by occupant contact
(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact
(6) Glazing out-of-place by occupant contact and holed by occupant contact
(7) Glazing removed prior to accident
(8) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

NOTE: SKETCH INTRUDED AREAS

Row Width (cm)

_____

_____

_____

_____





LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters) COMPARISON VALUE	–	INTRUDED VALUE	=	INTRUSION	DOMINANT CRUSH DIRECTION
11	Floor Pan	—	–	—	=	7	Vert
11	Toe Pan	—		—	=	6	Long
13	(R) Door Panel	—	–	—	=	3	LAT
21	Back Panel	—	–	—	=	3	Long
22	" "	—	–	—	=	5	Long
23	" "	—	–	—	=	2	Lw
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		
			–		=		

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. 11	48. 18	49. 1	50. 1
2nd	51. 11	52. 05	53. 1	54. 2
3rd	55. 22	56. 26	57. 1	58. 2
4th	59. 13	60. 11	61. 1	62. 3
5th	63. 21	64. 26	65. 1	66. 2
6th	67. ___	68. ___	69. ___	70. ___
7th	71. ___	72. ___	73. ___	74. ___
8th	75. ___	76. ___	77. ___	78. ___
9th	79. ___	80. ___	81. ___	82. ___
10th	83. ___	84. ___	85. ___	86. ___

LOCATION OF INTRUSION

Front Seat
- (11) Left
- (12) Middle
- (13) Right

Second Seat
- (21) Left
- (22) Middle
- (23) Right

Third Seat
- (31) Left
- (32) Middle
- (33) Right

Fourth Seat
- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____
- (99) Unknown

INTRUDING COMPONENT

Interior Components
- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components
- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	—	DAMAGE VALUE	=	DEFORMATION
	—		=	
	—		=	
	—		=	
	—		=	

STEERING COLUMN

87. Steering Column Type 1
    (1) Fixed column
    (2) Tilt column
    (3) Telescoping column
    (4) Tilt and telescoping column
    (8) Other column type (specify): _____
    (9) Unknown

88. Tilt Steering Column Adjustment 0
    (0) No tilt steering column
    (1) Full up
    (2) Between full up and center
    (3) Center
    (4) Between center and full down
    (5) Full down
    (9) Unknown

89. Telescoping Steering Column Adjustment 0
    (0) No telescoping steering column
    (1) Full back
    (2) Between full back and midpoint
    (3) Midpoint
    (4) Between midpoint and full forward
    (5) Full forward
    (9) Unknown

90. Steering Rim/Spoke Deformation 00
    ____Code actual measured deformation to the nearest centimeter
    (00) No steering rim deformation
    (01-14) Actual measured value in centimeters
    (15) 15 centimeters or more
    (98) Observed deformation cannot be measured
    (99) Unknown

91. Location of Steering Rim/Spoke Deformation 00
    (00) No steering rim deformation

    Quarter Sections
    (01) Section A
    (02) Section B
    (03) Section C
    (04) Section D



    Half Sections
    (05) Upper half of rim/spoke
    (06) Lower half of rim/spoke
    (07) Left half of rim/spoke
    (08) Right half of rim/spoke



    (09) Complete steering wheel collapse
    (10) Undetermined location
    (99) Unknown

INSTRUMENT PANEL

92. Odometer Reading 091,000
    90890 kilometers
    Code to the nearest 1,000 kilometers
    (000) No odometer
    (001) Less than 1,500 kilometers
    (500) 499,500 kilometers or more
    (999) Unknown
    56,478 miles X 1.6093 = 90,877.2 kilometers
    Source: Inspection

93. Instrument Panel Damage from Occupant Contact? 1
    (0) No
    (1) Yes
    (9) Unknown

94. Type of Knee Bolster Covering 0
    (0) No knee bolster
    (1) Padded
    (2) Rigid plastic
    (8) Other (specify): _____
    (9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 0
    (0) No knee bolster
    (1) No deformation
    (2) Yes - deformation
    (9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 1
    (0) No glove compartment door
    (1) No - door did not open
    (2) Yes - door opened
    (9) Unknown

97. Adaptive (Assistive) Driving Equipment 0
    (0) No adaptive driving equipment
    (1) Adaptive driving equipment installed (Check all that apply.)
        [ ] Hand controls for braking/acceleration
        [ ] Steering control devices (attached to OEM steering wheel
        [ ] Steering knob attached to steering wheel
        [ ] Low effort power steering (unit or device)
        [ ] Replacement steering wheel (i.e., reduced diameter)
        [ ] Joy-stick steering controls
        [ ] Wheelchair tie-downs
        [ ] Modification to seat belts (specify): _____
        [ ] Additional or relocated switches (specify): _____
        [ ] Raised roof
        [ ] Wall-mounted head rest (used behind wheelchair)
        [ ] Other adaptive device (specify): _____
    (9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment









Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure.
Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	010	1	(L) Knee	Indentation	2
B	011	1	(R) Knee	BROKEN	2
C					
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column,transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment(e.g., tapedeck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object, (specify): _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(175) Air bag compartment cover-driver side
(180) Air bag-passenger side
(185) Air bag compartment cover-passenger side
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT
(1) Certain
(2) Probable
(3) Possible
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data **for each seat position** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a child safety seat is present, encode the data on the back of this page 11.

If the vehicle has automatic restraints available, encode the appropriate data on page 6.

		Left	Center	Right
FIRST	A-Availability	4	3	4
	B-Evidence of usage	04	03	04
	C-Used in this crash?	04	00	00
	D-Proper Use	1	0	0
	E-Failure Modes	1	0	0
	F-Anchorage Adjustment	1	0	1
SECOND	A-Availability	3		3
	B-Evidence of usage	00		00
	C-Used in this crash?	00		00
	D-Proper Use	0		0
	E-Failure Modes	0		0
	F-Anchorage Adjustment	0		0
OTHER	A-Availability			
	B-Evidence of usage			
	C-Used in this crash?			
	D-Proper Use			
	E-Failure Modes			
	F-Anchorage Adjustment			

A-Manual (Active) Belt System Availability

(0) None available
(1) Belt removed/destroyed
(2) Shoulder belt
(3) Lap belt
(4) Lap and shoulder belt
(5) Belt available - type unknown

Integral Belt Partially Destroyed

(6) Shoulder belt (lap belt destroyed/removed)
(7) Lap belt (shoulder belt destroyed/removed)
(8) Other belt (specify): _____
(9) Unknown

B/C-Manual (Active) Belt System Use

(00) None used, not available, or belt removed/destroyed
(01) Inoperable (specify): _____
(02) Shoulder belt
(03) Lap belt
(04) Lap and shoulder belt
(05) Belt used - type unknown
(08) Other belt used (specify): _____
(12) Shoulder belt used with child safety seat
(13) Lap belt used with child safety seat
(14) Lap and shoulder belt used with child safety seat
(15) Belt used with child safety seat - type unknown
(18) Other belt used with child safety seat (specify): _____
(99) Unknown if belt used

D-Proper Use of Manual (Active) Belts

(0) None used or not available
(1) Belt used properly
(2) Belt used properly with child safety seat

Belt Used Improperly

(3) Shoulder belt worn under arm
(4) Shoulder belt worn behind back or seat
(5) Belt worn around more than one person
(6) Lap belt worn on abdomen
(7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of manual belt system (specify): _____
(9) Unknown

E-Manual (Active) Belt Failure Modes During Accident

(0) No manual belt used or not available
(1) No manual belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other manual belt failure (specify): _____
(9) Unknown

F-Shoulder Belt Upper Anchorage Adjustment

(0) No shoulder belt
(1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

(2) In full up position
(3) In mid position
(4) In full down position
(5) Position unknown
(9) Unknown if position has adjustable upper anchorage adjustment

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Frontal Air Bags--Left Front	Frontal Air Bags-Right Front	OtherAir Bag
FIRST	Availability/Function	0	0	0
	Deployment	0	0	0
	Failure	0	0	0

Air Bag System Availability/Function
(0) Not equipped/not available
(1) Air bag

Non-functional
(2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Air Bag System Deployment
(This Occupant Position)
(0) Not equipped/not available
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, accident sequence undetermined
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

AUTOMATIC BELTS

		Left	Right
FIRST	A-Availability/Function		
	B-Use		
	C-Type		
	D-Proper Use		
	E-Failure Modes		

A-Automatic (Passive) Belt System Availability/Function
(0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional
(4) Automatic belts destroyed or rendered inoperative
(9) Unknown

B-Automatic (Passive) Belt System Use
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

C-Automatic (Passive) Belt System Type
(0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

D-Proper Use of Automatic (Passive) Belt System
(0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly
(3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

E-Automatic (Passive) Belt Failure Modes During Accident
(0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify):
(8) Other automatic belt failure (specify): _____
(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data ***for the driver and first seat passenger*** in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
A-Type of air bag?		
B-Flaps open at tear points?		
C-Flaps damaged?		
D-Air bag damaged?		
E-Source of air bag damage		
F-Air bag tethered?		
G-Air bag have vent ports?		
H-Other occupant contact air bag?		
I-Occupant wearing eyewear?		

A-Type of Air Bag
(0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

B-Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?
(0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

C-Were Air Bag Module Cover Flap(s) Damaged?
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

D-Was There Damage To The Air Bag?
(00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage
(02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

E-Source of Air Bag Damage
(00) Not equipped/not available
(01) Not damaged
(02) Object worn by occupant, (specify): _____
(03) Object carried by occupant, (specify): _____
(04) Adaptive/assistive controls, (specify): _____
(05) Fire in vehicle
(06) Thermal burns
(07) Rescue or emergency efforts
(88) Other damage source (specify): _____
(95) Damaged, unknown source
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

F-Was The Air Bag Tethered?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of tether straps): _____
(3) Deployed, unknown if tethered
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

G-Did The Air Bag Have Vent Ports?
(0) Not equipped/not available
(1) No
(2) Yes (specify number of vent ports): _____
(3) Deployed, unknown if vent ports present
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

H-Was the Air Bag in this Occupant's Position Contacted by Another Occupant?
(0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if other occupant contact to air bag
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

I-Was This Occupant Wearing Eye-wear?
(0) Not equipped/not available
(1) No
(2) Eyeglasses/sunglasses
(3) Contact lenses
(4) Deployed, unknown if eyewear worn
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



DRIVER AIR BAG SKETCHES (Cont'd)

3. DRIVER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W_U) _____ width (W_L) _____

height (H) _____



4. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS



PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W) _____

height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

width (W_U) _____

height (H_U) _____

b. Lower Flap

width (W_L) _____

height (H_L) _____



5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON *"OTHER"* AIR BAG (Back)

"OTHER" AIR BAG SKETCHES (Cont'd)

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	A-Head Restraint Type/Damage	1	0	1
	B-Seat Type	07	07	07
	C-Seat Orientation	1	1	1
	D-Seat Track Position	5	5	6
	E-Seat Back Incline Pre/Post Impact	23	23	23
	F-Seat Performance	1	1	1
SECOND	A-Head Restraint Type/Damage	0		0
	B-Seat Type	02		02
	C-Seat Orientation	3		3
	D-Seat Track Position	1		1
	E-Seat Back Incline Pre/Post Impact	01		01
	F-Seat Performance	1		1
THIRD	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			
OTHER	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

A-Head Restraint Type/Damage by Occupant at This Occupant Position
(0) No head restraints
(1) Integral — no damage
(2) Integral — damaged during accident
(3) Adjustable — no damage
(4) Adjustable — damaged during accident
(5) Add-on — no damage
(6) Add-on — damaged during accident
(8) Other Specify):_____
(9) Unknown

B-Seat Type (this Occupant Position)
(00) Occupant not seated or no seat
(01) Bucket
(02) Bucket with folding back
(03) Bench
(04) Bench with separate back cushions
(05) Bench with folding back(s)
(06) Split bench with separate back cushions
(07) Split bench with folding back(s)
(08) Pedestal (i.e., column supported)
(09) Box mounted seat (i.e., van type)
(10) Other seat type (specify):
_____
(99) Unknown

C-Seat Orientation (this Occupant Position)
(0) Occupant not seated or no seat
(1) Forward facing seat
(2) Rear facing seat
(3) Side facing seat (inward)
(4) Side facing seat (outward)
(8) Other (specify):
_____
(9) Unknown

D-Seat Track Adjusted Position Prior To Impact
(0) Occupant not seated or no seat
(1) Non-adjustable seat track

Adjustable Seat Track
(2) Seat at forward most track position
(3) Seat between forward most and middle track positions
(4) Seat at middle track position
(5) Seat between middle and rear most track positions
(6) Seat at rear most track position
(9) Unknown

E-Seat Back Incline Prior and Post Impact
(00) Occupant not seated or no seat
(01) Not adjustable

Upright prior to impact
(11) Moved to completely rearward position
(12) Moved to rearward midrange position
(13) Moved to slightly rearward position
(14) Retained pre-impact position
(15) Moved to slightly forward position
(16) Moved to forward midrange position
(17) Moved to completely forward position

Slightly reclined prior to impact
(21) Moved to completely rearward position
(22) Moved to rearward midrange position
(23) Retained pre-impact postion
(24) Moved to upright position
(25) Moved to slightly forward position
(26) Moved to forward midrange position
(27) Moved to completely forward position

Completely reclined prior to impact
(31) Retained pre-impact position
(32) Moved to rearward midrange position
(33) Moved to slightly rearward position
(34) Moved to upright position
(35) Moved to slightly forward position
(36) Moved to forward midrange position
(37) Moved to completely forward position

(99) Unknown

F-Seat Performance (this Occupant Position)
(0) Occupant not seated or no seat
(1) No seat performance failure(s)
(2) Seat adjusters failed
(3) Seat back folding locks or "seat back" failed (specify):
_____
(4) Seat tracks/anchors failed
(5) Deformed by impact of occupant
(6) Deformed by passenger compartment intrusion (specify):_____
(7) Combination of above (specify):
_____
(8) Other (specify):
_____
(9) Unknown







Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat
   - (0) No child safety seat
   - (1) Infant seat
   - (2) Toddler seat
   - (3) Convertible seat
   - (4) Booster seat
   - (7) Other type child safety seat (specify): _____
   - (8) Unknown child safety seat type
   - (9) Unknown if child safety seat used

2. Child Safety Seat Orientation
   - (00) No child safety seat

   Designed for Rear Facing for This Age/Weight
   - (01) Rear facing
   - (02) Forward facing
   - (08) Other orientation (specify): _____
   - (09) Unknown orientation

   Designed for Forward Facing for This Age/Weight
   - (11) Rear facing
   - (12) Forward facing
   - (18) Other orientation (specify): _____
   - (19) Unknown orientation

   Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
   - (21) Rear facing
   - (22) Forward facing
   - (28) Other orientation (specify): _____
   - (29) Unknown orientation
   - (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage
   Note: Options Below Are Used for Variables 3-5.
   - (00) No child safety seat

   Not Designed with Harness/Shield/Tether
   - (01) After market harness/shield/tether added, not used
   - (02) After market harness/shield/tether used
   - (03) Child safety seat used, but no after market harness/shield/tether added
   - (09) Unknown if harness/shield/tether added or used

   Designed With Harness/Shield/Tether
   - (11) Harness/shield/tether not used
   - (12) Harness/shield/tether used
   - (19) Unknown if harness/shield/tether used

   Unknown If Designed With Harness/Shield/Tether
   - (21) Harness/shield/tether not used
   - (22) Harness/shield/tether used
   - (29) Unknown if harness/shield/tether used

   (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
   (Specify make/model and occupant number)

   _____

   _____

   _____

   _____

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [ ] Yes [ ]

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection
(1) Complete ejection
(2) Partial ejection
(3) Ejection, Unknown degree
(9) Unknown

Ejection Area
(1) Windshield
(2) Left front
(3) Right front
(4) Left rear
(5) Right rear
(6) Rear
(7) Roof
(8) Other area (e.g., back of pickup, etc.) (specify): _____
(9) Unknown

Ejection Medium
(1) Door/hatch/tailgate
(2) Nonfixed roof structure
(3) Fixed glazing
(4) Nonfixed glazing (specify): _____
(5) Integral structure
(8) Other medium (specify): _____
(9) Unknown

Medium Status (Immediately Prior to Impact)
(1) Open
(2) Closed
(3) Integral structure
(9) Unknown

ENTRAPMENT No [ ] Yes [ ]

Describe entrapment mechanism: _____

Component(s): _____

(Note on vehicle interior sketch)

U.S. Department of Transportation
National Highway Traffic Safety Administration

OCCUPANT ASSESSMENT FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number 05
2. Case Number - Stratum 011A
3. Vehicle Number 02
4. Occupant Number 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 17
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 1
(1) Male
(2) Female-not reported pregnant
(3) Female-pregnant-1st trimester(1st-3rd month)
(4) Female-pregnant-2nd trimester(4th-6th month)
(5) Female-pregnant-3rd trimester(7th-9th month)
(6) Female-pregnant-term unknown
(9) Unknown

7. Occupant's Height 999
Code actual height to the nearest centimeter.
(999) Unknown

___ ___ inches X 2.54 = ___ ___ ___ centimeters

8. Occupant's Weight 999
Code actual weight to the nearest kilogram.
(999) Unknown

___ ___ ___ pounds X .4536 = ___ ___ ___ kilograms

9. Occupant's Role 1
(1) Driver
(2) Passenger
(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

Second Seat
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

Third Seat
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

Fourth Seat
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 9Ø
(0) Normal posture

Abnormal posture
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

EJECTION/ENTRAPMENT

12. Ejection 0
    (0) No ejection
    (1) Complete ejection
    (2) Partial ejection
    (3) Ejection, unknown degree
    (9) Unknown

13. Ejection Area 0
    (0) No ejection
    (1) Windshield
    (2) Left front
    (3) Right front
    (4) Left rear
    (5) Right rear
    (6) Rear
    (7) Roof
    (8) Other area (e.g., back of pickup, etc.) (specify):_____
    (9) Unknown

14. Ejection Medium 0
    (0) No ejection
    (1) Door/hatch/tailgate
    (2) Nonfixed roof structure
    (3) Fixed glazing
    (4) Nonfixed glazing (specify): _____
    (5) Integral structure
    (8) Other medium (specify): _____
    (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0
    (0) No ejection
    (1) Open
    (2) Closed
    (3) Integral structure
    (9) Unknown

16. Entrapment 0
    (0) Not entrapped/exit not inhibited
    (1) Entrapped/pinned - mechanically restrained
    (2) Could not exit vehicle due to jammed doors, fire, etc. (specify):_____
    (9) Unknown

17. Occupant Mobility Pw PAR 4
    (0) Occupant fatal before removed from vehicle
    (1) Removed from vehicle while unconscious or not oriented to time or place
    (2) Removed from vehicle due to perceived serious injuries
    (3) Exited vehicle with some assistance
    (4) Exited vehicle under own power
    (5) Occupant fully ejected
    (8) Removed from vehicle for other reasons (specify): _____
    (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4
    (0) None available
    (1) Belt removed/destroyed
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt available—type unknown

    Integral Belt Partially Destroyed
    (6) Shoulder belt (lap belt destroyed/removed)
    (7) Lap belt (shoulder belt destroyed/removed)
    (8) Other belt (specify): _____
    (9) Unknown

19. Manual (Active) Belt System Use 04
    (00) None used, not available, or belt removed/destroyed
    (01) Inoperative (specify): _____
    (02) Shoulder belt
    (03) Lap belt
    (04) Lap and shoulder belt
    (05) Belt used—type unknown
    (08) Other belt used (specify): _____
    (12) Shoulder belt used with child safety seat
    (13) Lap belt used with child safety seat
    (14) Lap and shoulder belt used with child safety seat
    (15) Belt used with child safety seat—type unknown
    (18) Other belt used with child safety seat (specify): _____
    (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9X
    (0) None used or not available
    (1) Belt used properly
    (2) Belt used properly with child safety seat

    Belt Used Improperly
    (3) Shoulder belt worn under arm
    (4) Shoulder belt worn behind back or seat
    (5) Belt worn around more than one person
    (6) Lap belt worn on abdomen
    (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of manual belt system (specify): _____
    (9) Unknown

NASS CODING CHANGE
1st Review: 1F
2nd Review: _____

21. Manual (Active) Belt Failure Modes During Accident 1
    (0) No manual belt used or not available
    (1) No manual belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify): _____
    (8) Other manual belt failure (specify): _____
    (9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 1
    (0) No manual shoulder belt
    (1) No upper anchorage adjustment for manual shoulder belt

    Adjustable shoulder Belt Upper Anchorage
    (2) In full up position
    (3) In mid position
    (4) In full down position
    (5) Position unknown
    (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0
    (0) Not equipped/not available
    (1) 2 point automatic belts
    (2) 3 point automatic belts
    (3) Automatic belts - type unknown

    Non-functional
    (4) Automatic belts destroyed or rendered inoperative
    (9) Unknown

24. Automatic (Passive) Belt System Use 0
    (0) Not equipped/not available/destroyed or rendered inoperative
    (1) Automatic belt in use
    (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
    (3) Automatic belt use unknown
    (9) Unknown

25. Automatic (Passive) Belt System Type 0
    (0) Not equipped/not available
    (1) Non-motorized system
    (2) Motorized system
    (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0
    (0) Not equipped/not available/not used
    (1) Automatic belt used properly
    (2) Automatic belt used properly with child safety seat

    Automatic Belt Used Improperly
    (3) Automatic shoulder belt worn under arm
    (4) Automatic shoulder belt worn behind back
    (5) Automatic belt worn around more than one person
    (6) Lap portion of automatic belt worn on abdomen
    (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
    (8) Other improper use of automatic belt system (specify): _____
    (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0
    (0) Not equipped/not available/not in use
    (1) No automatic belt failure(s)
    (2) Torn webbing (stretched webbing not included)
    (3) Broken buckle or latchplate
    (4) Upper anchorage separated
    (5) Other anchorage separated (specify): _____
    (6) Broken retractor
    (7) Combination of above (specify):
    (8) Other automatic belt failure (specify): _____
    (9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4
    (0) None used
    (1) Police did not indicate belt use
    (2) Shoulder belt
    (3) Lap belt
    (4) Lap and shoulder belt
    (5) Belt used, type not specified
    (6) Child safety seat
    (7) Automatic belt
    (8) Other type belt, (specify): _____
    (9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 0
    (0) No air bag available
    (1) Police did not indicate air bag availability/function
    (2) Deployed
    (3) Not deployed
    (4) Unknown if deployed
    (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

[✓] Vehicle inspection
[ ] Official injury data
[ ] Driver/occupant interview
[ ] Other (specify): _____
[ ] Unknown if belt used

_____
_____
_____
_____

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag
    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0
    (0) Not equipped/not available
    (1) Air bag
    Non-functional
    (2) Air bag disconnected (specify): _____
    (3) Air bag not reinstalled
    (9) Unknown
    Specify type of "other" air bag present: _____

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0
    (0) Not equipped with an "other" air bag
    (1) Deployed during accident (as a result of impact)
    (2) Deployed inadvertently just prior to accident
    (3) Deployed, details unknown
    (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
    (5) Unknown if deployed
    (7) Nondeployed
    (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0
    (0) Not equipped/not available
    (1) No previous accidents

    Yes
    (2) Previous accident(s) without deployment(s)
    (3) One previous accident with deployment
    (4) More than one previous accident with at least one deployment
    (8) Previous accidents, unknown deployment status
    (9) Unknown

36. Type of Air Bag 0
    (0) Not equipped/not available
    (1) Original manufacturer installed system
    (2) Retrofitted air bag
    (3) Replacement air bag
    (8) Unknown type of air bag
    (9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0
    (0) Not equipped/not available
    (1) No prior maintenance
    (2) Yes, prior maintenance (specify): _____
    (9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00
    (00) Not equipped/not available
    _____ Code the accident event sequence number that initiated the air bag deployment
    (96) Deployed, unknown event
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

39. CDC For Air Bag Deployment Impact 0
    (0) Not equipped/not available
    (1) Highest delta V
    (2) Second highest delta V
    (3) Other non-coded delta V (specify): _____
    (6) Deployed, unknown event
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 000
    (_000) Not equipped/not available
    Code the value of the delta V for the impact that initiated the air bag deployment
    (_996) Deployment, unknown longitudinal Delta V
    (_997) Not deployed
    (_998) Unknown if deployed
    (_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes
    (3) Deployed, unknown if flap(s) opened at designated tear points
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (3) Deployed, unknown if air bag module cover flap(s) damaged
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

43. Was There Damage To The Air Bag? 00
    (00) Not equipped/not available
    (01) Not damaged

    Yes - Air Bag Damage
    (02) Ruptured
    (03) Cut
    (04) Torn
    (05) Holed
    (06) Burned
    (07) Abraded
    (88) Other damage (specify): _____
    (95) Damaged, details unknown
    (96) Deployed, unknown if damaged
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION *continued*

44. Source of Air Bag Damage 00
    (00) Not equipped/not available
    (01) Not damaged
    (02) Object worn by occupant, (specify): _____
    (03) Object carried by occupant, (specify): _____
    (04) Adaptive/assistive controls, (specify): _____
    (05) Fire in vehicle
    (06) Thermal burns
    (07) Rescue or emergency efforts
    (88) Other damage source (specify): _____
    (95) Damaged, unknown source
    (96) Deployed, unknown if damaged
    (97) Not deployed
    (98) Unknown if deployed
    (99) Unknown

45. Was The Air Bag Tethered? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of tether straps): _____
    (3) Deployed, unknown if tethered
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

46. Did The Air Bag Have Vent Ports? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify number of vent ports): _____
    (3) Deployed, unknown if vent ports present
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0
    (0) Not equipped/not available
    (1) No
    (2) Yes (specify): _____
    (3) Deployed, unknown if other occupant contact to air bag
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

48. Was This Occupant Wearing Eye-wear? 0
    (0) Not air bag equipped/air bag not available
    (1) No
    (2) Eyeglasses/sunglasses
    (3) Contact lenses
    (4) Deployed, unknown if eyewear worn
    (7) Not deployed
    (8) Unknown if deployed
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 1
    (0) No head restraints
    (1) Integral—no damage
    (2) Integral—damaged during accident
    (3) Adjustable—no damage
    (4) Adjustable—damaged during accident
    (5) Add-on—no damage
    (6) Add-on—damaged during accident
    (8) Other (specify): _____
    (9) Unknown

50. Seat Type (this Occupant Position) 07
    (00) Occupant not seated or no seat
    (01) Bucket
    (02) Bucket with folding back
    (03) Bench
    (04) Bench with separate back cushions
    (05) Bench with folding back(s)
    (06) Split bench with separate back cushions
    (07) Split bench with folding back(s)
    (08) Pedestal (i.e., column supported)
    (09) Box mounted seat (i.e., van type)
    (10) Other seat type (specify): _____
    (99) Unknown

51. Seat Orientation (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) Forward facing seat
    (2) Rear facing seat
    (3) Side facing seat (inward)
    (4) Side facing seat (outward)
    (8) Other (specify): _____
    (9) Unknown

52. Seat Track Adjusted Position Prior To Impact 5
    (0) Occupant not seated or no seat
    (1) Non-adjustable seat track

    Adjustable Seat Track
    (2) Seat at forward most track position
    (3) Seat between forward most and middle track positions
    (4) Seat at middle track position
    (5) Seat between middle and rear most track positions
    (6) Seat at rear most track position
    (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*

53. Seat Back Incline Prior and Post Impact 23
    (00) Occupant not seated or no seat
    (01) Not adjustable

    Upright prior to impact
    (11) Moved to completely rearward position
    (12) Moved to rearward midrange position
    (13) Moved to slightly rearward position
    (14) Retained pre-impact position
    (15) Moved to slightly forward position
    (16) Moved to forward midrange position
    (17) Moved to completely forward position



    Slightly reclined prior to impact
    (21) Moved to completely rearward position
    (22) Moved to rearward midrange position
    (23) Retained pre-impact position
    (24) Moved to upright position
    (25) Moved to slightly forward position
    (26) Moved to forward midrange position
    (27) Moved to completely forward position



    Completely reclined prior to impact
    (31) Retained pre-impact position
    (32) Moved to rearward midrange position
    (33) Moved to slightly rearward position
    (34) Moved to upright position
    (35) Moved to slightly forward position
    (36) Moved to forward midrange position
    (37) Moved to completely forward position



    (99) Unknown

54. Seat Performance (this Occupant Position) 1
    (0) Occupant not seated or no seat
    (1) No seat performance failure(s)
    (2) Seat adjusters failed
    (3) Seat back folding locks or "seat back" failed (specify):_____
    (4) Seat track/anchors failed
    (5) Deformed by impact of occupant
    (6) Deformed by passenger compartment intrusion, (specify):_____
    (7) Combination of above (specify):_____
    (8) Other (specify): _____
    (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model 000
(000) No child safety seat
Applicable codes are found in your NASS CDS Data Collection, Coding and Editing
(950) Built-in child safety seat
(997) Other make/model (specify):
_____
(998) Unknown make/model
(999) Unknown if child safety seat used

56. Type of Child Safety Seat 0
(0) No child safety seat
(1) Infant seat
(2) Toddler seat
(3) Convertible seat
(4) Booster seat - with shield
(5) Booster seat - without shield
(7) Other type child safety seat (specify):
_____
(8) Unknown child safety seat type
(9) Unknown if child safety seat used

57. Child Safety Seat Orientation 00
(00) No child safety seat

Designed for Rear Facing for This Age/Weight
(01) Rear facing
(02) Forward facing
(08) Other orientation (specify):
_____
(09) Unknown orientation

Designed For Forward Facing for This Age/Weight
(11) Rear facing
(12) Forward facing
(18) Other orientation (specify):
_____
(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
(21) Rear facing
(22) Forward facing
(28) Other orientation (specify):
_____
(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage 00

59. Child Safety Seat Shield Usage 00

60. Child Safety Seat Tether Usage 00

Note: Options below applicable to Variables OA58-OA60.
(00) No child safety seat

Not Designed With Harness/Shield/Tether
(01) After market harness/shield/tether added, not used
(02) After market harness/shield/tether used
(03) Child safety seat used, but no after market harness/shield/tether added
(09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether
(11) Harness/shield/tether not used
(12) Harness/shield/tether used
(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether
(21) Harness/shield/tether not used
(22) Harness/shield/tether used
(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 2

(0) O - No injury
(1) C - Possible injury
(2) B - Nonincapacitating injury
(3) A - Incapacitating injury
(4) K - Killed
(5) U - Injury, severity unknown
(6) Died prior to accident
(9) Unknown

62. Treatment - Mortality 4

(0) No treatment
(1) Fatal
(2) Fatal - ruled disease (specify):

_____

Nonfatal
(3) Hospitalization
(4) Transported and released
(5) Treatment at scene - nontransported
(6) Treatment later
(7) Treatment - other (specify):

_____

(8) Transported to a medical facility-unknown if treated
(9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 2

(0) Not treated at a medical facility
(1) Trauma center
(2) Hospital
(3) Medical clinic
(4) Physician's office
(5) Treatment later at medical facility
(8) Other (specify):

_____

(9) Unknown

64. Hospital Stay 00

(00) Not Hospitalized
____Code the number of days (up through 60) that the occupant stayed in hospital.
(61) 61 days or more
(99) Unknown

65. Working Days Lost 97

____Code the number of days (up through 60) that the occupant lost from work due to the accident
(00) No working days lost
(61) 61 days or more
(62) Fatally injured
(97) Not working prior to accident
(99) Unknown

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER

INJURY CONSEQUENCES

66. Time to Death 00
____Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)
(00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 00

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00
____Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
(00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____
(97) Other result (includes fatal ruled disease) (specify): _____
(99) Unknown

70. Number of Recorded Injuries for This Occupant 01
____Code the actual number of injuries recorded for this occupant.
(00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 02
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given (specify units): _____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) – HCO_3 01
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

U.S. Department of Transportation

National Highway Traffic Safety Administration

OCCUPANT INJURY FORM

Form Approved
O.M.B. No. 2127-0021

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number	05	3. Vehicle Number	02
2. Case Number - Stratum	01 1A	4. Occupant Number	01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. 3	6. 2	7. 9	8. 04	9. 02	10. 1	11. 4	12. 006	13. 2	14. 1	15. 00
2nd	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.
3rd	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.
4th	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.
5th	49.	50.	51.	52.	53.	54.	55.	56.	57.	58.	59.
6th	60.	61.	62.	63.	64.	65.	66.	67.	68.	69.	70.
7th	71.	72.	73.	74.	75.	76.	77.	78.	79.	80.	81.
8th	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.
9th	93.	94.	95.	96.	97.	98.	99.	100.	101.	102.	103.
10th	104.	105.	106.	107.	108.	109.	110.	111.	112.	113.	114.

HS Form 433B (1/96)

This report is authorized by P.L. 89-563, Title 1, Section 106, 108, and 112. While you are not required to respond, your cooperation is needed to make the results of this data collection effort comprehensive, accurate, and timely.

OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90 Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
11th											
12th											
13th											
14th											
15th											
16th											
17th											
18th											
19th											
20th											
21st											
22nd											
23rd											
24th											
25th											

OCCUPANT INJURY CLASSIFICATION

Body Region

(1) Head
(2) Face
(3) Neck
(4) Thorax
(5) Abdomen
(6) Spine
(7) Upper Extremity
(8) Lower Extremity
(9) Unspecified

Type of Anatomic Structure

(1) Whole Area
(2) Vessels
(3) Nerves
(4) Organs (includes Muscles/ligaments)
(5) Skeletal (includes joints)
(6) Head - LOC
(9) Skin

Specific Anatomic Structure

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02.

The exceptions to this rule apply to:

Whole Area
(02) Skin - Abrasion
(04) Skin - Contusion
(06) Skin - Laceration
(08) Skin - Avulsion
(10) Amputation
(20) Burn
(30) Crush
(40) Degloving
(50) Injury - NFS
(90) Trauma, other than mechanical

Head - LOC
(02) Length of LOC

(04) Level
(06) of
(08) Consciousness

(10) Concussion

Spine
(02) Cervical
(04) Thoracic
(06) Lumbar

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

(1) Minor Injury
(2) Moderate Injury
(3) Serious Injury
(4) Severe Injury
(5) Critical Injury
(6) Maximum (untreatable)
(7) Injured, unknown severity

Aspect

(1) Right
(2) Left
(3) Bilateral
(4) Central
(5) Anterior
(6) Posterior
(7) Superior
(8) Inferior
(9) Unknown
(0) Whole region

SOURCE OF INJURY DATA

OFFICIAL RECORDS
(1) Autopsy records with or without hospital/medical records
(2) Hospital/medical records other than emergency room (e.g., discharge summary)
(3) Emergency room records only (including associated X-rays or other lab reports)
(4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS
(5) Lay coroner report
(6) E.M.S. personnel
(7) Interviewee
(8) Other source (specify): _____
(9) Police

INJURY SOURCE CONFIDENCE LEVEL

(1) Certain
(2) Probable
(3) Possible
(9) Unknown

DIRECT/INDIRECT INJURY

(1) Direct contact injury
(2) Indirect contact injury
(3) Noncontact injury
(7) Injured, unknown source

INJURY SOURCES

FRONT
(001) Windshield
(002) Mirror
(003) Sunvisor
(004) Steering wheel rim
(005) Steering wheel hub/spoke
(006) Steering wheel (combination of codes 004 and 005)
(007) Steering column, transmission selector lever, other attachment
(008) Cellular telephone or CB radio
(009) Add on equipment (e.g., tape deck, air conditioner)
(010) Left instrument panel and below
(011) Center instrument panel and below
(012) Right instrument panel and below
(013) Glove compartment door
(014) Knee bolster
(015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
(016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
(017) Windshield reinforced by exterior object (specify) _____
(019) Other front object (specify): _____

LEFT SIDE
(051) Left side interior surface, excluding hardware or armrests
(052) Left side hardware or armrest
(053) Left A (A1/A2)-pillar
(054) Left B-pillar
(055) Other left pillar (specify): _____
(056) Left side window glass
(057) Left side window frame
(058) Left side window sill
(059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(060) Other left side object (specify): _____

RIGHT SIDE
(101) Right side interior surface, excluding hardware or armrests
(102) Right side hardware or armrest
(103) Right A (A1/A2)-pillar
(104) Right B-pillar
(105) Other right pillar (specify): _____
(106) Right side window glass
(107) Right side window frame
(108) Right side window sill
(109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
(110) Other right side object (specify): _____

INTERIOR
(151) Seat, back support
(152) Belt restraint webbing/buckle
(153) Belt restraint B-pillar or door frame attachment point
(154) Other restraint system component (specify): _____
(155) Head restraint system
(160) Other occupants (specify): _____
(161) Interior loose objects
(162) Child safety seat (specify): _____
(163) Other interior object (specify): _____

AIR BAG
(170) Air bag-driver side
(171) Air bag-driver side and eyewear
(172) Air bag-driver side and jewelry
(173) Air bag-driver side and object held
(174) Air bag-driver side and object in mouth
(175) Air bag compartment cover-driver side
(176) Air bag compartment cover-driver side and eyewear
(177) Air bag compartment cover-driver side and jewelry
(178) Air bag compartment cover-driver side and object held
(179) Air bag compartment cover-driver side and object in mouth
(180) Air bag-passenger side
(181) Air bag-passenger side and eyewear
(182) Air bag-passenger side and jewelry
(183) Air bag-passenger side and object held
(184) Air bag-passenger side and object in mouth
(185) Air bag compartment cover-passenger side
(186) Air bag compartment cover-passenger side and eyewear
(187) Air bag compartment cover-passenger side and jewelry
(188) Air bag compartment cover-passenger side and object held
(189) Air bag compartment cover-passenger side and object in mouth
(190) Other air bag (specify) _____
(195) Other air bag compartment cover (specify) _____

ROOF
(201) Front header
(202) Rear header
(203) Roof left side rail
(204) Roof right side rail
(205) Roof or convertible top

FLOOR
(251) Floor (including toe pan)
(252) Floor or console mounted transmission lever, including console
(253) Parking brake handle
(254) Foot controls including parking brake

REAR
(301) Backlight (rear window)
(302) Backlight storage rack, door, etc.
(303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT
(401) Hand controls for braking/acceleration
(402) Steering control devices (attached to OEM steering wheel)
(403) Steering knob attached to steering wheel
(405) Replacement steering wheel (i.e., reduced diameter)
(406) Joy stick steering controls
(407) Wheelchair tie-downs
(408) Modification to seat belts, (specify): _____
(409) Additional or relocated switches, (specify): _____
(410) Raised roof
(411) Wall mounted head rest (used behind wheel chair)
(412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE
(451) Hood
(452) Outside hardware (e.g., outside mirror, antenna)
(453) Other exterior surface or tires (specify): _____
(454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE
(501) Front bumper
(502) Hood edge
(503) Other front of vehicle (specify): _____
(504) Hood
(505) Hood ornament
(506) Windshield, roof rail, A-pillar
(507) Side surface
(508) Side mirrors
(509) Other side protrusions (specify): _____
(510) Rear surface
(511) Undercarriage
(512) Tires and wheels
(513) Other exterior of other motor vehicle (specify): _____
(514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT
(551) Ground
(598) Other vehicle or object (specify): _____
(599) Unknown vehicle or object

NONCONTACT INJURY
(601) Fire in vehicle
(602) Flying glass
(603) Other noncontact injury source (specify): _____
(604) Air bag exhaust gases
(697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Restrained?

__ No

✓ Yes

Blood Alcohol Level (mg/dl)

BAL = NR

Glasgow Coma Scale Score

GCSS = NR

Units of Blood Given

Units = 0

Arterial Blood Gases

pH = __.__

PO_2 = ___

PCO_2 ___

HCO_3 ___

no work

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

ER ⊖LOC

NOSE CONTUSION
STEERING WHEEL



OFFICIAL INJURY DATA — SKELETAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





U.S. Department of Transportation
National Highway Traffic Safety Administration

SMASH PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

05	011A	03	[redacted], 96
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

GENERAL INFORMATION

VEHICLE 1		VEHICLE 2	
NASS Vehicle Number	01	NASS Vehicle Number	
Year	1993	Year	
Make	Pontiac	Make	
Model	Bonneville SE	Model	
Body Style	4S	Body Style	
CDC	03 RPEN1	CDC	BARRIER
PDOF	⊕ 090 °	PDOF	± °
Heading Angle	⊕ 270 °	Heading Angle	± °

VEHICLE SPECIFICATIONS

VEHICLE 1		VEHICLE 2	
Wheelbase	281 cm	Wheelbase	cm
Overall Length	507 cm	Overall Length	cm
Overall Width	187 cm	Overall Width	cm
Weight	1525 + 151 + 0 = 1676 kg	Weight	+ + = kg
	Curb Occupant(s) Cargo		Curb Occupant(s) Cargo
Engine Displacement	3.8 L	Engine Displacement	. L
Drive System	FWD	Drive System	
Size	4	Size	
Stiffness	4	Stiffness	

DAMAGE INFORMATION

VEHICLE 1		VEHICLE 2	
Damage Known?	Y	Damage Known?	
Damage Length	054 cm	Damage Length	cm
Damage Offset	⊕ 005 cm	Damage Offset	± cm
Crush Depth: C1	2 cm	Crush Depth: C1	cm
C2	8 cm	C2	cm
C3	6 cm	C3	cm
C4	5 cm	C4	cm
C5	6 cm	C5	cm
C6	5 cm	C6	cm

National Accident Sampling System-Crashworthiness Data System: SMASH Program Summary

SCENE INFORMATION

Rest and Impact Positions [ ] No [ ] Yes

	VEHICLE 1		VEHICLE 2	
Rest Position	X	___ ___ ___ . ___ m	X	___ ___ ___ . ___ m
	Y	___ ___ ___ . ___ m	Y	___ ___ ___ . ___ m
	Heading Angle	___ ___ ___ °	Heading Angle	___ ___ ___ °
Impact Position	X	___ ___ ___ . ___ m	X	___ ___ ___ . ___ m
	Y	___ ___ ___ . ___ m	Y	___ ___ ___ . ___ m
	Heading Angle	___ ___ ___ °	Heading Angle	___ ___ ___ °
Slip Angle (-180 to +180)		___ ___ ___ °		___ ___ ___ °

VEHICLE MOTION

	VEHICLE 1	VEHICLE 2
Sustained Contact	[ ] No [ ] Yes	[ ] No [ ] Yes
Vehicle Rotation	[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest	[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X ___ ___ ___ . ___ m	X ___ ___ ___ . ___ m
	Y ___ ___ ___ . ___ m	Y ___ ___ ___ . ___ m
Heading Angle	___ ___ ___ °	___ ___ ___ °
Curved Path	[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m	X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

FRICTION INFORMATION

Coefficient of Friction ___ ___

Rolling Resistance Option 1

Vehicle 1 Rolling Resistance		Vehicle 2 Rolling Resistance	
LF	___ . ___ ___	LF	___ . ___ ___
RF	___ . ___ ___	RF	___ . ___ ___
LR	___ . ___ ___	LR	___ . ___ ___
RR	___ . ___ ___	RR	___ . ___ ___

IF THIS COMMON IMPACT WAS WITH A CDS VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate damage sketch and dimensions to the form.

Summary of Results Using Damage

Speed Change (Damage)

Vehicle #1

Total	7 km/h	(4 mph)
Longitudinal	0 km/h	(0 mph)
Latitudinal	-7 km/h	(-4 mph)
PDOF Angle	90 °	
Energy Dissipated	= 2961 Joules	(2184 Ft-Lb)
Barrier Equivalent Speed	= 6.7 km/h	(4.2 mph)

Calculated using size and stiffness categories.

Vehicle #2

Total	0 km/h	(0 mph)
Longitudinal	0 km/h	(0 mph)
Latitudinal	0 km/h	(0 mph)
PDOF Angle	0 °	
Energy Dissipated	= 0 Joules	(0 Ft-Lb)
Barrier Equivalent Speed	= 0.0 km/h	(0.0 mph)

Calculated using size and stiffness categories.

General Information

	Vehicle #1	Vehicle #2
Year	1993	1900
Make	Pontiac	
Model	Bonneville SE	
CDC	03RPEN1	BARRIER
Side Damaged	R	
PDOF Angle	90 °	0 °
Heading Angle	270 °	0 °
Calculation method:	Size and Stiffness	Size and Stiffness
Size Category	4	11
Stiffness Category	4	11
Vehicle Weight	1676 kgs (3695 lbs)	453592 kgs (999999 lbs)

Damage Information

	Vehicle #1	Vehicle #2
Vehicle Damage Known	Yes	Yes
Crush Length	54.0 cm (21 in)	0.0 cm (0 in)
C1	2.0 cm (1 in)	0.0 cm (0 in)
C2	8.0 cm (3 in)	0.0 cm (0 in)
C3	6.0 cm (2 in)	0.0 cm (0 in)
C4	5.0 cm (2 in)	0.0 cm (0 in)
C5	6.0 cm (2 in)	0.0 cm (0 in)
C6	5.0 cm (2 in)	0.0 cm (0 in)
D	-4.9 cm (-2 in)	0.0 cm (0 in)
D'	-5.0 cm (-2 in)	0.0 cm (0 in)

Vehicle Dimensions

	Vehicle #1	Vehicle #2
Length	506.7 cm (199 in)	0.0 cm (0 in)
Width	189.2 cm (74 in)	0.0 cm (0 in)
Wheelbase	281.4 cm (111 in)	254.0 cm (100 in)
Weight	1676 kgs (3695 lbs)	453592 kgs (999999 lbs)
CG to Front of Veh	251.0 cm (99 in)	127.0 cm (50 in)
Engine Displacement	3.8 liters	0.0 liters
Moment of Inertia	388702 kgs (34405 lbs)	29375740821 kgs (2600101632 lbs)
Vehicle Mass	1676 kgs (9.6 lb-s^2/in)	453515 kgs (2600.1 lb-s^2/in)

1993 Pontiac Bonneville SE



1993

U.S. Department of Transportation
National Highway Traffic Safety Administration

SMASH PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run
05	011A	01	[redacted], 96

GENERAL INFORMATION

	VEHICLE 1	VEHICLE 2
NASS Vehicle Number	01	02
Year	1993	1988
Make	Pontiac.	FORD
Model	Bonneville SE	RANGER
Body Style	4S	PU
CDC	10 L YAW 5	01 FDEW3
PDOF	~~070~~ ok	020
Heading Angle	340 °	080 °

VEHICLE SPECIFICATIONS

	VEHICLE 1	VEHICLE 2
Wheelbase	281 cm	318 cm
Overall Length	507 cm	490 ~~489~~ cm
Overall Width 64+41+32	187 cm	170 cm
Weight	1525 + ~~151~~ 137 + 0 = ~~1676~~ 1662 kg (Curb + Occupant(s) + Cargo)	~~1515~~ 1490 + 66 + ~~136~~ 61 = ~~1717~~ 1597 kg (Curb + Occupant(s) + Cargo)
Engine Displacement	3.8 L	2.9 L
Drive System	FWD	4WD
Size	4	~~4~~ 6
Stiffness	4	~~4~~ 8

DAMAGE INFORMATION

	VEHICLE 1	VEHICLE 2
Damage Known?	Y	Y
Damage Length	197 cm	148 cm
Damage Offset	012 cm	± 000 cm
Crush Depth: C1	00 cm	58 cm
C2	56 cm	20 cm
C3	72 cm	14 cm
C4	84 cm	6 cm
C5	26 cm	~~0~~ 1 cm
C6	00 cm	~~0~~ 1 cm

National Accident Sampling System-Crashworthiness Data System: SMASH Program Summary

SCENE INFORMATION

Rest and Impact Positions [ ] No [ ] Yes

	VEHICLE 1		VEHICLE 2	
Rest Position	X	___ ___ ___ . ___ m	X	___ ___ ___ . ___ m
	Y	___ ___ ___ . ___ m	Y	___ ___ ___ . ___ m
	Heading Angle	___ ___ ___ °	Heading Angle	___ ___ ___ °
Impact Position	X	___ ___ ___ . ___ m	X	___ ___ ___ . ___ m
	Y	___ ___ ___ . ___ m	Y	___ ___ ___ . ___ m
	Heading Angle	___ ___ ___ °	Heading Angle	___ ___ ___ °
Slip Angle (-180 to +180)		___ ___ ___ °		___ ___ ___ °

VEHICLE MOTION

	VEHICLE 1	VEHICLE 2
Sustained Contact	[ ] No [ ] Yes	[ ] No [ ] Yes
Vehicle Rotation	[ ] No [ ] Yes	[ ] No [ ] Yes
Rotation Stop Before Rest	[ ] No [ ] Yes	[ ] No [ ] Yes
End of Rotation Position	X ___ ___ ___ . ___ m	X ___ ___ ___ . ___ m
	Y ___ ___ ___ . ___ m	Y ___ ___ ___ . ___ m
Heading Angle	___ ___ ___ °	___ ___ ___ °
Curved Path	[ ] No [ ] Yes	[ ] No [ ] Yes
Point on Path	X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m	X ___ ___ ___ . ___ m Y ___ ___ ___ . ___ m
Rotation Direction	[ ] None [ ] CW [ ] CCW	[ ] None [ ] CW [ ] CCW
Rotation >360°	[ ] No [ ] Yes	[ ] No [ ] Yes

FRICTION INFORMATION

Coefficient of Friction ___ ___

Rolling Resistance Option 1

Vehicle 1 Rolling Resistance		Vehicle 2 Rolling Resistance	
LF	___ . ___ ___	LF	___ . ___ ___
RF	___ . ___ ___	RF	___ . ___ ___
LR	___ . ___ ___	LR	___ . ___ ___
RR	___ . ___ ___	RR	___ . ___ ___

IF THIS COMMON IMPACT WAS WITH A CDS VEHICLE *NOT IN TRANSPORT,* FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate damage sketch and dimensions to the form.

Summary of Results Using Damage

05 011a re-run arr

Speed Change
(Damage)

Vehicle #1

Total	37 km/h (23 mph)
Longitudinal	-13 km/h (-8 mph)
Latitudinal	35 km/h (21 mph)
PDOF Angle	-70 °
Energy Dissipated	= 198466 Joules (146361 Ft-Lb)
Barrier Equivalent Speed	= 55.1 km/h (34.2 mph)

Calculated using size and stiffness categories.

Vehicle #2

Total	38 km/h (24 mph)
Longitudinal	-36 km/h (-22 mph)
Latitudinal	-13 km/h (-8 mph)
PDOF Angle	20 °
Energy Dissipated	= 44883 Joules (33100 Ft-Lb)
Barrier Equivalent Speed	= 20.5 km/h (12.8 mph)

Calculated using size and stiffness categories.

General Information

	Vehicle #1	Vehicle #2
Year	1993	1988
Make	Pontiac	Ford
Model	Bonneville SE	ranger
CDC	10LYAW5	01FDEW3
Side Damaged	L	F
PDOF Angle	-70 °	20 °
Heading Angle	340 °	80 °
Calculation method:	Size and Stiffness	Size and Stiffness
Size Category	4	6
Stiffness Category	4	8
Vehicle Weight	1662 kgs (3664 lbs)	1597 kgs (3521 lbs)

Damage Information

	Vehicle #1	Vehicle #2
Vehicle Damage Known	Yes	Yes
Crush Length	197.0 cm (78 in)	148.0 cm (58 in)
C1	0.0 cm (0 in)	58.0 cm (23 in)
C2	56.0 cm (22 in)	20.0 cm (8 in)
C3	72.0 cm (28 in)	14.0 cm (6 in)
C4	84.0 cm (33 in)	6.0 cm (2 in)
C5	26.0 cm (10 in)	0.1 cm (0 in)
C6	0.0 cm (0 in)	0.1 cm (0 in)
D	12.0 cm (5 in)	0.0 cm (0 in)
D'	5.5 cm (2 in)	-41.3 cm (-16 in)

Vehicle Dimensions

	Vehicle #1	Vehicle #2
Length	506.7 cm (199 in)	490.0 cm (193 in)
Width	187.0 cm (74 in)	170.0 cm (67 in)
Wheelbase	281.4 cm (111 in)	318.0 cm (125 in)
Weight	1662 kgs (3664 lbs)	1597 kgs (3521 lbs)
CG to Front of Veh	251.0 cm (99 in)	264.7 cm (104 in)
Engine Displacement	3.8 liters	2.0 liters
Moment of Inertia	385455 kgs (34117 lbs)	346414 kgs (30662 lbs)
Vehicle Mass	1662 kgs (9.5 lb-s^2/in)	1597 kgs (9.2 lb-s^2/in)

1988 Ford ranger



1993 Pontiac Bonneville SE



05 011a re-run arr [redacted] 1996

Summary of Results Using Damage

Speed Change (Damage)

Vehicle #1

Total	37 km/h	(23 mph)
Longitudinal	-13 km/h	(-8 mph)
Latitudinal	35 km/h	(22 mph)
PDOF Angle	-70 °	
Energy Dissipated	= 198466 Joules	(146361 Ft-Lb)
Barrier Equivalent Speed	= 54.9 km/h	(34.1 mph)

Calculated using crush coefficients entered by the user.

Vehicle #2

Total	37 km/h	(23 mph)
Longitudinal	-33 km/h	(-21 mph)
Latitudinal	-15 km/h	(-10 mph)
PDOF Angle	25 °	
Energy Dissipated	= 44310 Joules	(32677 Ft-Lb)
Barrier Equivalent Speed	= 19.8 km/h	(12.3 mph)

Calculated using crush coefficients entered by the user.

General Information

	Vehicle #1	Vehicle #2
Year	1993	1988
Make	Pontiac	Ford
Model	Bonneville SE	Pickup
CDC	10LYAW5	01FDEW3
Side Damaged	L	F
PDOF Angle	-70 °	25 °
Heading Angle	340 °	80 °

Calculation method:	Vehicle's Crush Coeff.	Vehicle's Crush Coeff.
d0 crush coeff.	63.30 sqrt(N)	106.50 sqrt(N)
d1 crush coeff.	7.21 sqrt(N)/cm	5.68 sqrt(N)/cm

Damage Information

	Vehicle #1	Vehicle #2
Vehicle Damage Known	Yes	Yes
Crush Length	197.0 cm (78 in)	148.0 cm (58 in)
C1	0.0 cm (0 in)	58.0 cm (23 in)
C2	56.0 cm (22 in)	20.0 cm (8 in)
C3	72.0 cm (28 in)	14.0 cm (6 in)
C4	84.0 cm (33 in)	6.0 cm (2 in)
C5	26.0 cm (10 in)	0.0 cm (0 in)
C6	0.0 cm (0 in)	0.0 cm (0 in)
D	12.0 cm (5 in)	0.0 cm (0 in)
D'	5.5 cm (2 in)	-24.9 cm (-10 in)

Vehicle Dimensions

	Vehicle #1	Vehicle #2
Length	506.7 cm (199 in)	489.0 cm (193 in)
Width	189.2 cm (74 in)	170.0 cm (67 in)
Wheelbase	281.4 cm (111 in)	318.0 cm (125 in)
Weight	1676 kgs (3695 lbs)	1717 kgs (3785 lbs)
CG to Front of Veh	251.0 cm (99 in)	251.0 cm (99 in)
Engine Displacement	3.8 liters	2.9 liters
Moment of Inertia	388702 kgs (34405 lbs)	370925 kgs (32831 lbs)
Vehicle Mass	1676 kgs (9.6 lb-s^2/in)	1717 kgs (9.8 lb-s^2/in)

1988 Ford Pickup



1993 Pontiac Bonneville SE



05011A00000011[redacted]969.0000000000000207300000006[redacted]96[redacted]96[redacted]96[redacted]96021255000
00136500002901308 0205
05011A00010012[redacted]969.0010000000000104L0230F
05011A00020012[redacted]969.0010000000000104R50000
05011A00030012[redacted]969.0010000000000104R60000
05011A00040012[redacted]969.0010000000000104R60000
05011A00050012[redacted]969.0010000000000104R57000
05011A00060012[redacted]969.0010000000000230R3100N
05011A01000021 9.00 0000000009322002041G2HX53L1P1[redacted]024089000011804192
0214221022030117991189
05011A01000022 9.00 0000000001030312015300000000000000[redacted]001001037-013+03
5198599810550301
05011A01000031 9.00 000000000010210LYAW05036003RPEN01197000056072084026000+
012054002008006005006005-00599822628115311000201040201001000
05011A01000041 9.00 00000000098313100000012222202122221013616160691111101
05011A01000042 9.00 0000000001111632111631107531114[redacted]1118331225331106
33211833121123220070806411910
05011A01010051 9.00 0000000003721680641119224210404115000004211001999011-01
321010112144011422600000000000041000620101020832011011
05011A01010161 9.00 0000000001140210585022100
05011A01010261 9.00 0000000001140650495022100
05011A01010361 9.00 0000000001140684315022100
05011A01010461 9.00 0000000001140684325022100
05011A01010561 9.00 0000000001140678495022100
05011A01010661 9.00 0000000001140646535022100
05011A01010761 9.00 0000000001890402120041100
05011A01010861 9.00 0000000001150206485022100
05011A01010961 9.00 0000000001251402185022100
05011A01011061 9.00 0000000001251404185022100
05011A01011161 9.00 0000000001450242530511101
05011A01011261 9.00 0000000001441410430511101
05011A01011361 9.00 0000000001540624480511101
05011A01011461 9.00 0000000001542020280511101
05011A01011561 9.00 0000000001544226420511101
05011A01011661 9.00 0000000001541626420511101
05011A01011761 9.00 0000000001521404320511101
05011A01011861 9.00 0000000001852604350511101
05011A01011961 9.00 0000000001190602120542103
05011A01012061 9.00 0000000001190202120542103
05011A01012161 9.00 0000000001190402120542103
05011A01012261 9.00 0000000001290602120542103
05011A01012361 9.00 0000000001290202120542103
05011A01012461 9.00 0000000001290402120542103
05011A01012561 9.00 0000000001390602126022300
05011A01012661 9.00 0000000001390202126021300
05011A01012761 9.00 0000000001390402120512101
05011A01012861 9.00 0000000001790402120511101
05011A01012961 9.00 0000000001790602136022300
05011A01013061 9.00 0000000001890402120511101
05011A01013161 9.00 0000000001890202120511101
05011A01013261 9.00 0000000001890202120041100

05011A01020051 9.00 0000000001221470412219000010404111000004000000000000 00
0000000000010311016000000000000410006201010203190110 11
05011A01020161 9.00 0000000001140654530512102
05011A01020261 9.00 0000000001140678490512102
05011A01020361 9.00 0000000001140630490512102
05011A01020461 9.00 0000000001140624430512102
05011A01020561 9.00 0000000001140402360512102
05011A01020661 9.00 0000000001140684310512102
05011A01020761 9.00 0000000001140684320512102
05011A01020861 9.00 0000000001150200380512102
05011A01020961 9.00 0000000001650208260512202
05011A01021061 9.00 0000000001251004240512102
05011A01021161 9.00 0000000001250600120512102
05011A01021261 9.00 0000000001250200280512102
05011A01021361 9.00 0000000001290202100512102
05011A01021461 9.00 0000000001290402100512102
05011A01021561 9.00 0000000001490402110511102
05011A01021661 9.00 0000000001490402110511102
05011A01021761 9.00 0000000001790402120511102
05011A01021861 9.00 0000000001590402120511102
05011A01021961 9.00 0000000001890402130511102
05011A01030051 9.00 0000000001119990322239000004404111000004000000000000 00
0000000000010311011000000000000231019700000000071512 41
05011A01030161 9.00 0000000002160410201512100
05011A01030261 9.00 0000000002290600176022300
05011A01030361 9.00 0000000002290202176022300
05011A01030461 9.00 0000000003240216121513100
05011A01030561 9.00 0000000003297402121512100
05011A01030661 9.00 0000000002890402111511100
05011A01030761 9.00 0000000003890202111511100
05011A02000021 9.00 0000000008812471301FTCR15T9JP[redacted]072089096001804192
0214221000990166082188
05011A02000022 9.00 0000000001010100014700601031316100[redacted]0001038-036-01
304499810210301
05011A02000031 9.00 0000000000010101FDEW03063100RDA0021480580200140060000000
000 1481203181400100040105010100 1000
05011A02000041 9.00 0000000000611000000001222220012222200216161001111 1100
05011A02000042 9.00 0000000001118111105122226121311132126 12
100000009110010
05011A02010051 9.00 0000000001719999991110000004404911000004000000000000 00
0000000000010715231000000000000242009700000000001021011
05011A02010161 9.00 0000000003290402140062100

```
05011A00000066       9.00 000000000CAR-COMPACT PICKUP/OBTUSEANGLE
05011A00000171       9.00 000000000V1 WAS TRAVELING NORTHBOUND AND V2 WAS TRAVELI
NG EASTBOUND.  AS V1 TRAVELED
05011A00000271       9.00 000000000INTO THE INTERSECTION IT WAS IMPACTED ON THE L
EFT SIDE BY THE FRONT OF V2.
05011A00000371       9.00 000000000AFTER IMPACT, V2 ROLLED OVER ONTO ITS RIGHT SI
DE WHERE IT CAME TO FINAL REST.
05011A00000471       9.00 000000000 V1 ROTATED COUNTER CLOCKWISE AND TRAVELED OFF
 THE ROAD WHERE IT IMPACTED A
05011A00000571       9.00 000000000SIGN POST AND CAME TO FINAL REST AFTER IT IMPA
CTED ITS RIGHT SIDE WHEELS WITH
05011A00000671       9.00 000000000A CULVERT.  THE DRIVER AND THE DRIVERS SIDE RE
AR PASSENGER OF V1 WERE FATALLY
05011A00000771       9.00 000000000INJURIED. THE PASSENGER SIDE REAR PASSENGER WA
S TRANSPORTED TO A LOCAL
05011A00000871       9.00 000000000HOSPITAL AND RELEASED.  THE DRIVER OF V2 WAS A
LSO TRANSPORTED AND RELEASED.
05011A00000181       9.00 00000000001 FULL SIZE      1993/PONTIAC/BONNEVILLE LEFT
    SEVERE       NONE
05011A00000281       9.00 00000000002 COMPACT PICKUP 1988/FORD/RANGER 4X4  FRONT
    MODERATE     NONE
05011A00000191       9.00 00000000001 DRIVER   FRONT LEFT MAN-LAP/SHLDR brain   h
emorhage  5 hood of other
05011A00000291       9.00 000000000                        AIR BAG
             vehicle
05011A00000391       9.00 00000000001 PASSENGER 2ND LEFT  MAN-LAP/SHLDR brain   h
emorhage  5 L side
05011A00000491       9.00 00000000001 PASSENGER 2ND RIGHT MAN-LAP/SHLDR brain   c
oncussion 2 seatback
05011A00000591       9.00 00000000002 DRIVER   FRONT LEFT MAN-LAP/SHLDR nose    c
ontusion  1 steering wheel
05011A999999990000000000000000000000000000000010000000000000000010000000010000
0000000000000
```

INTERIOR VEHICLE Vehicle: 1

11

INTRA ERRORS

OCC0541 2 ********* THIS CASE SHOWS A
POSSIBLE HOLED WINDSHIELD. ******** CC0542 ****** CHECK YOUR DATA AND
IF CORRECT, NOTIFY YOUR ZONE ****** CC0543 GLAZING WINDSHIELD IV31 equ
als 3 or 5 or CONTACT WINDSHIELD IV39 CC0544 equals 4 or 6.

0

OCCUPANT ASSESSMENT Vehicle: 1 Occupant: 1

11

INTRA ERRORS

OHH1271 2 ******* THI
S CASE SHOWS EJECTION WITH RESTRAINT USAGE. ****** HH1272 ****** CHE
CK YOUR DATA AND IF CORRECT, NOTIFY YOUR ZONE ****** HH1273 EJECTION OA
12 is equal to 1-3 and ((MANUAL BELT USE OA19 does HH1274 not equal 0
0, 01 or 99) or HH1275 (FRONTAL AI
R BAG SYSTEM DEPLOYMENT OA31 does not equal 0, 7 or HH1276 9) or (AUTO
MATIC BELT USE OA24 does not equal 0, 2 or 9)).

0

GENERAL VEHICLE Vehicle: 2

11

INTRA ERRORS

OGG0421 2 If ROLLOVER GV45 equals 01-
17 or 98, then BASIS FOR DELTA V GV58 GG0422 should equal 04-10.

01

PSU05 ERROR SUMMARY SCREEN [redacted]/96
CASE 011A
CURRENT VERSION: 9.00

FORM NAME	NUMBER OF DOLLAR SIGNS	NUMBER OF LEVEL 1 ERRORS	NUMBER OF LEVEL 2 ERRORS	VERSION NUMBER CONSISTENT
Accident	0	0	0	Y
General Vehicle	0	0	1	Y
Vehicle Exterior	0	0	0	Y
Vehicle Interior	0	0	1	Y
Occupant Assessment	0	0	1	Y
Occupant Injury	0	0	0	Y
Total Inter Errors		0	0	
Total Case Errors	0	0	3	

0

U.S. Department of Transportation
National Highway Traffic Safety Administration

SLIDE INDEX

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Primary Sampling Unit Number 05 Case Number—Stratum 0 1 1 17

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter
1-3	1	N	Approach of V1
4-7	1	NE	V1 is Impacted By V2 and is Pushed into A sign,
			and Travels to Final Rest in a culvert.
8-10	1	SW	Lookback From Final Rest and original Path of travel
11-12	1	N	Sign Post Impacted By V1. shows Paint transfers.
			Looks like Damage to fence is from sign.
13-15	2	E	Approach of V2.
16-17	2	E	V2 Impacts with V1
18-20	2	E	V2 Then Rollover onto its (R) side.
21-23	2	W	Lookback from Final Rest & original Path of Travel.
24	2	—	Gouge mark from V2.
25	—	N	RP.
26-28	1	—	Front of V1, Looks like windshield was cut By Rescue to Help get Driver out of car.
29-35	1	—	Damage to (L) side of V1
36	1	—	BACK of V1
37-44	1	—	(R) side Damage of V1
45	1	—	Fuel Tank
46-82	1	—	Interior of V1 Including Intrusion, contact Points and
			Views of AIR BAG.
83	1	—	Close up of Rescue crew Damage To Door Locks
84-88	2	—	Frontal Damage To V2
89-93	2	—	(L) side and BACK of V2
94-98	2	—	(R) side Rollover Damage To V2.
99	2	—	Fuel Tank
100	2	—	Movement in Bed.
101-118	2	—	Interior of V2 Including Contact Points &
			Intrusions

HS Form 434B (1/96)

Slide No.	Vehicle No.	Direction of Picture	Description of Slide Subject Matter

PSU 05-011A (1996) #1

PSU 05-011A (1996) #2

PSU 05-011A (1996) #3

PSU 05-011A (1996) #4

PSU 05-011A (1996) #5

PSU 05-011A (1996) #6

PSU 05-011A (1996) #7

PSU 05-011A (1996) #8

PSU 05-011A (1996) #9

PSU 05-011A (1996) #10

PSU 05-011A (1996) #11

PSU 05-011A (1996) #12

PSU 05-011A (1996) #13

PSU 05-011A (1996) #14

PSU 05-011A (1996) #15

PSU 05-011A (1996) #16

PSU 05-011A (1996) #17

PSU 05-011A (1996) #18

PSU 05-011A (1996) #19

PSU 05-011A (1996) #20

PSU 05-011A (1996) #21

PSU 05-011A (1996) #22

PSU 05-011A (1996) #23

PSU 05-011A (1996) #24

PSU 05-011A (1996) #25

PSU 05-011A (1996) #26

PSU 05-011A (1996) #27

PSU 05-011A (1996) #28

PSU 05-011A (1996) #29

PSU 05-011A (1996) #30

PSU 05-011A (1996) #31

PSU 05-011A (1996) #32

PSU 05-011A (1996) #33

PSU 05-011A (1996) #34

PSU 05-011A (1996) #35

PSU 05-011A (1996) #36

PSU 05-011A (1996) #37

PSU 05-011A (1996) #38

PSU 05-011A (1996) #39

PSU 05-011A (1996) #40

PSU 05-011A (1996) #41

PSU 05-011A (1996) #42

PSU 05-011A (1996) #43

PSU 05-011A (1996) #44

PSU 05-011A (1996) #45

PSU 05-011A (1996) #46

PSU 05-011A (1996) #47

PSU 05-011A (1996) #48

PSU 05-011A (1996) #49

PSU 05-011A (1996) #50

PSU 05-011A (1996) #51

PSU 05-011A (1996) #52

PSU 05-011A (1996) #53

PSU 05-011A (1996) #54

PSU 05-011A (1996) #55

PSU 05-011A (1996) #56

PSU 05-011A (1996) #57
Best Available

PSU 05-011A (1996) #58
Best Available

PSU 05-011A (1996) #59
Best Available

PSU 05-011A (1996) #60
Best Available

PSU 05-011A (1996) #61
Best Available

PSU 05-011A (1996) #62
Best Available

PSU 05-011A (1996) #63
Best Available

PSU 05-011A (1996) #64
Best Available

PSU 05-011A (1996) #65
Best Available

PSU 05-011A (1996) #66
Best Available

PSU 05-011A (1996) #67
Best Available

PSU 05-011A (1996) #68

PSU 05-011A (1996) #69

PSU 05-011A (1996) #70
Best Available

PSU 05-011A (1996) #71
Best Available

PSU 05-011A (1996) #72

PSU 05-011A (1996) #73

PSU 05-011A (1996) #74

PSU 05-011A (1996) #75

PSU 05-011A (1996) #76

PSU 05-011A (1996) #77

PSU 05-011A (1996) #78

PSU 05-011A (1996) #79

PSU 05-011A (1996) #80
Best Available

PSU 05-011A (1996) #81

PSU 05-011A (1996) #82

PSU 05-011A (1996) #83

PSU 05-011A (1996) #84
Best Available

PSU 05-011A (1996) #85
Best Available

PSU 05-011A (1996) #86
Best Available



PSU 05-011A (1996) #87
Best Available



PSU 05-011A (1996) #88

PSU 05-011A (1996) #89
Best Available

PSU 05-011A (1996) #90
Best Available

PSU 05-011A (1996) #91
Best Available

PSU 05-011A (1996) #92
Best Available

PSU 05-011A (1996) #93
Best Available

PSU 05-011A (1996) #94
Best Available

PSU 05-011A (1996) #95
Best Available

PSU 05-011A (1996) #96

PSU 05-011A (1996) #97

PSU 05-011A (1996) #98

PSU 05-011A (1996) #99

PSU 05-011A (1996) #100

PSU 05-011A (1996) #101
Best Available

PSU 05-011A (1996) #102
Best Available

PSU 05-011A (1996) #103

PSU 05-011A (1996) #104

PSU 05-011A (1996) #105

PSU 05-011A (1996) #106
Best Available

PSU 05-011A (1996) #107
Best Available

PSU 05-011A (1996) #108

PSU 05-011A (1996) #109

PSU 05-011A (1996) #110

PSU 05-011A (1996) #111

PSU 05-011A (1996) #112
Best Available

PSU 05-011A (1996) #113
Best Available

PSU 05-011A (1996) #114

PSU 05-011A (1996) #115

PSU 05-011A (1996) #116

PSU 05-011A (1996) #117
Best Available

PSU 05-011A (1996) #118